



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



AUTO SAFETY HOTLINE
(800) 424-9393
Wash. D.C. Area 366-0123

DYNAMIC SCIENCE, INC.
In-Depth Accident Investigation

Case Number: DSI-95-SP-013

, 1996

Technical Report Documentation Page

1. Report No. DS 9513		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle In-Depth Accident Investigation				5. Report Date	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-94-D-27058	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract This case was selected for investigation based on the fire involvement of the case vehicle and a possible defect that caused the fire. This two-vehicle collision occurred in 1995, a summer weekday, on a divided trafficway in New Jersey. The collision occurred when Vehicle 2, traveling southbound on a northbound roadway of a north/south trafficway, struck Vehicle 1 in a head-on configuration. Vehicle 1, a 1983 Dodge Ram van, was being driven northbound. There were six occupants in this vehicle. It was reported that the driver and the right front occupant was restrained by lap and shoulder restraints. Restraint usage for the other four occupants is unknown. Vehicle 1 was traveling at a speed estimated as between 81 and 97 KPH (50 and 60 MPH). Vehicle 2, a 1991 Toyota Celica, was being driven southbound on the northbound roadway. The driver of Vehicle 2 was not restrained by the available 3-point manual lap and shoulder restraint. Vehicle 2 was traveling at a speed estimated to have been between 81 and 97 KPH (50 and 60 MPH). This two-vehicle collision occurred when the driver of Vehicle 2 entered the northbound roadway of the north/south trafficway from an unknown exit ramp of the northbound roadway. Once the driver of Vehicle 2 entered the roadway he traveled southbound (the wrong direction). Vehicle 2 struck the front end of Vehicle 1 with its frontal plane. After the initial impact, Vehicle 1 rotated clockwise and the rear end of the vehicle went airborne as it rotated. Vehicle 1, as it was in the air and rotating, mounted the median barrier and slid along the top side of the barrier to its final rest position. During this sequence Vehicle 1 subsequently caught fire. Vehicle 2 was pushed rearward and counterclockwise to its final rest position. Vehicle 1's damage consisted of major frontal damage with the maximum crush of 123.0 cm (48.4 in) on the right front corner. This appears to have caused major intrusion into the occupant compartment, including the movement of the engine rearward and to the left. Police indicated that the fire probably started near the carburetor. It appeared that the gas line came off the carburetor during the movement of the engine. The interior inspection of Vehicle 1 conducted by DSI, showed a heavier burn pattern present in the front portion of the vehicle. This burn pattern would support the information from the state police that the fire was started in the engine compartment.					
17. Key Words Fire, crash.			18. Distribution Statement		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price		

Form DOT F 1700.7 (8-72) Reproduction of this form and completed page is authorized

TECHNICAL SUMMARY

CONTRACTOR: Dynamic Science, Inc.
CASE NUMBER: DS95013

This case was selected for investigation based on the fire involvement of the case vehicle and a possible defect that caused the fire.

This two-vehicle collision occurred in 1995, a summer weekday, on a divided trafficway in New Jersey. The collision occurred when Vehicle 2, traveling southbound on a northbound roadway of a north/south trafficway, struck Vehicle 1 in a head-on configuration.

Vehicle 1, a 1983 Dodge Ram van, was being driven northbound. There were six occupants in this vehicle. It was reported that the driver and the right front occupant was restrained by lap and shoulder restraints. Restraint usage for the other four occupants is unknown. Vehicle 1 was traveling at a speed estimated as between 81 and 97 KPH (50 and 60 MPH).

Vehicle 2, a 1991 Toyota Celica, was being driven southbound on the northbound roadway. The driver of Vehicle 2 was not restrained by the available 3-point manual lap and shoulder restraint. Vehicle 2 was traveling at a speed estimated to have been between 81 and 97 KPH (50 and 60 MPH).

This two-vehicle collision occurred when the driver of Vehicle 2 entered the northbound roadway of the north/south trafficway from an unknown exit ramp of the northbound roadway. Once the driver of Vehicle 2 entered the roadway he traveled southbound (the wrong direction). Vehicle 2 struck the front end of Vehicle 1 with its frontal plane.

The Delta V for Vehicle 1 was computed, using CRASH-3 PC, as 60 KPH (37 MPH). Vehicle 1 was assigned a CDC of 72FDEW7. The Delta V for Vehicle 2 was computed as 88 KPH (55 MPH). Vehicle 2 was assigned a CDC of 72FDEW4.

After the initial impact, Vehicle 1 rotated clockwise and the rear end of the vehicle went airborne as it rotated. Vehicle 1, as it was in the air and rotating, mounted the median barrier and slid along the top side of the barrier to its final rest position. During this sequence Vehicle 1 subsequently caught fire. Vehicle 2 was pushed rearward and counterclockwise to its final rest position.

Vehicle 1's damage consisted of major frontal damage with the maximum crush of 123.0 cm (48.4 in) on the right front corner. This appears to have caused major intrusion into the occupant compartment, including the movement of the engine rearward and to the left. Police indicated that the fire probably started near the carburetor. It appeared that the gas line came off the carburetor during the movement of the engine. The interior inspection of Vehicle 1 conducted by DSI showed a heavier burn pattern present in the front portion of the vehicle. This burn pattern would support the information from the state police that the fire was started in the engine compartment (photographs 30-33).

The driver of Vehicle 1 sustained moderate injuries consisting of a closed head injury with positive loss of consciousness and smoke inhalation. The right front occupant sustained major injuries that later resulted in death. The injuries consisted of bilateral lower extremity third degree burns (about 10%), right buttock tissue avulsion, right femur fracture, left open tibia/fibula fractures, myocardial contusion and mild pulmonary inhalation injury. The driver and the right front occupant were rescued from the burning vehicle by a passing motorist, then were transported by ground ambulance to a trauma center. Further rescue attempts of the other four occupants were impossible due to the vehicle's being engulfed by flames. The driver of Vehicle 1 was the sole survivor in this vehicle. The right front occupant and four rear seated occupants of the vehicle reportedly sustained fatal injuries resulting from the fire in the vehicle and the impact with Vehicle 2.

The driver of Vehicle 2 sustained moderate injuries consisting of a loss of consciousness, subarachnoid hematoma, acetabular column fracture, abdominal contusion, and right knee abrasions, contusions and a laceration with the maximum AIS equal to AIS-3. The driver was transported to a trauma center where he was admitted for treatment.

Vehicles 1 and 2 were towed from the collision scene due to the damage sustained from this collision.

This research was supported by the National Highway Traffic Safety Administration (NHTSA), U.S. Department of Transportation. The opinions, findings, and recommendations contained herein are those of the authors, and do not necessarily represent those of NHTSA.

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

DYNAMIC SCIENCE, INC.
ACCIDENT INVESTIGATION
CASE NUMBER: DS95013

TABLE OF CONTENTS

Accident Data	1
Ambience	1
Roadway	2
Traffic Controls	2
Vehicles	3
Vehicle Damage and Velocity Estimates	4
Collision Sequence	6
Occupant Data	8
Injuries	12
List of Abbreviations	14
Accident Schematic	15
Collision Measurement Table	16
Photo Index	17

Appendices:

- A. Police Accident Report
- B. Photo Copies of Collision Scene
- C. Photos

Case Number: DS95013

ACCIDENT DATA:

Location: New Jersey
Area/Type: Urban
Date/Time: Summer / Weekday
Accident Type: Car/Van - Head-on

INJURY SEVERITY:

Vehicle 1: Driver, AIS-3
R/F Occupant, AIS-4, later reportedly expired
Four other occupants in the rear portion of the vehicle, unknown seat positions, reportedly sustained fatal injuries

Vehicle 2: Driver, AIS-3

AMBIENCE:

Viewing Conditions: No viewing restriction
Cloud Cover: Clear
Precipitation: None
Road Surface: Dry

ROADWAY:

	VEHICLE 1	VEHICLE 2
Type:	Divided trafficway, 5-lane northbound	Divided trafficway, 5-lane northbound (traveling southbound)
Width:	15.2 m (50.0 ft)	15.2 m (50.0 ft)
Traffic Density:	Light	Light
Median:	Concrete	Concrete
Edge:	Asphalt shoulder	Asphalt shoulder
Surface:	Asphalt	Asphalt
Reported Defects:	None	None
Co-efficient of Friction (est.):	.70 dry	.70 dry
Vertical Alignment:	Up grade	Down grade
Horizontal Alignment:	Straight	Straight

TRAFFIC CONTROLS:

	VEHICLE 1	VEHICLE 2
Signals:	None	None
Signs:	None	Do Not Enter sign wherever Vehicle 1 entered the northbound roadway
Speed Limit:	89 KPH (55 MPH)	89 KPH (55 MPH)
Markings:	Standard lane markings	Standard lane markings

VEHICLES:

	VEHICLE 1	VEHICLE 2
Description:	1983 Dodge Ram van	1991 Toyota Celica
Odometer:	Unknown, unable to read due to the fire in the vehicle	Unknown, unable to read due to the damage
Engine:	5.2 L / V8	2.2 L / L4
Vehicle Modifications:	None known	None
Tire Condition:	Good tread depth	Good tread depth
Manual Restraints:	Unable to inspect, fire in vehicle	3-point lap and shoulder restraints at the front seating positions, left and right rear seating positions; 2-point lap restraints at the rear center seating position.
Automatic Restraints:	None	Supplemental Restraint System (driver's side air bag)
Reported Defects:	None	None
Cargo:	Unknown, fire in vehicle	None
Windshield Damage:	Unknown, fire in vehicle	Cracked by impact forces and occupant contact
Fleet:	None	None
Tow Status:	Towed due to damage	Towed due to damage

VEHICLE DAMAGE:

	VEHICLE 1	VEHICLE 2
Object Struck:	Vehicle 2	Vehicle 1
Event Number:	01	01
CDC:	72FDEW7	72FDEW4
Maximum Crush:	123.0 cm (48.4 in) @ C ₆	105.5 cm (41.5 in) @ C ₆

VEHICLE VELOCITY ESTIMATES:

	VEHICLE 1	VEHICLE 2
Impact Speed:	81 - 97 KPH (50 - 60 MPH)	81 - 97 KPH (50 - 60 MPH)
Total Delta V:	60 KPH (37 MPH)	88 KPH (55 MPH)
Longitudinal Delta V:	-59 KPH (-37 MPH)	-87 KPH (-54 MPH)
Lateral Delta V:	-10 KPH (-6 MPH)	-15 KPH (-10 MPH)
Energy Dissipation:	474,621.4 joules (350,015.8 ft-lbs)	228,6616.2 joules (168,596.0 ft-lbs)

Calculations based upon: CRASH-3 PC

Case Number: DSI-95-SP-013

VEHICLE DAMAGE:

	VEHICLE 1	VEHICLE 1
Object Struck:	Fire	Median Barrier
Event Number:	03	02
CDC:	N/A	09LPLW1
Maximum Crush:		Zone 1

VEHICLE VELOCITY ESTIMATES:

	VEHICLE 1	VEHICLE 1
Impact Speed:	N/A	40 - 48 KPH (25 - 30 MPH)
Total Delta V:	Not computed, fire in vehicle	No Computed, insufficient data
Longitudinal Delta V:		
Lateral Delta V:		
Energy Dissipation:		

COLLISION SEQUENCE:

PRE-CRASH:

This two-vehicle collision occurred on a summer weekday, on a northbound roadway of a north/south divided trafficway in New Jersey. There is a posted speed limit of 89 kilometers per hour (55 MPH). The collision occurred when Vehicle 2 was traveling southbound (the wrong direction) on the northbound roadway. Vehicle 2 struck Vehicle 1 in a head-on configuration.

Vehicle 1, a 1983 Dodge Ram van, was being driven northbound on the north/south trafficway. The driver was a 59 year old male. In the right front seating position was a 54 year old female. It was reported that the driver and the right front occupant were restrained by lap and shoulder restraints. In the vehicle's rear seating positions, unknown locations, were a 72 year old female, an 80 year old female, a 69 year old female and a 62 year old female. It is unknown if any of the rear occupants were restrained by the available restraint systems in the vehicle. Vehicle 1 was traveling at a speed estimated to have been between 81 and 97 kilometers per hour (50 and 60 MPH).

Vehicle 2, a 1991 Toyota Celica, was being driven southbound by a 24 year old male driver on the northbound roadway. The driver was not restrained by the available 3-point manual lap and shoulder restraint, however, the vehicle had a supplemental restraint system (air bag) that deployed during impact. Vehicle 2 was traveling at a speed estimated to have been between 81 and 97 kilometers per hour (50 and 60 MPH).

This two-vehicle collision occurred when the driver of Vehicle 2 entered the northbound roadway of the north/south trafficway from an unknown exit ramp of the northbound roadway. Once the driver entered the roadway he traveled southbound, the wrong direction on a one-way roadway. Vehicle 2 struck the front end of Vehicle 1 with its frontal plane.

CRASH:

The Delta V for Vehicle 1 was computed, using CRASH-3 PC, as 60 kilometers per hour (37 MPH). Vehicle 1 was assigned a Collision Deformation Classification (CDC) of 72FDEW7 and a Principle Direction of Force (PDOF) of 010 degrees. The combined direct and induced damage width was 130.0 centimeters (51.2 in) [CRASH "L" = 187.0 cm (73.6 in)], and the maximum crush depth was 123.0 centimeters (48.4 in) located at C₆.

The Delta V for Vehicle 2 was computed as 88 kilometers per hour (55 MPH). Vehicle 2 was assigned a CDC of 72FDEW4 and a PDOF of 010 degrees. The combined direct and

Case Number: DSI-95-SP-013

The Delta V for Vehicle 2 was computed as 88 kilometers per hour (55 MPH). Vehicle 2 was assigned a CDC of 72FDEW4 and a PDOF of 010 degrees. The combined direct and induced damage width was 73.0 centimeters (28.7 in) [CRASH "L" = 140.0 cm (55.1 in)] , and the maximum crush depth was 105.5 centimeters (41.5 in) located at C₆.

POST CRASH:

After the impact, Vehicle 1 rotated clockwise and the rear end of the vehicle went airborne. Vehicle 1, as it was in the air, mounted the median barrier and slid along the top side of the barrier to its final rest position, facing southeast. During this time frame it appears Vehicle 1 caught fire. Vehicle 2 was pushed rearward and counterclockwise to its final rest position, facing southeast.

SUPPLEMENTAL RESTRAINT SYSTEM:

Vehicle 2 was equipped with a Supplemental Restraint System (driver's side air bag). The air bag deployed during the collision with Vehicle 1. The longitudinal component of the Delta V for the air bag deployment impact was a minus 87 kilometers per hour (54 MPH).

SCENE CLEARANCE:

The driver and right front occupant of Vehicle 1 were reportedly pulled out of the vehicle by a passing motorist. Further rescue attempts of the other four occupants were impossible due to the vehicle's being engulfed by flames. The driver and right front occupant were transported by ground ambulance to a trauma center for treatment. The other four occupants of Vehicle 1 were fatally injured.

The driver of Vehicle 2 reportedly sustained incapacitating injuries in the collision. On arrival at the scene, a police officer removed the driver from his vehicle, because of fuel spilling under the vehicle and the close proximity of Vehicle 1 that was on fire. He was transported by ground ambulance to a trauma center for treatment.

Vehicles 1 and 2 were towed from the collision scene due to the damage sustained from this collision.

SAFETY STANDARDS:

No violations of the Federal Motor Vehicle Safety Standards were found during vehicle inspections.

DRIVER AND OTHER OCCUPANTS:

VEHICLE 1

	DRIVER	OCCUPANT 2
Age/Sex:	59 Yrs. / Male	54 Yrs / Female
Seated Position:	Left Front	Right front
Seat Type:	Bucket Seat / box mounted, (van)	Bucket Seat / box mounted (van)
Height:	Unknown	Unknown
Weight:	Unknown	Unknown
Pre-existing Medical Condition:	None	None
Body Posture:	Upright seated position	Upright seated position
Hand Position:	On Steering Wheel, Unknown location	Unknown
Foot Position:	Unknown	Unknown
Restraint Usage:	Reportedly wearing a manual 3-point lap and shoulder restraint	Reportedly wearing a manual 3-point lap and shoulder restraint
Additional Occupants:	Five	N/A

DRIVER AND OTHER OCCUPANTS (Con't):

VEHICLE 1

	OCCUPANT 3	OCCUPANT 4
Age/Sex:	72 Yrs. / Female	80 Yrs / Female
Seated Position:	Rear seating position, unknown location	Rear seating position, unknown location
Seat Type:	Unknown	Unknown
Height:	Unknown	Unknown
Weight:	Unknown	Unknown
Pre-existing Medical Condition:	None	None
Body Posture:	Unknown	Unknown
Hand Position:	Unknown	Unknown
Foot Position:	Unknown	Unknown
Restraint Usage:	Unknown	Unknown
Additional Occupants:	N/A	N/A

DRIVER AND OTHER OCCUPANTS (Con't):

VEHICLE 1

	OCCUPANT 5	OCCUPANT 6
Age/Sex:	69 Yrs. / Female	62 Yrs. / Female
Seated Position:	Rear seating position, unknown location	Rear seating position, unknown location
Seat Type:	Unknown	Unknown
Height:	Unknown	Unknown
Weight:	Unknown	Unknown
Pre-existing Medical Condition:	Unknown	Unknown
Alcohol/Drug Involvement:	None	None
Body Posture:	Unknown	Unknown
Hand Position:	Unknown	Unknown
Foot Position:	Unknown	Unknown
Restraint Usage:	Unknown	Unknown
Additional Occupants:	N/A	N/A

DRIVER AND OTHER OCCUPANTS (Con't):

VEHICLE 2

DRIVER

Age/Sex:	24 Yrs. / Male
Seated Position:	Left Front
Seat Type:	Bucket Seat
Height:	Unknown
Weight:	Unknown
Pre-existing Medical Condition:	None
Alcohol/Drug Involvement:	None
Driving Experience:	8 years
Body Posture:	Upright seated position
Hand Position:	Steering wheel, unknown location
Foot Position:	Unknown
Restraint Usage:	A supplemental restraint system (air bag)
Additional Occupants:	None

INJURIES:

Vehicle 1

	INJURY	AIS/OIC Code	ICD-9	Source	Confidence Level
DRIVER	Closed head injury w/ positive loss of consciousness	160802.3,0	850.5	Unknown	Unknown
	Smoke inhalation	919202.3,0	986	Fire in vehicle	Certain
R/F OCCUPANT	Bilateral lower extremity third degree burns (about 10%)	892012.2,3	948.1	Fire in vehicle	Certain
	Right buttock tissue avulsion	590800.1,1	877.0	Unknown	Unknown
	Right femur fracture	851800.3,1	820.8	Instrument panel	Probable
	Left open tibia fracture	853404.3,2	823.82	Toe pan	Probable
	Left open fibula fracture	851605.3,2	823.82	Toe pan	Probable
	Myocardial contusion	441002.3,4	861.01	Unknown	Unknown
	Mild Pulmonary inhalation injury	919203.3,0	986	Fire in vehicle	Certain
Four Rear Seat Occupants	Fatal injuries, due to impact and fire in vehicle				

INJURIES (Con't):**Vehicle 2**

	INJURY	AIS/OIC CODE	ICD-9	SOURCE	Confidence Level
DRIVER	Loss of consciousness < 1 hour	160202.2,0	850.1	Windshield	Certain
	Right occipital subarachnoid hematoma	140684.3,1	852.0	Windshield	Certain
	Left upper abdominal quadrant contusion	590402.1,2	922.2	Air bag	Certain
	Right knee abrasions	890202.1,1	916.0	Center instrument panel	Certain
	Right knee contusions	890402.1,1	924.11	Center instrument panel	Certain
	Right knee laceration	890602.1,1	891.0	Center instrument panel	Certain
	Right posterior acetabular column fracture (multiple bone fragments)	852602.2,1	808.0	Center console area	Certain

List of Abbreviations


FT	Feet
IN	Inches
AME	After Market Equipment
AIS	Abbreviated Injury Scale
CCW	Counterclockwise
CDC	Collision Deformation Classification
C/F	Center Front
CG	Center of Gravity
CM	Centimeter
C/R	Center Rear
CW	Clockwise
E, EB	East, Eastbound
FRP	Final Rest Position
KG	Kilogram
KM/H	Kilometers per Hour
L/F	Left Front
L/R	Left Rear
M	Meter
N, NB	North, Northbound
NE	Northeast
NW	Northwest
OEM	Original Equipment Manufacture
PDOF	Principal Direction Of Force
POI	Point of Impact
R	Radius of Curvature
R/F	Right Front
RL	Reference Line
RP	Reference Point
R/R	Right Rear
S, SB	South, Southbound
SE	Southeast
SW	Southwest
V1	Vehicle 1
W, WB	West, Westbound

DYNAMIC SCIENCE
DSI-95-SP-013
1 CM = 3.6 METERS
1 IN = 30.0 FEET

0 15' 0" 30' 0"



VEHICLES:
V1 - 1983 Dodge Ram van
V2 - 1991 Toyota Celica



COLLISION MEASUREMENTS

Case Number: DSI-95-SP-013

Reference Point: North end of storm drain, located near the median barrier

Reference Line: East side of the median barrier

DATA POINT	LONGITUDINALS	LATERALS
Yellow solid line	0	E 1.0 m (3.3 ft)
1st white broken line	0	E 4.1 m (13.3 ft)
2nd white broken line	0	E 7.1 m (23.3 ft)
3rd white broken line	0	E 10.1 m (33.3 ft)
4th white broken line	0	E 13.5 m (43.3 ft)
White solid line (right edge line)	0	E 16.2 m (53.3 ft)
POI #1 (V1 vs. V2)	S 12.1 m (39.8 ft)	E 2.5 m (8.3 ft)
POI #2 (V1 vs. median barrier) approx.	S 11.0 m (36.0 ft)	0
Vehicle 2 Final Rest Position (FRP)		
Right front wheel	S 0.6 m (2.0 ft)	E 7.1 m (23.3 ft)
Right rear wheel	N 0.9 m (2.8 ft)	E 5.9 m (19.2 ft)
Vehicle 1 Final Rest Position (FRP)		
Right front wheel	N 4.1 m (13.5 ft)	0
Left front wheel	N 4.8 m (15.6 ft)	E 1.5 m (5.0 ft)


CASE NUMBER DS9513

MISSING DATA

THE FOLLOWING DATA ARE NOT INCLUDED IN THIS CASE:

PAGE NUMBER(S)

(17) photo index







SP13-007



SP13-008































































































CH

BEST AVAILABLE

PAGE 1 OF 6


1 CASE NO.		40 STATION		INITIAL ACCIDENT INVESTIGATION REPORT										11 REPORTABLE <input checked="" type="checkbox"/> NON-REPORTABLE <input type="checkbox"/>																																																																	
2 DATE OF COLLISION			41 DAY OF COLLISION					44 TIME	45 NO. OF VEHICLES	46 NO. KILLED	47 NO. INJURED	48 COUNTY	MUN. CODE																																																																		
MONTH	DAY	YEAR	S	M	T	W	T	F	S	Use 2400 Hrs	2	4	3																																																																		
39 MUNICIPALITY										50 MILEPOST	51 DIRECTION	52 SERVICE AREA, RAMP, TOLL PLAZA, OR COMMUTER LOT																																																																			
VEH 1										53 POLICY NO.	54 INS. CODE	VEH 2		79 POLICY NO.	80 INS. CODE																																																																
PARKED VEHICLE										PEDESTRIAN		PEDALCYCLIST		PARKED VEHICLE		PEDESTRIAN		PEDALCYCLIST																																																													
55 DRIVER'S FIRST NAME										INITIAL		LAST NAME		56 DRIVER'S FIRST NAME										INITIAL		LAST NAME																																																					
56 NUMBER AND STREET										57 CITY										STATE		ZIP		EXPIRES		58 DRIVER'S LICENSE NUMBER										59 STATE		60 D.O.B.		61 EYES		62 SEX																																					
57 CITY										STATE		ZIP		EXPIRES		58 DRIVER'S LICENSE NUMBER										59 STATE		60 D.O.B.		61 EYES		62 SEX																																															
58 DRIVER'S LICENSE NUMBER										59 STATE		60 D.O.B.		61 EYES		62 SEX		59 OWNER'S FIRST NAME										INITIAL		LAST NAME		60 OWNER'S FIRST NAME										INITIAL		LAST NAME																																			
59 OWNER'S FIRST NAME										INITIAL		LAST NAME		60 OWNER'S FIRST NAME										INITIAL		LAST NAME		61 NUMBER AND STREET										62 NUMBER AND STREET																																									
60 NUMBER AND STREET										61 CITY										STATE		ZIP		EXPIRES		62 MAKE AND MODEL										COLOR		63 YEAR		64 PLATE NO.		65 STATE																																					
61 CITY										STATE		ZIP		EXPIRES		62 MAKE AND MODEL										COLOR		63 YEAR		64 PLATE NO.		65 STATE																																															
62 MAKE AND MODEL										COLOR		63 YEAR		64 PLATE NO.		65 STATE		66 VIN NUMBER										71 BODY TYPE		67 VIN NUMBER										97 BODY TYPE																																							
66 VIN NUMBER										71 BODY TYPE		67 VIN NUMBER										97 BODY TYPE		68 VEHICLE REMOVED TO										73 AUTHORITY		69 VEHICLE REMOVED TO										99 AUTHORITY																																	
68 VEHICLE REMOVED TO										73 AUTHORITY		69 VEHICLE REMOVED TO										99 AUTHORITY		74 TRAILER OWNER'S FIRST NAME										INITIAL		LAST NAME		75 TRAILER OWNER'S FIRST NAME										INITIAL		LAST NAME																													
74 TRAILER OWNER'S FIRST NAME										INITIAL		LAST NAME		75 TRAILER OWNER'S FIRST NAME										INITIAL		LAST NAME		76 MAKE										77 PLATE NO.		78 STATE		EXPIRES		79 MAKE										80 PLATE NO.		81 STATE		EXPIRES																					
75 MAKE										77 PLATE NO.		78 STATE		EXPIRES		79 MAKE										80 PLATE NO.		81 STATE		EXPIRES		105 INITIAL IMPACT										106 ALCOHOL DATA										110 PARKWAY DAMAGE										111 RAN OFF ROAD																	
105 INITIAL IMPACT										106 ALCOHOL DATA										110 PARKWAY DAMAGE										111 RAN OFF ROAD										112 TRAFFIC VOLUME										113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #									
106 ALCOHOL DATA										110 PARKWAY DAMAGE										111 RAN OFF ROAD										112 TRAFFIC VOLUME										113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #																			
110 PARKWAY DAMAGE										111 RAN OFF ROAD										112 TRAFFIC VOLUME										113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #																													
111 RAN OFF ROAD										112 TRAFFIC VOLUME										113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #																																							
112 TRAFFIC VOLUME										113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #																																																	
113 HAZARDOUS MATERIALS										114 NO. OF LANES										115 SERVICE TICKET #																																																											
114 NO. OF LANES										115 SERVICE TICKET #																																																																					
115 SERVICE TICKET #																																																																															
116 CHARGE										117 CHARGE										118 CHARGE										119 CHARGE																																																	
116 CHARGE										117 CHARGE										118 CHARGE										119 CHARGE																																																	
117 CHARGE										118 CHARGE										119 CHARGE																																																											
118 CHARGE										119 CHARGE																																																																					
119 CHARGE																																																																															
120 CHARGE										121 CHARGE										122 CHARGE										123 CHARGE																																																	
120 CHARGE										121 CHARGE										122 CHARGE										123 CHARGE																																																	
121 CHARGE										122 CHARGE										123 CHARGE																																																											
122 CHARGE										123 CHARGE																																																																					
123 CHARGE																																																																															
124 CHARGE										125 CHARGE										126 CHARGE										127 CHARGE																																																	
124 CHARGE										125 CHARGE										126 CHARGE										127 CHARGE																																																	
125 CHARGE										126 CHARGE										127 CHARGE																																																											
126 CHARGE										127 CHARGE																																																																					
127 CHARGE																																																																															
128 CHARGE										129 CHARGE										130 CHARGE										131 CHARGE																																																	
128 CHARGE										129 CHARGE										130 CHARGE										131 CHARGE																																																	
129 CHARGE										130 CHARGE										131 CHARGE																																																											
130 CHARGE										131 CHARGE																																																																					
131 CHARGE																																																																															
132 CHARGE										133 CHARGE										134 CHARGE										135 CHARGE																																																	
132 CHARGE										133 CHARGE										134 CHARGE										135 CHARGE																																																	
133 CHARGE										134 CHARGE										135 CHARGE																																																											
134 CHARGE										135 CHARGE																																																																					
135 CHARGE																																																																															
136 CHARGE										137 CHARGE										138 CHARGE										139 CHARGE																																																	
136 CHARGE										137 CHARGE										138 CHARGE										139 CHARGE																																																	
137 CHARGE										138 CHARGE										139 CHARGE																																																											
138 CHARGE										139 CHARGE																																																																					
139 CHARGE																																																																															
140 CHARGE										141 CHARGE										142 CHARGE										143 CHARGE																																																	
140 CHARGE										141 CHARGE										142 CHARGE										143 CHARGE																																																	
141 CHARGE										142 CHARGE										143 CHARGE																																																											
142 CHARGE										143 CHARGE																																																																					
143 CHARGE																																																																															
144 CHARGE										145 CHARGE										146 CHARGE										147 CHARGE																																																	
144 CHARGE										145 CHARGE										146 CHARGE										147 CHARGE																																																	
145 CHARGE										146 CHARGE										147 CHARGE																																																											
146 CHARGE										147 CHARGE																																																																					
147 CHARGE																																																																															
148 CHARGE										149 CHARGE										150 CHARGE										151 CHARGE																																																	
148 CHARGE										149 CHARGE										150 CHARGE										151 CHARGE																																																	
149 CHARGE										150 CHARGE										151 CHARGE																																																											
150 CHARGE										151 CHARGE																																																																					
151 CHARGE																																																																															
152 CHARGE										153 CHARGE										154 CHARGE										155 CHARGE																																																	
152 CHARGE										153 CHARGE										154 CHARGE										155 CHARGE																																																	
153 CHARGE										154 CHARGE										155 CHARGE																																																											
154 CHARGE										155 CHARGE																																																																					
155 CHARGE																																																																															
156 CHARGE										157 CHARGE										158 CHARGE										159 CHARGE																																																	
156 CHARGE										157 CHARGE										158 CHARGE										159 CHARGE																																																	
157 CHARGE										158 CHARGE										159 CHARGE																																																											
158 CHARGE										159 CHARGE																																																																					
159 CHARGE																																																																															
160 CHARGE										161 CHARGE										162 CHARGE										163 CHARGE																																																	
160 CHARGE										161 CHARGE										162 CHARGE										163 CHARGE																																																	
161 CHARGE										162 CHARGE										163 CHARGE																																																											
162 CHARGE										163 CHARGE																																																																					
163 CHARGE																																																																															
164 CHARGE										165 CHARGE										166 CHARGE										167 CHARGE																																																	
164 CHARGE										165 CHARGE										166 CHARGE										167 CHARGE																																																	
165 CHARGE										166 CHARGE										167 CHARGE																																																											
166 CHARGE										167 CHARGE																																																																					
167 CHARGE																																																																															
168 CHARGE										169 CHARGE										170 CHARGE										171 CHARGE																																																	
168 CHARGE										169 CHARGE										170 CHARGE										171 CHARGE																																																	
169 CHARGE										170 CHARGE										171 CHARGE																																																											
170 CHARGE										171 CHARGE																																																																					
171 CHARGE																																																																															
172 CHARGE										173 CHARGE										174 CHARGE										175 CHARGE																																																	
172 CHARGE										173 CHARGE										174 CHARGE										175 CHARGE																																																	
173 CHARGE										174 CHARGE										175 CHARGE																																																											
174 CHARGE										175 CHARGE																																																																					
175 CHARGE																																																																															
176 CHARGE										177 CHARGE										178 CHARGE										179 CHARGE																																																	
176 CHARGE										177 CHARGE										178 CHARGE										179 CHARGE																																																	
177 CHARGE										178 CHARGE										179 CHARGE																																																											
178 CHARGE										179 CHARGE																																																																					
179 CHARGE																																																																															
180 CHARGE										181 CHARGE										182 CHARGE										183 CHARGE																																																	
180 CHARGE										181 CHARGE										182 CHARGE										183 CHARGE																																																	
181 CHARGE										182 CHARGE										183 CHARGE																																																											
182 CHARGE										183 CHARGE																																																																					
183 CHARGE																																																																															
184 CHARGE										185 CHARGE										186 CHARGE										187 CHARGE																																																	
184 CHARGE										185 CHARGE										186 CHARGE										187 CHARGE																																																	
185 CHARGE										186 CHARGE										187 CHARGE																																																											
186 CHARGE										187 CHARGE																																																																					
187 CHARGE																																																																															
188 CHARGE										189 CHARGE										190 CHARGE										191 CHARGE																																																	
188 CHARGE										189 CHARGE										190 CHARGE										191 CHARGE																																																	
189 CHARGE										190 CHARGE										191 CHARGE																																																											
190 CHARGE										191 CHARGE																																																																					
191 CHARGE																																																																															
192 CHARGE										193 CHARGE										194 CHARGE										195 CHARGE																																																	
192 CHARGE										193 CHARGE										194 CHARGE										195 CHARGE																																																	
193 CHARGE										194 CHARGE										195 CHARGE																																																											
194 CHARGE										195 CHARGE																																																																					
195 CHARGE																																																																															
196 CHARGE										197 CHARGE										198 CHARGE										199 CHARGE																																																	
196 CHARGE										197 CHARGE										198 CHARGE										199 CHARGE																																																	
197 CHARGE										198 CHARGE										199 CHARGE																																																											
198 CHARGE										199 CHARGE																																																																					
199 CHARGE																																																																															
200 CHARGE										201 CHARGE										202 CHARGE										203 CHARGE																																																	
200 CHARGE										201 CHARGE										202 CHARGE										203 CHARGE																																																	
201 CHARGE										202 CHARGE										203 CHARGE																																																											
202 CHARGE										203 CHARGE																																																																					
203 CHARGE																																																																															
204 CHARGE										205 CHARGE										206 CHARGE										207 CHARGE																																																	
204 CHARGE										205 CHARGE										206 CHARGE										207 CHARGE																																																	
205 CHARGE										206 CHARGE										207 CHARGE																																																											
206 CHARGE										207 CHARGE																																																																					
207 CHARGE																																																																															
208 CHARGE										209 CHARGE										210 CHARGE										211 CHARGE																																																	
208 CHARGE										209 CHARGE										210 CHARGE										211 CHARGE																																																	
209 CHARGE										210 CHARGE										211 CHARGE																																																											
210 CHARGE										211 CHARGE																																																																					
211 CHARGE																																																																															
212 CHARGE										213 CHARGE										214 CHARGE										215 CHARGE																																																	
212 CHARGE										213 CHARGE										214 CHARGE										215 CHARGE																																																	
213 CHARGE										214 CHARGE										215 CHARGE																																																											
214 CHARGE										215 CHARGE																																																																					
215 CHARGE																																																																															
216 CHARGE										217 CHARGE										218 CHARGE										219 CHARGE																																																	
216 CHARGE										217 CHARGE										218 CHARGE										219 CHARGE																																																	
217 CHARGE										218 CHARGE										219 CHARGE																																																											
218 CHARGE										219 CHARGE																																																																					
219 CHARGE																																																																															
220 CHARGE										221 CHARGE										222 CHARGE										223 CHARGE																																																	
220 CHARGE										221 CHARGE										222 CHARGE										223 CHARGE																																																	
221 CHARGE										222 CHARGE										223 CHARGE																																																											
222 CHARGE										223 CHARGE																																																																					
223 CHARGE																																																																															
224 CHARGE										225 CHARGE										226 CHARGE										227 CHARGE																																																	
224 CHARGE										225 CHARGE										226 CHARGE										227 CHARGE																																																	
225 CHARGE										226 CHARGE										227 CHARGE																																																											
226 CHARGE										227 CHARGE																																																																					
227 CHARGE																																																																															
228 CHARGE										229 CHARGE										230 CHARGE										231 CHARGE																																																	
228 CHARGE										229 CHARGE										230 CHARGE										231 CHARGE																																																	
229 CHARGE										230 CHARGE										231 CHARGE																																																											
230 CHARGE										231 CHARGE																																																																					
231 CHARGE																																																																															
232 CHARGE										233 CHARGE										234 CHARGE										235 CHARGE																																																	
232 CHARGE										233 CHARGE										234 CHARGE										235 CHARGE																																																	
233 CHARGE										234 CHARGE										235 CHARGE																																																											
234 CHARGE										235 CHARGE																																																																					
235 CHARGE																																																																															
236 CHARGE										237 CHARGE										238 CHARGE										239 CHARGE																																																	
236 CHARGE										237 CHARGE										238 CHARGE										239 CHARGE																																																	
237 CHARGE										238 CHARGE										239 CHARGE																																																											
238 CHARGE										239 CHARGE																																																																					
239 CHARGE																																																																															
240 CHARGE										241 CHARGE										242 CHARGE										243 CHARGE																																																	
240 CHARGE										241 CHARGE										242 CHARGE										243 CHARGE																																																	
241 CHARGE										242 CHARGE										243 CHARGE																																																											
242 CHARGE										243 CHARGE																																																																					
243 CHARGE																																																																															
244 CHARGE										245 CHARGE										246 CHARGE										247 CHARGE																																																	
244 CHARGE										245 CHARGE										246 CHARGE										247 CHARGE																																																	
245 CHARGE										246 CHARGE										247 CHARGE																																																											
246 CHARGE										247 CHARGE																																																																					
247 CHARGE																																																																															
248 CHARGE										249 CHARGE										250 CHARGE										251 CHARGE																																																	
248 CHARGE										249 CHARGE										250 CHARGE										251 CHARGE																																																	
249 CHARGE										250 CHARGE										251 CHARGE																																																											
250 CHARGE										251 CHARGE																																																																					
251 CHARGE																																																																															
252 CHARGE										253 CHARGE										254 CHARGE										255 CHARGE																																																	
252 CHARGE										253 CHARGE										254 CHARGE										255 CHARGE																																																	
253 CHARGE										254 CHARGE										255 CHARGE																																																											
254 CHARGE										255 CHARGE																																																																					
255 CHARGE																																																																															
256 CHARGE										257 CHARGE										258 CHARGE										259 CHARGE																																																	
256 CHARGE										257 CHARGE										258 CHARGE										259 CHARGE																																																	
257 CHARGE										258 CHARGE										259 CHARGE																																																											
258 CHARGE										259 CHARGE																																																																					
259 CHARGE																																																																															
260 CHARGE										261 CHARGE										262 CHARGE										263 CHARGE																																																	
260 CHARGE										261 CHARGE										262 CHARGE										263 CHARGE																																																	
261 CHARGE										262 CHARGE										263 CHARGE																																																											
262 CHARGE										263 CHARGE																																																																					
263 CHARGE																																																																															
264 CHARGE										265 CHARGE										266 CHARGE										267 CHARGE																																																	
264 CHARGE										265 CHARGE										266 CHARGE										267 CHARGE																																																	
265 CHARGE										266 CHARGE										267 CHARGE																																																											
266 CHARGE										267 CHARGE																																																																					
267 CHARGE																																																																															
268 CHARGE										269 CHARGE										270 CHARGE										271 CHARGE																																																	
268 CHARGE										269 CHARGE										270 CHARGE										271 CHARGE																																																	
269 CHARGE										270 CHARGE										271 CHARGE																																																											
270 CHARGE										271 CHARGE																																																																					
271 CHARGE																																																																															
272 CHARGE										273 CHARGE										274 CHARGE										275 CHARGE																																																	
272 CHARGE										273 CHARGE										274 CHARGE										275 CHARGE																																																	
273 CHARGE										274 CHARGE										275 CHARGE																																																											
274 CHARGE										275 CHARGE																																																																					
275 CHARGE																																																																															
276 CHARGE										277 CHARGE										278 CHARGE										279 CHARGE																																																	
276 CHARGE										277 CHARGE										278 CHARGE										279 CHARGE																																																	
277 CHARGE										278 CHARGE										279 CHARGE																																																											
278 CHARGE										279 CHARGE																																																																					
279 CHARGE																																																																															
280 CHARGE										281 CHARGE										282 CHARGE										283 CHARGE																																																	
280 CHARGE										281 CHARGE										282 CHARGE										283 CHARGE																																																	
281 CHARGE										282 CHARGE										283 CHARGE																																																											
282 CHARGE										283 CHARGE																																																																					
283 CHARGE																																																																															
284 CHARGE										285 CHARGE										286 CHARGE										287 CHARGE																																																	
284 CHARGE										285 CHARGE										286 CHARGE										287 CHARGE																																																	
285 CHARGE										286 CHARGE										287 CHARGE																																																											
286 CHARGE										287 CHARGE																																																																					
287 CHARGE																																																																															
288 CHARGE										289 CHARGE										290 CHARGE										291 CHARGE																																																	
288 CHARGE										289 CHARGE										290 CHARGE										291 CHARGE																																																	
289 CHARGE										290 CHARGE										291 CHARGE																																																											
290 CHARGE										291 CHARGE																																																																					
291 CHARGE																																																																															
292 CHARGE										293 CHARGE										294 CHARGE										295 CHARGE																																																	
292 CHARGE										293 CHARGE										294 CHARGE										295 CHARGE																																																	
293 CHARGE										294 CHARGE										295 CHARGE																																																											
294 CHARGE																																																																															

INITIAL ACCIDENT INVESTIGATION REPORT

Station _____

Case No. _____

14	15	16	17	18	19	20	21	22	23	24	NAMES- ADDRESSES OF OCCUPANTS-IF DECEASED: DATE&TIME OF DEATH
0.1	7	U	1	6.9	F	1.2	6	1	SEE NARRATIVE		
0.1	7	U	1	6.2	F	1.2	6	1	SEE NARRATIVE		
0.2	1	1	1	2.4	M	0.9	7	2			

123 Show NORTH
by arrow

SEE ATTACHED DIAGRAMS

124 Accident Description

DRIVER #1 STATED: HE WAS TRAVELLING NORTH BOUND IN THE LEFT LANE COMING FROM
ENROUTE TO _____ WHEN HE SAW A VEHICLE COMING AT HIM HEAD
ON IN THE LEFT LANE. HE HAD NO WHERE TO GO AND THAT WAS ALL HE COULD
REMEMBER.

DRIVER #2: REFUSED TO GIVE A STATEMENT.

INVESTIGATION AT THE SCENE REVEALED: VEH. 1 WAS TRAVELLING NORTHBOUND IN THE LEFT
LANE OF THE _____ WHEN IT WAS STRUCK HEAD ON IN THE LL BY VEH. 2 TRAVELLING
SOUTHBOUND IN THE SAME LANE. AFTER INITIAL IMPACT VEH. 1 SPIN CLOCKWISE AND
WAS SENT AIRBORNE, STRUCK THE CENTER CONCRETE BARRIER WITH THE REAR DRIVER
SIDE AND CAME TO A FINAL RESTING POSITION ON TOP OF IT FACING SOUTHEAST.
VEH. 2 REBOUNDED REARWARD COMING TO A REST ACROSS THE 2ND AND 3RD LANE
ALSO FACING SOUTHEAST.

AT SOME POINT AFTER INITIAL IMPACT, VEH. 1 BURST INTO FLAMES. A PASSING MOTORIST,
IDENTIFIED AS _____ RESCUED THE DRIVER
AND RF PASSENGER FROM VEH. 1. FURTHER RESCUE ATTEMPTS OF THE REMAINING FOUR
PASSENGERS IN VEH. 1 WERE IMPOSSIBLE DUE TO IT BEING FULLY ENGULFED BY FLAMES.

UPON MY ARRIVAL AT THE SCENE, OFFICERS _____ AND

125. TROOPER'S SIGNATURE _____

126. BADGE NO. _____

127. STATION _____

128. TROOP _____

PAGE 2 of 6

MOTOR VEHICLE ACCIDENT DESCRIPTION

Station _____

Case No. _____

124 Accident Description

P.D. WERE CHECKING THE DRIVER OF VEH. 2.

MEMBERS OF _____ WERE ATTENDING TO THE RESCUED OCCUPANTS OF VEH. 1 JUST NORTH OF THE TWO VEHICLES. DRIVER 2 WAS REMOVED FROM HIS VEHICLE BY THE _____ OFFICERS DUE TO THE FUEL SPILLING UNDER THE VEHICLE AND THE CLOSE PROXIMITY OF VEH. 1 ON FIRE. _____ AND I SECURED

THE SCENE AND DIVERTED TRAFFIC AROUND IT. FIRE DEPT., AMBULANCE,

FIRE DEPT., E.M.S., AND F.A.S. ALSO RESPONDED TO THE SCENE. THE FIRE WAS EXTINGUISHED BY THE FIRE DEPARTMENTS. DRIVER AND PASSENGER OF VEH. 1 WERE TRANSPORTED TO UNIVERSITY HOSPITAL IN _____ BY _____ AND

FIRST AID SQUADS RESPECTIVELY. DRIVER 2 WAS TRANSPORTED TO _____ BY _____ FIRST AID SQUAD ALSO. BLOOD WAS DRAWN AND LOGGED AS EVIDENCE AT _____ STATION.

_____ NORTH RESPONDED AND PROCESSED THE SCENE.

A.A.I. RESPONDED AND ASSISTED PROCESSING THE SCENE.

_____ RESPONDED AND DR. _____ PRONOUNCED

THE FOUR UNKNOWN PASSENGERS IN VEH. 1 DEAD AT 5:40 AM.

AND _____ OF THE _____ PROS. OFFICE RESPONDED TO ASSIST THE INVESTIGATION.

VEH. 1, INTACT WITH THE FOUR UNKNOWN DECEASED, WERE TRANSPORTED TO THE M.E. OFFICE IN _____ FOR IDENTIFICATION PURPOSES BY _____

_____ RESPONDED TO THE

M.E. OFFICE AND ASSISTED IDENTIFYING THE FOUR UNKNOWN OCCUPANTS. THE OCCUPANTS WERE TENTATIVELY IDENTIFIED AS _____ FEMALE, AGE 72, OF _____ FEMALE,

AGE 80, OF _____ FEMALE,

AGE 69, OF _____ AND _____ FEMALE,

AGE 62, OF _____ FINAL CONFIRMATION OF THEIR

IDENTITIES IS PENDING THE RESULTS OF DENTAL RECORDS CHECK.

SUMMONSES *

_____ WERE ISSUED TO DRIVER 2 PENDING FURTHER INVESTIGATION BY _____ AND _____

PROS. OFFICE. SERVICE TICKET _____

WERE ALSO ISSUED TO RESPONDING EMERGENCY SERVICES.

_____ : INFO. UNAVAILABLE DUE TO FIRE, TO BE PROVIDED AT A LATER DATE.

_____ : DUE TO FIRE, IT WAS UNABLE TO DETERMINE IF 4 DECEASED IN REAR AREA WERE WEARING SAFETY DEVICES.

TROOPER'S SIGNATURE _____

BADGE NO. _____

STATION, _____

TROOP _____

PAGE 3 of 6

MOTOR VEHICLE ACCIDENT DESCRIPTION

Station _____

Case No. _____

124 Accident Description

	NORTH	SOUTH	EAST	WEST
RP1-A	—	39' 10"	8' 4"	—
RP1-B	13' 6"	—	—	—
RP1-C	15' 7"	—	5'	—
RP1-D	2' 10"	—	19' 2"	—
RP1-E	—	2'	23' 3"	—

RP1 = REFERENCE POINT 1 NORTH EAST CORNER OF STORM DRAIN
LOCATED 68' 8" NORTH OF MP.

A = INITIAL POINT OF IMPACT (GOUGE MARK IN LEFT LANE)

B = RIGHT FRONT TIRE OF VEHICLE 1

C = LEFT FRONT TIRE OF VEHICLE 1

D = RIGHT REAR TIRE OF VEHICLE 2

E = RIGHT FRONT TIRE OF VEHICLE 2

TROOPER'S SIGNATURE

BADGE NO.

STATION

TROOP

PAGE

4 of 6

BEST AVAILABLE

ENLARGED MOTOR VEHICLE ACCIDENT DIAGRAM


Station _____
Case No. _____

123 SHOW NORTH
BY ARROW



(SCALE 1 INCH = 10 FEET) RE-IMPACT / IMPACT

CENTER MEDIAN
LEFT SHOULDER



MVA-4A (3-90)

TROOPER'S SIGNATURE		BADGE NO.	STATION	TROOP	PAGE 5 of 6
---------------------	--	-----------	---------	-------	-------------

62'8"

MP

1

2

pot

RIGHT

SHOULDER

BEST AVAILABLE

ENLARGED MOTOR VEHICLE ACCIDENT DIAGRAM

Station

Case No.


123 SHOW NORTH
BY ARROW



SCALE 1 INCH = 10 FEET POST ACCIDENT


CENTER MEDIAN
LEFT SHOULDER

33'
10'




PH 1


BEST AVAILABLE



TROOPER'S SIGNATURE	BADGE NO.	STATION	TROOP	PAGE 6 of 6



BEST AVAILABLE






BEST AVAILABLE




BEST AVAILABLE



BEST AVAILABLE




BEST AVAILABLE




BEST AVAILABLE



BEST AVAILABLE




BEST AVAILABLE




BEST AVAILABLE




BEST AVAILABLE










BEST AVAILABLE



BEST AVAILABLE



BEST AVAILABLE



BEST AVAILABLE

Summary of Results Using Damage

DSI-95-SP-013

Speed Change
(Damage)

Vehicle #1

Total 64 km/h (40 mph)
 Longitudinal -63 km/h (-39 mph)
 Latitudinal -11 km/h (-7 mph)
 PDOF Angle 10 °
 Energy Dissipated = 429100 Joules (316445 Ft-Lb)
 Barrier Equivalent Speed = 72.3 km/h (44.9 mph)
 Calculated using size and stiffness categories.

Vehicle #2

Total 94 km/h (58 mph)
 Longitudinal -92 km/h (-57 mph)
 Latitudinal -16 km/h (-10 mph)
 PDOF Angle 10 °
 Energy Dissipated = 375132 Joules (276646 Ft-Lb)
 Barrier Equivalent Speed = 83.6 km/h (52.0 mph)
 Calculated using size and stiffness categories.

General Information

	Vehicle #1	Vehicle #2
Year	1983	1991
Make	Dodge	Toyota
Model	Ram Van	Celica
CDC	12FDEW7	12FDEW4
Side Damaged	F	F
PDOF Angle	10 °	10 °
Heading Angle	0 °	180 °

Calculation method: Size and Stiffness Size and Stiffness

Size Category 7 2
 Stiffness Category 7 2
 Vehicle Weight 1978 kgs (4361 lbs) 1344 kgs (2963 lbs)



ACCIDENT FORM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-95-SP-013

IDENTIFICATION

3. Number of General Vehicle
Forms Submitted02

4. Date of Accident

(Month, Day, Year) SUMMER 1 WEEKDAY 9 5

5. Time of Accident

EARLY MORNING

Code reported military time of accident.

NOTE: Midnight = 2400
Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. _____ SS15 Administrative Use 07. _____ SS16 Pedestrian Crash Data Study 0
(Data for this special study available
in a separate file.)8. _____ SS17 Impact Fires 09. _____ SS18 Unsafe Driver Actions 0

10. _____ SS19 _____

NUMBER OF EVENTS

11. Number of Recorded Events
in This Accident04Code the number of events which occurred
in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columns.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. <u>0 1</u>	13. <u>01</u>	14. <u>01</u>	15. <u>F</u>	16. <u>02</u>	17. <u>21</u>	18. <u>F</u>
19. <u>0 2</u>	20. <u>02</u>	21. <u>21</u>	22. <u>L</u>	23. <u>54</u>	24. <u>00</u>	25. <u>0</u>
26. <u>0 3</u>	27. <u>02</u>	28. <u>21</u>	29. <u>U</u>	30. <u>54</u>	31. <u>00</u>	32. <u>0</u>
33. <u>0 4</u>	34. <u>02</u>	35. <u>21</u>	36. <u>N</u>	37. <u>33</u>	38. <u>00</u>	39. <u>N</u>
40. <u>0 5</u>	41. _____	42. _____	43. _____	44. _____	45. _____	46. _____

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

CODES FOR CLASS OF VEHICLE

- | | |
|--|--|
| <ul style="list-style-type: none"> (00) Not a motor vehicle (01) Subcompact/mini (wheelbase < 254 cm) (02) Compact (wheelbase ≥ 254 but < 265 cm) (03) Intermediate (wheelbase ≥ 265 but < 278 cm) (04) Full size (wheelbase ≥ 278 but < 291 cm) (05) Largest (wheelbase ≥ 291 cm) (09) Unknown passenger car size (14) Compact utility vehicle (15) Large utility vehicle (≤ 4,500 kgs GVWR) (16) Utility station wagon (≤ 4,500 kgs GVWR) (19) Unknown utility type (20) Minivan (≤ 4,500 kgs GVWR) (21) Large van (≤ 4,500 kgs GVWR) (24) Van Based school bus (≤ 4,500 kgs GVWR) (28) Other van type (≤ 4,500 kgs GVWR) (29) Unknown van type (≤ 4,500 kgs GVWR) (30) Compact pickup truck (≤ 4,500 kgs GVWR) | <ul style="list-style-type: none"> (31) Large pickup truck (≤ 4,500 kgs GVWR) (38) Other pickup truck (≤ 4,500 kgs GVWR) (39) Unknown pickup truck type (≤ 4,500 kgs GVWR) (45) Other light truck (≤ 4,500 kgs GVWR) (48) Unknown light truck type (≤ 4,500 kgs GVWR) (49) Unknown light vehicle type (50) School bus (excludes van based)(> 4,500 kgs GVWR) (58) Other bus (> 4,500 kgs GVWR) (59) Unknown bus type (60) Truck (> 4,500 kgs GVWR) (67) Tractor without trailer (68) Tractor-trailer(s) (78) Unknown medium/heavy truck type (79) Unknown light/medium/heavy truck type (80) Motored cycle (90) Other vehicle (99) Unknown |
|--|--|

CODES FOR GENERAL AREA OF DAMAGE (GAD)

- | | | | |
|--|--|---|---|
| CDS APPLICABLE
AND OTHER
VEHICLES | <ul style="list-style-type: none"> (0) Not a motor vehicle (N) Noncollision (F) Front | <ul style="list-style-type: none"> (R) Right side (L) Left side (B) Back | <ul style="list-style-type: none"> (T) Top (U) Undercarriage (9) Unknown |
|--|--|---|---|
-
- | | | | |
|--|--|---|---|
| TDC
APPLICABLE
VEHICLES | <ul style="list-style-type: none"> (0) Not a motor vehicle (N) Noncollision (F) Front (R) Right side | <ul style="list-style-type: none"> (L) Left side (B) Back of unit with cargo area
(rear of trailer or straight truck) (D) Back (rear of tractor) | <ul style="list-style-type: none"> (C) Rear of cab (V) Front of cargo area (T) Top (U) Undercarriage (9) Unknown |
|--|--|---|---|

CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

- | | |
|---|--|
| <p>(01-30) — Vehicle Number</p> <p>Noncollision</p> <ul style="list-style-type: none"> (31) Overturn — rollover (excludes end-over-end) (32) Rollover — end-over-end (33) Fire or explosion (34) Jackknife (35) Other intraunit damage (specify): _____ (36) Noncollision injury (38) Other noncollision (specify): _____ (39) Noncollision — details unknown <p>Collision With Fixed Object</p> <ul style="list-style-type: none"> (41) Tree (≤ 10 cm in diameter) (42) Tree (> 10 cm in diameter) (43) Shrubbery or bush (44) Embankment (45) Breakaway pole or post (any diameter) <p>Nonbreakaway Pole or Post</p> <ul style="list-style-type: none"> (50) Pole or post (≤ 10 cm in diameter) (51) Pole or post (> 10 cm but ≤ 30 cm in diameter) (52) Pole or post (> 30 cm in diameter) (53) Pole or post (diameter unknown) (54) Concrete traffic barrier (55) Impact attenuator (56) Other traffic barrier (includes guardrail)
(specify): _____ | <ul style="list-style-type: none"> (57) Fence (58) Wall (59) Building (60) Ditch or culvert (61) Ground (62) Fire hydrant (63) Curb (64) Bridge (68) Other fixed object (specify): _____ (69) Unknown fixed object <p>Collision with Nonfixed Object</p> <ul style="list-style-type: none"> (70) Passenger car, light truck, van, or other vehicle not in-transport (71) Medium/heavy truck or bus not in-transport (72) Pedestrian (73) Cyclist or cycle (74) Other nonmotorist or conveyance (75) Vehicle occupant (76) Animal (77) Train (78) Trailer, disconnected in transport (79) Object fell from vehicle in-transport (88) Other nonfixed object (specify): _____ (89) Unknown nonfixed object (98) Other event (specify): _____ (99) Unknown event or object |
|---|--|



GENERAL VEHICLE FORM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DS1-95-SP-013

3. Vehicle Number

01

VEHICLE IDENTIFICATION

4. Vehicle Model Year

Code the last two digits of the model year
(99) Unknown

83

5. Vehicle Make (specify):

DODGE

Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(99) Unknown

07

6. Vehicle Model (specify):

RAM VAN

Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(999) Unknown

461

7. Body Type

Note: Applicable codes may be found on
the back of this page.

21

8. Vehicle Identification Number

2 B 7 H B 2 3 T 6 D K X X X X X X X

Left justify; Slash zeros and letter Z (0 and Z)
No VIN—Code all zeros
Unknown—Code all nines

9. Vehicle Special Use (This Trip)

- (0) No special use
(1) Taxi
(2) Vehicle used as school bus
(3) Vehicle used as other bus
(4) Military
(5) Police
(6) Ambulance
(7) Fire truck or car
(8) Other (specify):
(9) Unknown

0

OFFICIAL RECORDS

10. Police Reported Vehicle Disposition

- (0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

1

11. Police Reported Travel Speed

Code to the nearest kmph (NOTE: 000 means
less than 0.5 kmph)
(160) 159.5 kmph and above
(999) Unknown

999

____ mph X 1.6093 = ____ kmph

12. Speed Limit

- (000) No statutory limit
Code posted or statutory speed limit
in kmph
(999) Unknown

089

55 mph X 1.6093 = 089 kmph

13. Police Reported Alcohol Presence For Driver

- (0) No alcohol present
(1) Yes alcohol present
(7) Not reported
(8) No driver present
(9) Unknown

9

14. Alcohol Test Result For Driver

- Code actual value (decimal implied
before first digit—0.xx)
(95) Test refused
(96) None given
(97) AC test performed, results unknown
(98) No driver present
(99) Unknown

97

Source: PAR

15. Police Reported Other Drug Presence For
Driver

- (0) No other drug(s) present
(1) Yes other drug(s) present
(7) Not reported
(8) No driver present
(9) Unknown

9

16. Other Drug Specimen Test Result For Driver

- (0) No specimen test given
(1) Drug(s) not found in specimen
(2) Drug(s) found in specimen, (specify):
(3) Specimen test given, results unknown or not
obtained
(8) No driver present
(9) Unknown if specimen test given

9

17. Driver's Zip Code

- (00001) Driver not a resident of U.S. or territories
Code actual 5-digit zip code
(99998) No driver present
(99999) Unknown

18. Driver's Race/Ethnic Origin

- (1) White (non-Hispanic)
(2) Black (non-Hispanic)
(3) White (Hispanic)
(4) Black (Hispanic)
(5) American Indian, Eskimo or Aleut
(6) Asian or Pacific Islander
(7) Other (specify):
(8) No driver present
(9) Unknown

9

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): _____
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles ($\leq 4,500$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks ($\leq 4,500$ kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ($\leq 4,500$ kgs GVWR)
- (23) Van based motorhome ($\leq 4,500$ kgs GVWR)
- (24) Van based school bus ($\leq 4,500$ kgs GVWR)
- (25) Van based other bus ($\leq 4,500$ kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): _____
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, $\leq 4,500$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)

- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks ($\leq 4,500$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): _____
- (59) Unknown bus type

Medium/Heavy Trucks ($> 4,500$ kgs GVWR)

- (60) Step van ($> 4,500$ kgs GVWR)
- (61) Single unit straight truck ($4,500$ kgs $<$ GVWR $\leq 8,850$ kgs)
- (62) Single unit straight truck ($8,850$ kgs $<$ GVWR $\leq 12,000$ kgs)
- (63) Single unit straight truck ($> 12,000$ kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): _____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction φ

- (0) Non-interchange area and non-junction
- (1) Interchange area related

Non-Interchange junctions

- (2) Intersection related
- (3) Driveway, alley access related
- (4) Other junction (specify) _____

- (5) Unknown type of junction

- (9) Unknown

20. Trafficway Flow 2

- (0) Not physically divided (two way traffic)
- (1) Divided trafficway-median strip without positive barrier
- (2) Divided trafficway-median strip with positive barrier
- (3) One way traffic
- (9) Unknown

21. Number Of Travel Lanes 5

- (1) One
- (2) Two
- (3) Three
- (4) Four
- (5) Five
- (6) Six
- (7) Seven or more
- (9) Unknown

22. Roadway Alignment 1

- (1) Straight
- (2) Curve right
- (3) Curve left
- (9) Unknown

23. Roadway Profile 2

- (1) Level
- (2) Uphill grade (>2%)
- (3) Hill crest
- (4) Downhill grade (>2%)
- (5) Sag
- (9) Unknown

24. Roadway Surface Type 2

- (1) Concrete
- (2) Bituminous (asphalt)
- (3) Brick or block
- (4) Slag, gravel, or stone
- (5) Dirt
- (8) Other (specify): _____
- (9) Unknown

25. Roadway Surface Condition 1

- (1) Dry
- (2) Wet
- (3) Snow or slush
- (4) Ice
- (5) Sand, dirt, or oil
- (8) Other (specify): _____
- (9) Unknown

26. Light Conditions 3

- (1) Daylight
- (2) Dark
- (3) Dark, but lighted
- (4) Dawn
- (5) Dusk
- (9) Unknown

27. Atmospheric Conditions φ

- (0) No adverse atmospheric-related driving conditions
- (1) Rain
- (2) Sleet/hail
- (3) Snow
- (4) Fog
- (5) Rain and fog
- (6) Sleet and fog
- (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
- (9) Unknown

28. Traffic Control Device φ

- (0) No traffic control(s)
- (1) Traffic control signal (not RR crossing)

Regulatory






































- (2) Stop sign
- (3) Yield sign
- (4) School zone sign
- (5) Other regulatory sign (specify): _____

- (6) Warning sign (not RR crossing)
- (7) Unknown sign
- (8) Miscellaneous/other controls including RR controls (specify): _____

- (9) Unknown

29. Traffic Control Device Functioning φ

- (0) No traffic control device
- (1) Traffic control device not functioning (specify) _____
- (2) Traffic control device functioning properly
- (9) Unknown

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I. Single Driver	A. Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B. Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C. Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II. Same Trafficway Same Direction	D. Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 26, 27	 24 DECEL. 28, 29, 30, 31	 26 AVOID COLLISION WITH VEH.	(EACH • 32) SPECIFICS OTHER (EACH • 33) SPECIFICS UNKNOWN
	E. Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	(EACH • 42) SPECIFICS OTHER (EACH • 43) SPECIFICS UNKNOWN
	F. Sideswipe Angle	 44 45 46 47	 46 45 47	(EACH • 48) SPECIFICS OTHER	(EACH • 49) SPECIFICS UNKNOWN	
III. Same Trafficway Opposite Direction	G. Head-On	 50 LATERAL MOVE	(EACH • 52) SPECIFICS OTHER	(EACH • 53) SPECIFICS UNKNOWN		
	H. Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	(EACH • 62) SPECIFICS OTHER (EACH • 63) SPECIFICS UNKNOWN
	I. Sideswipe Angle	 64 LATERAL MOVE	(EACH • 66) SPECIFICS OTHER	(EACH • 67) SPECIFICS UNKNOWN		
IV. Change Trafficway Vehicle Turning	J. Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 71 INITIAL SAME DIRECTIONS	 73 72	(EACH • 74) SPECIFICS OTHER	(EACH • 75) SPECIFICS UNKNOWN
	K. Turn Into Path	 77 76 TURN INTO SAME DIRECTION	 79 78 TURN INTO OPPOSITE DIRECTIONS	 81 80 TURN INTO OPPOSITE DIRECTIONS	 83 82	(EACH • 84) SPECIFICS OTHER (EACH • 85) SPECIFICS UNKNOWN
V. Intersecting Paths (Vehicle Damage)	L. Straight Paths	 87 86	 88 89	(EACH • 90) SPECIFICS OTHER	(EACH • 91) SPECIFICS UNKNOWN	
VI. Miscellaneous	M. Backing Etc.	 92 BACKING VEH.	 93 OTHER VEH. OR OBJECT	98 Other Accident Type 99 Unknown Accident Type 00 No Impact		

PRECRASH DRIVER RELATED DATA

30. Driver's Distraction/Inattention To Driving
(Prior To Recognition Of Critical Event)99

- (00) No driver present
- (01) Attentive or not distracted
- (02) Looked but did not see
Distractions
- (03) By other occupant(s), (specify): _____
- (04) By moving object in vehicle (specify): _____
- (05) While talking or listening to cellular phone (specify location and type of phone): _____
- (06) While dialing cellular phone (specify location and type of phone): _____
- (07) While adjusting climate controls
- (08) While adjusting radio, cassette, CD (specify): _____
- (09) While using other device/object in vehicle (specify): _____
- (10) Sleepy or fell asleep
- (11) Distracted by outside person, object, or event (specify): _____
- (12) Eating or drinking
- (13) Smoking related
- (97) Distracted/inattentive, details unknown
- (98) Other, distraction (specify): _____
- (99) Unknown

31. Pre-Event Movement (Prior to Recognition of Critical Event)

01

- (00) No driver present
- (01) Going straight
- (02) Decelerating in traffic lane
- (03) Accelerating in traffic lane
- (04) Starting in traffic lane
- (05) Stopped in traffic lane
- (06) Passing or overtaking another vehicle
- (07) Disabled or parked in travel lane
- (08) Leaving a parking position
- (09) Entering a parking position
- (10) Turning right
- (11) Turning left
- (12) Making a U-turn
- (13) Backing up (other than for parking position)
- (14) Negotiating a curve
- (15) Changing lanes
- (16) Merging
- (17) Successful avoidance maneuver to a previous critical event
- (97) Other (specify): _____
- (99) Unknown

32. Critical Precrash Event

54*This Vehicle Loss of Control Due To:*

- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off) (specify): _____
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): _____
- (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): _____
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): _____
- (09) Unknown cause of control loss

This Vehicle Traveling

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (18) This vehicle decelerating
- (19) Unknown travel direction

Other Motor Vehicle In Lane

- (50) Other vehicle stopped
- (51) Traveling in same direction with lower steady speed
- (52) Traveling in same direction while decelerating
- (53) Traveling in same direction with higher speed
- (54) Traveling in opposite direction
- (55) In crossover
- (56) Backing
- (59) Unknown travel direction of other motor vehicle in lane

Other Motor Vehicle Encroaching Into Lane

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

Pedestrian, Pedalcyclist, or Other Nonmotorist

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway (specify): _____
- (84) Pedalcyclist or other nonmotorist approaching roadway, (specify): _____
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): _____

Object or Animal

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location
- (98) Other critical precrash event (specify): _____
- (99) Unknown

33. Attempted Avoidance Maneuver 01

- (00) No driver present
- (01) No avoidance maneuver
- (02) Braking (no lockup)
- (03) Braking (lockup)
- (04) Braking (lockup unknown)
- (05) Releasing brakes
- (06) Steering left
- (07) Steering right
- (08) Braking and steering left
- (09) Braking and steering right
- (10) Accelerating
- (11) Accelerating and steering left
- (12) Accelerating and steering right
- (98) Other action (specify):

(99) Unknown

34. Pre-Impact Stability 1

- (0) No driver present
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify):

(9) Precrash stability unknown

35. Pre-Impact Location 1

- (0) No driver present
- (1) Stayed in original travel lane
- (2) Stayed on roadway but left original travel lane
- (3) Stayed on roadway, not known if left original travel lane
- (4) Departed roadway
- (5) Remained off roadway
- (6) Returned to roadway
- (7) Entered roadway
- (9) Unknown

36. Accident Type 52

(Note: Applicable codes on back of this page)

- (00) No impact

Code the number of the diagram that best describes the accident circumstance

- (98) Other accident type (specify):

(99) Unknown

STOP HERE IF GV07 DOES NOT EQUAL 01 - 49

OCCUPANT RELATED

37. Driver Presence in Vehicle 1
 (0) Driver not present
 (1) Driver present
 (9) Unknown
38. Number of Occupants This Vehicle 6
 (00-96) Code actual number of occupants for this vehicle
 (97) 97 or more
 (99) Unknown
39. Number of Occupant Forms Submitted 6

AIR BAG RELATED

40. Is this an AOPS Vehicle? 0
 (0) No (includes unknown)
 (1) Yes - researcher determined
 (2) VIN determined air bag system
 (3) VIN determined automatic (passive) belts
 (4) VIN determined air bag and automatic (passive) belts
41. Air Bag(s) Deployment, First Seat Frontal 0
 (0) Not equipped or not available
 (1) No air bags deployed
Single Air Bag Vehicle
 (2) Driver air bag deployed
 (3) Driver air bag, unknown if deployed
Multiple Air Bag Vehicle
 (4) Driver side only deployed
 (5) Passenger side only deployed
 (6) Driver and passenger side deployed
 (7) Driver and passenger side unknown if deployed
 (8) Air bag(s) deployed, details unknown
 (9) Unknown
42. Air Bag(s) Deployment, Other Than First Seat Frontal 0
 (0) Not equipped with an "other" air bag
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight 1560
 _____ Code weight to nearest 10 kilograms.
 (045) Less than 450 kilograms
 (610) 6,100 kilograms or more
 (999) Unknown
3,473 lbs X .4536 = 1575 kgs
 Source: _____

44. Vehicle Cargo Weight 9990
 _____ Code weight to nearest 10 kilograms.
 (000) Less than 5 kilograms
 (450) 4,500 kilograms or more
 (999) Unknown
 _____ lbs X .4536 = _____ kgs
 Source: _____

ROLLOVER DATA

45. Rollover 0
 (00) No rollover (no overturning)
Rollover (primarily about the longitudinal axis)
 (01-16) Code the number of quarter turns
 (17) Rollover, 17 or more quarter turns (specify):
 (98) Rollover—end-over-end (i.e., primarily about the lateral axis)
 (99) Rollover (overturn), details unknown
46. Rollover Initiation Type 0
 (00) No rollover
 (01) Trip-over
 (02) Flip-over
 (03) Turn-over
 (04) Climb-over
 (05) Fall-over
 (06) Bounce-over
 (07) Collision with another vehicle
 (08) Other rollover initiation type specify):
 (98) Rollover—end-over-end
 (99) Unknown rollover initiation type
47. Location of Rollover Initiation 0
 (0) No rollover
 (1) On roadway
 (2) On shoulder—paved
 (3) On shoulder—unpaved
 (4) On roadside or divided trafficway median
 (8) Rollover—end-over-end
 (9) Unknown
48. Rollover Initiation Object Contacted 0
 (Note: Applicable codes on back of page)
49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0
 (0) No rollover
 (1) Wheels/tires
 (2) Side plane
 (3) End plane
 (4) Undercarriage
 (5) Other location on vehicle (specify):
 (6) Non-contact rollover forces (specify):
 (8) Rollover—end-over-end
 (9) Unknown
50. Direction of Initial Roll 0
 (0) No rollover
 (1) Roll right - primarily about the longitudinal axis
 (2) Roll left - primarily about the longitudinal axis
 (8) Rollover—end-over-end
 (9) Unknown roll direction

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

Noncollision

- (31) Turn-over — fall-over
- (32) No rollover impact initiation (end-over-end)
- (34) Jackknife

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)
(specify): _____

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____

- (69) Unknown fixed object

Collision with Nonfixed Object

- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____

- (89) Unknown nonfixed object

- (98) Other event (specify): _____

- (99) Unknown event or object

OVERRIDE/UNDERRIDE (THIS VEHICLE)

51. Front Override/Underride (this Vehicle) Ø52. Rear Override/Underride (this Vehicle) Ø

- (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride

Override (see specific CDC)

[Between 2 CDS applicable vehicles (Bodytype, GV07=1-49)]

- (1) 1st CDC
(2) 2nd CDC
(3) Other not automated CDC (specify):

Underride (see specific CDC)

[Between 2 CDS applicable vehicles (Bodytype, GV07=1-49)]

- (4) 1st CDC
(5) 2nd CDC
(6) Other not automated CDC (specify):

- (7) Medium/heavy truck or bus override (of any configuration)
(9) Unknown

HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V

Values: (000)-(359) Code actual value

- (997) Noncollision
(998) Impact with object
(999) Unknown

53. Heading Angle For This Vehicle Ø Ø Ø54. Heading Angle For Other Vehicle 1 8 Ø

RECONSTRUCTION DATA

55. Towed Trailing Unit Ø

- (0) No towed unit
(1) Yes—towed trailing unit
(9) Unknown

56. Documentation of Trajectory Data for This Vehicle Ø

- (0) No
(1) Yes

57. Post Collision Condition of Tree or Pole (For Highest Delta V) Ø

- (0) Not collision (for highest delta V) with tree or pole
(1) Not damaged
(2) Cracked/sheared
(3) Tilted <45 degrees
(4) Tilted ≥45 degrees
(5) Uprooted tree
(6) Separated pole from base
(7) Pole replaced
(8) Other (specify):

(9) Unknown

ACCIDENT RECONSTRUCTION PROGRAMS HIGHEST DELTA V

58. Basis for Total (Resultant) Delta V (highest) Ø 1

- (00) No vehicle inspection

Delta V Calculated

- (01) Reconstruction program
-damage only routine
(02) Reconstruction program
-damage and trajectory routine
(03) Missing vehicle algorithm

Delta V Not Calculated

- (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.

All vehicles within scope (CDC applicable) of reconstruction program but one of the collision conditions is beyond the scope of the reconstruction program or other acceptable reconstruction technique, regardless of adequacy of damage data.

- (05) Rollover
(06) Other non-horizontal forces
(07) Sideswipe type damage
(08) Severe override
(09) Yielding object
(10) Overlapping damage
(11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available,

- (98) Other, (specify):

COMPUTER GENERATED CRASH SEVERITY

59. Total Delta V

06059.7 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means less than 0.5 kmph)

(160) 159.5 kmph and above

(999) Unknown

60. Longitudinal Component of Delta V

Highest

+059-58.8 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: __000 means greater than

-0.5 kmph and less than +0.5 kmph)

(±160) ±159.5 kmph and above

(999) Unknown

61. Lateral Component of Delta V

Highest

+010-10.4 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: __000 means greater than -0.5 kmph and less than +0.5 kmph)

(±160) ±159.5 kmph and above

(999) Unknown

62. Energy Absorption

474.60047462.4 Nearest 100 joules (highest)

____ Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)

(9997) 999,650 joules or more

(9999) Unknown

63. Impact Speed

Highest

998

____ Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means

less than 0.5 kmph)

(160) 159.5 kmph and above

(998) Trajectory algorithm not run

(999) Unknown

DELTA V CONFIDENCE LEVEL

64. Confidence In Reconstruction Program Results (For Highest Delta V)

(0) No reconstruction

(1) Collision fits model — results appear reasonable

(2) Collision fits model — results appear high

(3) Collision fits model — results appear low

(4) Borderline reconstruction — results appear reasonable

OTHER SPEED ESTIMATE

65. Barrier Equivalent Speed

Highest

07676.2 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means

less than 0.5 kmph)

(160) 159.5 kmph and above

(999) Unknown

IS MISSING VEHICLE ALGORITHM APPLICABLE FOR THIS VEHICLE? [] YES [X] NO

IF YES: IS A COMPLETED PROGRAM SUMMARY INCLUDED? [] YES [] NO

ESTIMATED DELTA V

VEHICLE INSPECTION

66. Estimated Highest Delta V (Researcher Determined)

(0) Reconstruction Delta V coded

Estimated Delta V

- (1) Less than 10 kmph
- (2) ≥ 10 kmph but < 25 kmph
- (3) ≥ 25 kmph but < 40 kmph
- (4) ≥ 40 kmph but < 55 kmph
- (5) ≥ 55 kmph

Other estimates of damage severity

- (6) Minor
- (7) Moderate
- (8) Severe

(9) Unknown

67. Type of Vehicle Inspection

- (0) No inspection
- (1) Vehicle fully repaired-no damage evident
- (2) Partial inspection (specify): _____
- (3) Complete inspection

*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67=0), ***

DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***

THE EXTERIOR VEHICLE, INTERIOR VEHICLE,
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

EXTERIOR VEHICLE FORM

1. Primary Sampling Unit Number

3. Vehicle Number

2. Case Number - Stratum

DSI-95-SP-Ø13

$$\phi \perp$$

VEHICLE IDENTIFICATION

VIN 2B7H B23T6DK X X X X X X Model Year 83

Vehicle Make (specify): DODGE

Vehicle Model (specify): Ram VAN

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
01	FULL FRONTAL	FULL FRONTAL	C6

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

[illegible]

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	<u>127.6</u>	inches	x 2.54	=	<u>324</u> cm
Overall Length	<u>196.9</u>	inches	x 2.54	=	<u>500</u> cm
Maximum Width	<u>Ø79.9</u>	inches	x 2.54	=	<u>203</u> cm
Curb Weight	<u>Ø3473</u>	pounds	x .4536	=	<u>1575</u> kg
Average Track	<u>N/A</u>	inches	x 2.54	=	<u>N/A</u> cm
Front Overhang	<u>Ø28.3</u>	inches	x 2.54	=	<u>Ø72</u> cm
Rear Overhang	<u>Ø40.9</u>	inches	x 2.54	=	<u>104</u> cm
Undeformed End Width	<u>Ø73.6</u>	inches	x 2.54	=	<u>187</u> cm
Engine Size: cyl./displ.	<u>5200</u>	cc	x .001	=	<u>5.2</u> L
	<u>317</u>	CID	x .0164	=	<u>5.2</u> L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE

3. Rotation physically restricted b. Tire deflated

RF	<u>1</u>
LF	<u>1</u>
RR	<u>3</u>
LR	<u>2</u>

RF	<u>1</u>
LF	<u>2</u>
RR	<u>1</u>
LR	<u>2</u>

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION:

☐ Manual ☒ Automatic

END ~~SHIFT~~ ≥ 10 CM

☒ Yes ☐ No

ORIGINAL SPECIFICATIONS

Wheelbase 32.4 cm

Overall Length .500 cm

Maximum Width $2\phi 3$ cm

Curb Weight 1575 kg

Average Track *N/A* cm

Front Overhang 72 cm

Rear Overhang 1.04 cm

Undeformed End Width 187 cm

Engine Size: cyl./displ. 5.7 L

WHEEL STEER ANGLES

**(For locked front wheels or
displaced rear axles only)**

RF ④ 2 1 0

LF (±) 2 1 0

RR ± 0

LR ± ○






Within ± 5 degrees

DRIVE WHEELS

☐ FWD ☒ RWD ☐ 4WD

Approximate
Cargo Weight UNK kg

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CODES FOR OBJECT CONTACTED

(99) Unknown event or object

[illegible]

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>Ø 1</u>	5. <u>Ø 1</u>	6. <u>1 2</u>	7. <u>F</u>	8. <u>D</u>	9. <u>E</u>	10. <u>W</u>	11. <u>Ø 7</u>

Second Highest Delta "V"

12. <u>Ø 2</u>	13. <u>5 4</u>	14. <u>Ø 9</u>	15. <u>L</u>	16. <u>P</u>	17. <u>L</u>	18. <u>W</u>	19. <u>Ø 1</u>
----------------	----------------	----------------	--------------	--------------	--------------	--------------	----------------

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. <u>L</u>	21. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	22. <u>±D</u>
<u>187</u>	<u>Ø Ø Ø</u>	<u>Ø Ø 5</u>	<u>Ø 2 2</u>	<u>Ø 8 5</u>	<u>Ø 9 7</u>	<u>1 2 3</u>	<u>⊕ - Ø 2 4</u>

Second Highest Delta "V"

23. <u>L</u>	24. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	25. <u>±D</u>
<u>-----</u>	<u>-----</u>	<u>-----</u>	<u>-----</u>	<u>-----</u>	<u>-----</u>	<u>-----</u>	<u>-----</u>

26. Undeformed End Width
(Coded when highest severity impact is an end plane impact.) 187
 _____ Code to the nearest centimeter
 (250) 250 centimeters or more
 (998) No highest severity end plane impact
 (999) Unknown

27. Direct Damage Width
(For highest severity impact) 14Ø
 _____ Code to the nearest centimeter
 (250) 250 centimeters or more
 (999) Unknown

28. Original Wheelbase 324
 _____ Code to the nearest centimeter
 (650) 650 centimeters or more
 (999) Unknown
127.6 inches X 2.54 = 324 centimeters

29. Original Average Track Width 999
 _____ Code to the nearest centimeter
 (185) 185 centimeters or more
 (999) Unknown
 _____ inches X 2.54 = _____ centimeters

FUEL SYSTEM

30. Are CDCs Documented
but Not Coded on The
Automated File?

- (0) No
(1) Yes

1

31. Researcher's Assessment of Vehicle
Disposition

- (0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

1

32. Is This A Multi-Stage Manufactured Vehicle
And/Or A Certified Altered Vehicle?

- (0) No post manufacturer modifications
(1) Yes - post manufacturer modifications
(specify): _____

0

(Include photograph of CERTIFICATION
PLACARD in case report)

- (9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence

- (0) No fire

2

Yes, fire occurred

- (1) Minor
(2) Major
(9) Unknown

34. Origin of Fire

- (0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention
system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify): _____

4

- (9) Unknown

35. Location of Fuel Tank-1 Filler Cap

2

36. Location of Fuel Tank-2 Filler Cap

0

- (0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on
left side plane
(3) Aft of center of the rear wheels (rear axle) on
right side plane
(4) Forward of center of the rear wheels (rear axle)
on left side plane
(5) Forward of center of the rear wheels (rear axle)
on right side plane
(6) Over the center of the rear wheels (rear axle)
on left side plane
(7) Over the center of the rear wheels (rear axle)
on right side plane
(8) Other (specify): _____
(9) Unknown

37. Type of Fuel Tank-1

1

38. Type of Fuel Tank-2

0

- (0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1

1

40. Location of Fuel Tank-2

0

- (0) No fuel tank
(1) Aft of center of the rear wheels (rear axle)
centered
(2) Aft of center of the rear wheels (rear axle) left
side
(3) Aft of center of the rear wheels (rear axle) right
side
(4) Forward of center of the rear wheels (rear axle)
centered
(5) Forward of center of the rear wheels (rear axle)
left side
(6) Forward of center of the rear wheels (rear axle)
right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

41. Damage to Fuel Tank-1

9

42. Damage to Fuel Tank-2

0

- (0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): _____
(9) Unknown

43. Leakage Location of Fuel System-1

9

44. Leakage Location of Fuel System-2

φ

(0) No fuel tank

(1) No fuel leakage

Primary Area Of Leakage

(2) Tank

(3) Filler neck

(4) Cap

(5) Lines/pump/filter

(6) Vent/emission recovery

(8) Other (specify): _____

(9) Unknown

45. Fuel Type-1

φ 1

46. Fuel Type-2

φ φ*Single Fuel Type*

(00) No fuel tank

(01) Gasoline

(02) Diesel

(03) CNG (Compressed Natural Gas)

(04) LPG (Liquid Petroleum Gas) also known as Propane

(05) LNG (Liquid Natural Gas)

(06) Methanol (M100 or M85)

(07) Ethanol (E100 or E85)

(08) Other (Hydrogen or others) (specify): _____

Electric Powered or Electric/Solar Powered Vehicles

(10) Lead Acid Battery

(11) Nickel-Iron Battery

(12) Nickel-Cadmium Battery

(13) Sodium Metal Chloride Battery

(14) Sodium Sulfur Battery

(18) Other (Specify): _____

(98) Other Hybrid (specify): _____

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks?

φ

(0) No (one or two tanks only)

Yes - More Than Two Tanks(1) Yes -- no damage to any tank or filler cap and no fuel system leakage(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location): _____(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):

Type of tank _____

Tank location _____

Filler cap location _____

Tank damage _____

Location of leakage _____

Type of fuel _____

(9) Unknown if more than two tanks

COMMENTS

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED ***

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.



INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DS1-95-SP-0133. Vehicle Number 01

INTEGRITY

4. Passenger Compartment Integrity 98

(00) No integrity loss

Yes, Integrity Was Lost Through

(01) Windshield

(02) Door (side)

(03) Door/hatch (back door)

(04) Roof

(05) Roof glass

(06) Side window

(07) Rear window (backlight)

(08) Roof and roof glass

(09) Windshield and door (side)

(10) Windshield and roof

(11) Side and rear window (side window and backlight)

(12) Windshield and side window

(13) Door and side window

(98) Other combination of above (specify):

01, 02, 06, 07

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 2 7. LR 0 8. RR 1 9. TGH 1

(0) No door/gate/hatch

(1) Door/gate/hatch remained closed and operational

(2) Door/gate/hatch came open during collision

(3) Door/gate/hatch jammed shut

(8) Other (specify): _____

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch
Opening in Collision. If IV05-IV09 = 2, Then code 010. LF 0 11. RF 9 12. LR 0 13. RR 0 14. TGH 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

(1) Door operational (no damage)

(2) Latch/striker failure due to damage

(3) Hinge failure due to damage

(4) Door structure failure due to damage

(5) Door support (i.e., pillar, sill, roof side rail,
etc.) failure due to damage

(6) Latch/striker and hinge failure due to damage

(8) Other failure (specify): _____

(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 9 17. RF 9 18. LR 9 19. RR 920. BL 9 21. Roof 0 22. Other 9

(0) No glazing

(1) AS-1 — Laminated

(2) AS-2 — Tempered

(3) AS-3 — Tempered-tinted (original)

(4) AS-2 — Tempered-with after market tint

(5) AS-3 — Tempered-tinted (with additional after market tint)

(6) AS-14 — Glass/Plastic

(7) Glazing removed prior to accident

(8) Other (specify): _____

(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR 1 27. RR 128. BL 1 29. Roof 0 30. Other 2

(0) No glazing

(1) Fixed

(2) Closed

(3) Partially opened

(4) Fully opened

(7) Glazing removed prior to accident

(9) Unknown

Glazing Damage from Impact Forces

31. WS 9 32. LF 9 33. RF 9 34. LR 9 35. RR 936. BL 9 37. Roof 0 38. Other 9

(0) No glazing

(1) No glazing damage from impact forces

(2) Glazing in place and cracked from impact forces

(3) Glazing in place and holed from impact forces

(4) Glazing out-of-place (cracked or not) and not holed from impact
forces

(5) Glazing out-of-place and holed from impact forces

(6) Glazing disintegrated from impact forces

(7) Glazing removed prior to accident

(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 9 40. LF 9 41. RF 9 42. LR 9 43. RR 944. BL 9 45. Roof 0 46. Other 9

(0) No glazing

(1) No occupant contact to glazing

(2) Glazing contacted by occupant but no glazing damage

(3) Glazing in place and cracked by occupant contact

(4) Glazing in place and holed by occupant contact

(5) Glazing out-of-place (cracked or not) by occupant
contact and not holed by occupant contact(6) Glazing out-of-place by occupant contact and holed by occupant
contact



(7) Glazing removed prior to accident

(8) Glazing disintegrated by occupant contact

(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters)			INTRUSION	DOMINANT CRUSH DIRECTION
		COMPARISON VALUE	INTRUDED VALUE	=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		
		—		=		

CATASTROPHIC FIRE

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

INTRUDING COMPONENT

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. _____	48. _____	49. _____	50. _____
2nd	51. _____	52. _____	53. _____	54. _____
3rd	55. _____	56. _____	57. _____	58. _____
4th	59. _____	60. _____	61. _____	62. _____
5th	63. _____	64. _____	65. _____	66. _____
6th	67. _____	68. _____	69. _____	70. _____
7th	71. _____	72. _____	73. _____	74. _____
8th	75. _____	76. _____	77. _____	78. _____
9th	79. _____	80. _____	81. _____	82. _____
10th	83. _____	84. _____	85. _____	86. _____

Interior Components

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): _____

Exterior Components

- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

LOCATION OF INTRUSION

Front Seat

- (11) Left
- (12) Middle
- (13) Right

Fourth Seat

- (41) Left
- (42) Middle
- (43) Right

Second Seat

- (21) Left
- (22) Middle
- (23) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) _____

(99) Unknown

Third Seat

- (31) Left
- (32) Middle
- (33) Right

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE

—

DAMAGE VALUE

=

DEFORMATION

UNK

—

UNK

=

UNK

Ø

—

Ø

=

Ø

—

=

—

=

STEERING COLUMN

INSTRUMENT PANEL

87. Steering Column Type

- (1) Fixed column
 (2) Tilt column
 (3) Telescoping column
 (4) Tilt and telescoping column
 (8) Other column type (specify):
 (9) Unknown

1

88. Tilt Steering Column Adjustment

- (0) No tilt steering column
 (1) Full up
 (2) Between full up and center
 (3) Center
 (4) Between center and full down
 (5) Full down
 (9) Unknown

0

89. Telescoping Steering Column Adjustment

- (0) No telescoping steering column
 (1) Full back
 (2) Between full back and midpoint
 (3) Midpoint
 (4) Between midpoint and full forward
 (5) Full forward
 (9) Unknown

0

90. Steering Rim/Spoke Deformation

- Code actual measured deformation to the nearest centimeter
 (00) No steering rim deformation
 (01-14) Actual measured value in centimeters
 (15) 15 centimeters or more
 (98) Observed deformation cannot be measured
 (99) Unknown

99

91. Location of Steering Rim/Spoke Deformation

- (00) No steering rim deformation


Quarter Sections

- (01) Section A
 (02) Section B
 (03) Section C
 (04) Section D



Half Sections

- (05) Upper half of rim/spoke
 (06) Lower half of rim/spoke
 (07) Left half of rim/spoke
 (08) Right half of rim/spoke



- (09) Complete steering wheel collapse
 (10) Undetermined location
 (99) Unknown

99

92. Odometer Reading

999,000

- _____ kilometers
 Code to the nearest 1,000 kilometers
 (000) No odometer
 (001) Less than 1,500 kilometers
 (500) 499,500 kilometers or more
 (999) Unknown

_____ miles X 1.6093 = _____ kilometers

Source: _____

93. Instrument Panel Damage from Occupant Contact?

- (0) No
 (1) Yes
 (9) Unknown

9

94. Type of Knee Bolster Covering

- (0) No knee bolster
 (1) Padded
 (2) Rigid plastic
 (8) Other (specify):
 (9) Unknown

0

95. Knee Bolsters Deformed from Occupant Contact?

- (0) No knee bolster
 (1) No deformation
 (2) Yes - deformation
 (9) Unknown

0

96. Did Glove Compartment Door Open During Collision(s)?

- (0) No glove compartment door
 (1) No - door did not open
 (2) Yes - door opened
 (9) Unknown

9

97. Adaptive (Assistive) Driving Equipment


- (0) No adaptive driving equipment
 (1) Adaptive driving equipment installed (Check all that apply.)
 [] Hand controls for braking/acceleration
 [] Steering control devices (attached to OEM steering wheel)
 [] Steering knob attached to steering wheel
 [] Low effort power steering (unit or device)
 [] Replacement steering wheel (i.e., reduced diameter)
 [] Joy-stick steering controls
 [] Wheelchair tie-downs
 [] Modification to seat belts (specify):
 [] Additional or relocated switches (specify):
 [] Raised roof
 [] Wall-mounted head rest (used behind wheelchair)
 [] Other adaptive device (specify):

0

(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).
 Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.
 Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A					
B					
C					
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

FRONT

- (001) Windshield
 (002) Mirror
 (003) Sunvisor
 (004) Steering wheel rim
 (005) Steering wheel hub/spoke
 (006) Steering wheel (combination of codes 004 and 005)
 (007) Steering column, transmission selector lever, other attachment
 (008) Cellular telephone or CB radio
 (009) Add on equipment (e.g., tape deck, air conditioner)
 (010) Left instrument panel and below
 (011) Center instrument panel and below
 (012) Right instrument panel and below
 (013) Glove compartment door
 (014) Knee bolster
 (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
 (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
 (017) Windshield reinforced by exterior object, (specify):
 (019) Other front object (specify):

CODES FOR INTERIOR COMPONENTS

LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
 (052) Left side hardware or armrest
 (053) Left A (A1/A2)-pillar
 (054) Left B-pillar
 (055) Other left pillar (specify):
 (056) Left side window glass
 (057) Left side window frame
 (058) Left side window sill
 (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
 (060) Other left side object (specify):

RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests
 (102) Right side hardware or armrest
 (103) Right A (A1/A2)-pillar
 (104) Right B-pillar
 (105) Other right pillar (specify):
 (106) Right side window glass
 (107) Right side window frame
 (108) Right side window sill
 (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
 (110) Other right side object (specify):

INTERIOR

- (151) Seat, back support
 (152) Belt restraint webbing/buckle
 (153) Belt restraint B-pillar or door frame attachment point
 (154) Other restraint system component (specify):
 (155) Head restraint system
 (160) Other occupants (specify):
 (161) Interior loose objects
 (162) Child safety seat (specify):
 (163) Other interior object (specify):

AIR BAG

- (170) Air bag-driver side
 (175) Air bag compartment cover-driver side
 (180) Air bag-passenger side
 (185) Air bag compartment cover-passenger side
 (190) Other air bag (specify)
 (195) Other air bag compartment cover (specify)

ROOF

- (201) Front header
 (202) Rear header
 (203) Roof left side rail
 (204) Roof right side rail
 (205) Roof or convertible top

FLOOR

- (251) Floor (including toe pan)
 (252) Floor or console mounted transmission lever, including console
 (253) Parking brake handle
 (254) Foot controls including parking brake

REAR

- (301) Backlight (rear window)
 (302) Backlight storage rack, door, etc.
 (303) Other rear object (specify):

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
 (402) Steering control devices (attached to OEM steering wheel)
 (403) Steering knob attached to steering wheel
 (405) Replacement steering wheel (i.e., reduced diameter)
 (406) Joy stick steering controls
 (407) Wheelchair tie-downs
 (408) Modification to seat belts, (specify):
 (409) Additional or relocated switches, (specify):
 (410) Raised roof
 (411) Wall mounted head rest (used behind wheel chair)
 (412) Other adaptive device (specify):

CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain
 (2) Probable
 (3) Possible
 (9) Unknown

MANUAL RESTRAINTS

NOTES Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			
SECOND	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify): _____

(9) Unknown

Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify): _____

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify): _____

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify): _____
- (99) Unknown if belt used

Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
- (8) Other improper use of manual belt system (specify): _____

(9) Unknown

Shoulder Belt Upper Anchorage Adjustment

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
FIRST	Availability/Function			
	Deployment	⓪	⓪	⓪
	Failure			

Air Bag System Availability/Function (0) Not equipped/not available (1) Air bag <i>Non-functional</i> (2) Air bag disconnected (specify): _____ (3) Air bag not reinstalled (9) Unknown	Frontal Air Bag System Deployment (This Occupant Position) (0) Not equipped/not available (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, accident sequence undetermined (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown	Air Bag(s) Deployment, <u>Other</u> Than First Seat Frontal (This Occupant Position) (0) Not equipped with an "other" air bag (1) Deployed during accident (as a result of impact) (2) Deployed inadvertently just prior to accident (3) Deployed, details unknown (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical) (5) Unknown if deployed (7) Nondeployed (9) Unknown
Are There Indications of Air Bag System Failure? (This Occupant Position) (0) Not equipped/not available (1) No (2) Yes (specify): _____ (9) Unknown		

AUTOMATIC BELTS

		Left	Right
FIRST	Availability/Function		
	Use	⓪	⓪
	Type		
	Proper Use		
	Failure Modes		

Automatic (Passive) Belt System Availability/Function (0) Not equipped/not available (1) 2 point automatic belts (2) 3 point automatic belts (3) Automatic belts - type unknown <i>Non-functional</i> (4) Automatic belts destroyed or rendered inoperative (9) Unknown	Proper Use of Automatic (Passive) Belt System (0) Not equipped/not available/not used (1) Automatic belt used properly (2) Automatic belt used properly with child safety seat <i>Automatic Belt Used Improperly</i> (3) Automatic shoulder belt worn under arm (4) Automatic shoulder belt worn behind back (5) Automatic belt worn around more than one person (6) Lap portion of automatic belt worn on abdomen (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____ (8) Other improper use of automatic belt system (specify): _____ (9) Unknown	Automatic (Passive) Belt Failure Modes During Accident (0) Not equipped/not available/not in use (1) No automatic belt failure(s) (2) Torn webbing (stretched webbing not included) (3) Broken buckle or latchplate (4) Upper anchorage separated (5) Other anchorage separated (specify): _____ (6) Broken retractor (7) Combination of above (specify): _____ (8) Other automatic belt failure (specify): _____ (9) Unknown
Automatic (Passive) Belt System Use (0) Not equipped/not available/destroyed or rendered inoperative (1) Automatic belt in use (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (3) Automatic belt use unknown (9) Unknown		
Automatic (Passive) Belt System Type (0) Not equipped/not available (1) Non-motorized system (2) Motorized system (9) Unknown		

FIRST SEAT FRONTAL AIR BAGS

NOTES: Encode the applicable data *for the driver and first seat passenger* in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?	/	/
Flaps open at tear points?	/	/
Flaps damaged?	/	/
Air bag damaged?	0	0
Source of air bag damage	/	/
Air bag tethered?	/	/
Air bag have vent ports?	/	/
Other occupant contact air bag?	/	/
Occupant wearing eyewear?	/	/

Type of Air Bag

- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?

- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was There Damage To The Air Bag?

- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify):

- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Source of Air Bag Damage

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):
- (03) Object carried by occupant, (specify):
- (04) Adaptive/assistive controls, (specify):
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):

- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Was The Air Bag Tethered?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps):
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Did The Air Bag Have Vent Ports?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was This Occupant Wearing Eye-wear?

- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
SECOND	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other
Specify: _____
- (9) Unknown

Seat Type (this Occupant Position)

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

Seat Performance (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown

Seat Orientation (this Occupant Position)




- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown

Seat Track Adjusted Position Prior To Impact

- (0) Occupant not seated or no seat
 - (1) Non-adjustable seat track
- Adjustable Seat Track**
- (2) Seat at forward most track position
 - (3) Seat between forward most and middle track positions
 - (4) Seat at middle track position
 - (5) Seat between middle and rear most track positions
 - (6) Seat at rear most track position
 - (9) Unknown

Seat Back Incline Prior and Post Impact

- (00) Occupant not seated or no seat
 - (01) Not adjustable
- Upright prior to impact**
- (11) Moved to completely rearward position
 - (12) Moved to rearward midrange position
 - (13) Moved to slightly rearward position
 - (14) Retained pre-impact position
 - (15) Moved to slightly forward position
 - (16) Moved to forward midrange position
 - (17) Moved to completely forward position
- Slightly reclined prior to impact**
- (21) Moved to completely rearward position
 - (22) Moved to rearward midrange position
 - (23) Retained pre-impact position
 - (24) Moved to upright position
 - (25) Moved to slightly forward position
 - (26) Moved to forward midrange position
 - (27) Moved to completely forward position
- Completely reclined prior to impact**
- (31) Retained pre-impact position
 - (32) Moved to rearward midrange position
 - (33) Moved to slightly rearward position
 - (34) Moved to upright position
 - (35) Moved to slightly forward position
 - (36) Moved to forward midrange position
 - (37) Moved to completely forward position
 - (99) Unknown



Coding diagrams for Seat Back Incline Position Prior and Post Impact

**DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)**

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify):

- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

- (00) No child safety seat
- Designed for Rear Facing for This Age/Weight
- (01) Rear facing
- (02) Forward facing
- (08) Other orientation (specify):
- (09) Unknown orientation

Designed for Forward Facing for This Age/Weight

- (11) Rear facing
- (12) Forward facing
- (18) Other orientation (specify):

- (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

- (21) Rear facing
- (22) Forward facing
- (28) Other orientation (specify):

- (29) Unknown orientation

- (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

- 5. Child Safety Seat Tether Usage
- Note: Options Below Are Used for Variables 3-5.
- (00) No child safety seat

Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used

- (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model
(Specify make/model and occupant number)

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No ☒ Yes ☐

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

Ejection Area

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

(7) Roof

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown**Ejection Medium**

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

(5) Integral structure

- (8) Other medium (specify):

(9) Unknown**Medium Status (Immediately Prior to Impact)**

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

ENTRAPMENT No ☐ Yes ☒

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DSI-95-SP-013

3. Vehicle Number

01

4. Occupant Number

01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age

59

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex

1

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height

999

Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight

999

Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role

1

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position

11

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify):

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify):

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify):

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify):

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify):

(99) Unknown

11. Occupant's Posture

9

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify):

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 9

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): _____
- (9) Unknown

17. Occupant Mobility 1

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 9

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 9

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4

- (0) None used
- (1) Police did not indicate belt use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Automatic belt
- (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1

- (0) No air bag available
- (1) Police did not indicate air bag availability/function
- (2) Deployed
- (3) Not deployed
- (4) Unknown if deployed
- (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☐ Not equipped/not available/destroyed or rendered inoperative
- ☐ Vehicle inspection
- ☐ Official injury data
- ☐ Driver/occupant interview
- ☐ Other (specify):

☒ Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Ø

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
- (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

31. Frontal Air Bag System Deployment Ø

(This Occupant Position)

- (0) Not equipped/not available
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

32. Other Than First Seat Frontal Air Bag Ø

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
- (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) Ø

- (0) Not equipped with an "other" air bag
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

34. Are There Indications of Air Bag System Failure? Ø

(This Occupant Position)

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):

(9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? ϕ

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag ϕ

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? ϕ

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify):

(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number $\phi\phi$

- (00) Not equipped/not available

Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact ϕ

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify):

(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact $\phi\phi\phi$

- (-000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes (specify):

(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? $\phi\phi$

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):

- (95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

44. Source of Air Bag Damage Ø Ø
 (00) Not equipped/not available
 (01) Not damaged
 (02) Object worn by occupant, (specify):

(03) Object carried by occupant, (specify):

(04) Adaptive/assistive controls, (specify):

- (05) Fire in vehicle
 (06) Thermal burns
 (07) Rescue or emergency efforts
 (08) Other damage source (specify):

- (95) Damaged, unknown source
 (96) Deployed, unknown if damaged
 (97) Not deployed
 (98) Unknown if deployed
 (99) Unknown

45. Was The Air Bag Tethered? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of tether straps):

- (3) Deployed, unknown if tethered
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

46. Did The Air Bag Have Vent Ports? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of vent ports):

- (3) Deployed, unknown if vent ports present
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

47. Was the Air Bag in this Occupant's Position
 Contacted by Another Occupant? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

- (3) Deployed, unknown if other occupant contact to
 air bag
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

48. Was This Occupant Wearing Eye-wear? Ø
 (0) Not equipped/not available
 (1) No
 (2) Eyeglasses/sunglasses
 (3) Contact lenses
 (4) Deployed, unknown if eyewear worn
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant
 at This Occupant Position 9

- (0) No head restraints
 (1) Integral—no damage
 (2) Integral—damaged during accident
 (3) Adjustable—no damage
 (4) Adjustable—damaged during accident
 (5) Add-on—no damage
 (6) Add-on—damaged during accident
 (8) Other (specify):

(9) Unknown

50. Seat Type (this Occupant Position) 99

- (00) Occupant not seated or no seat
 (01) Bucket
 (02) Bucket with folding back
 (03) Bench
 (04) Bench with separate back cushions
 (05) Bench with folding back(s)
 (06) Split bench with separate back cushions
 (07) Split bench with folding back(s)
 (08) Pedestal (i.e., column supported)
 (09) Box mounted seat (i.e., van type)
 (10) Other seat type (specify):

(99) Unknown

51. Seat Orientation (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) Forward facing seat
 (2) Rear facing seat
 (3) Side facing seat (inward)
 (4) Side facing seat (outward)
 (8) Other (specify):

(9) Unknown

52. Seat Track Adjusted Position Prior To Impact 9

- (0) Occupant not seated or no seat
 (1) Non-adjustable seat track

Adjustable Seat Track

- (2) Seat at forward most track position
 (3) Seat between forward most and middle track
 positions
 (4) Seat at middle track position
 (5) Seat between middle and rear most track
 positions
 (6) Seat at rear most track position
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 99

- (00) Occupant not seated or no seat
 (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
 (12) Moved to rearward midrange position
 (13) Moved to slightly rearward position
 (14) Retained pre-impact position
 (15) Moved to slightly forward position
 (16) Moved to forward midrange position
 (17) Moved to completely forward position




Slightly reclined prior to impact

- (21) Moved to completely rearward position
 (22) Moved to rearward midrange position
 (23) Retained pre-impact position
 (24) Moved to upright position
 (25) Moved to slightly forward position
 (26) Moved to forward midrange position
 (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
 (32) Moved to rearward midrange position
 (33) Moved to slightly rearward position
 (34) Moved to upright position
 (35) Moved to slightly forward position
 (36) Moved to forward midrange position
 (37) Moved to completely forward position

- (99) Unknown

54. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) No seat performance failure(s)
 (2) Seat adjusters failed
 (3) Seat back folding locks or "seat back" failed
 (specify): _____
 (4) Seat track/anchors failed
 (5) Deformed by impact of occupant
 (6) Deformed by passenger compartment intrusion,
 (specify): _____
 (7) Combination of above (specify): _____
 (8) Other (specify): _____
 (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES61. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):

- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

64. Hospital Stay 9 9

(00) Not Hospitalized

Code the number of days (up through 60) that the occupant stayed in hospital.

(61) 61 days or more

(99) Unknown

65. Working Days Lost 9 9

Code the number of days (up through 60) that the occupant lost from work due to the accident

(00) No working days lost

(61) 61 days or more

(62) Fatally injured

(97) Not working prior to accident

(99) Unknown

99. Case Occupant φ

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE**VARIABLES 66-74****TO BE CODED BY THE ZONE CENTER**

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****TRAUMA DATA**

66. Time to Death

_____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

0 0

67. 1st Medically Reported Cause of Death

0 0

68. 2nd Medically Reported Cause of Death

0 0

69. 3rd Medically Reported Cause of Death

0 0

_____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____

(97) Other result (includes fatal ruled disease) (specify): _____

(99) Unknown _____

70. Number of Recorded Injuries for This Occupant

_____ Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

0 2

71. Glasgow Coma Scale (GCS) Score (at Medical Facility)

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

1 5

72. Was the Occupant Given Blood?

- (1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given

973. Arterial Blood Gases (ABG) - HCO₃

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

0 1**BELT USE DETERMINATION**

74. Primary Source of Belt Use Determination

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

9



OCCUPANT INJURY FORM

BEST AVAILABLE

Form Approved

O.M.B. No. 2127-00

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

3. Vehicle Number

01

2. Case Number - Stratum

DSI-95-SP-013

4. Occupant Number

01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

Source of Injury Data	Body Region	A.I.S. - 90		Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Occupant Direct/ Indirect Injury	Area Intrusion Number	ICD-9	
		Type of Anatomic Structure	Specific Anatomic Structure									
1st	5. <u>2</u>	6. <u>1</u>	7. <u>6</u>	8. <u>08</u>	9. <u>02</u>	10. <u>3</u>	11. <u>0</u>	12. <u>697</u>	13. <u>9</u>	14. <u>7</u>	15. <u>00</u>	<u>950.5</u>
2nd	16. <u>2</u>	17. <u>9</u>	18. <u>1</u>	19. <u>92</u>	20. <u>02</u>	21. <u>3</u>	22. <u>0</u>	23. <u>601</u>	24. <u>1</u>	25. <u>3</u>	26. <u>00</u>	<u>986</u>
3rd	27. _____	28. _____	29. _____	30. _____	31. _____	32. _____	33. _____	34. _____	35. _____	36. _____	37. _____	_____
4th	38. _____	39. _____	40. _____	41. _____	42. _____	43. _____	44. _____	45. _____	46. _____	47. _____	48. _____	_____
5th	49. _____	50. _____	51. _____	52. _____	53. _____	54. _____	55. _____	56. _____	57. _____	58. _____	59. _____	_____
6th	60. _____	61. _____	62. _____	63. _____	64. _____	65. _____	66. _____	67. _____	68. _____	69. _____	70. _____	_____
7th	71. _____	72. _____	73. _____	74. _____	75. _____	76. _____	77. _____	78. _____	79. _____	80. _____	81. _____	_____
8th	82. _____	83. _____	84. _____	85. _____	86. _____	87. _____	88. _____	89. _____	90. _____	91. _____	92. _____	_____
9th	93. _____	94. _____	95. _____	96. _____	97. _____	98. _____	99. _____	100. _____	101. _____	102. _____	103. _____	_____
10th	104. _____	105. _____	106. _____	107. _____	108. _____	109. _____	110. _____	111. _____	112. _____	113. _____	114. _____	_____

OCCUPANT INJURY CLASSIFICATION

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive	(1) Right
(2) Face		two-digit numbers beginning with 02.	(2) Left
(3) Neck	<u>Vessels, Nerves, Organs.</u>		(3) Bilateral
(4) Thorax	<u>Bones, Joints</u> are assigned consecutive two digit numbers beginning with 02.		(4) Central
(5) Abdomen		To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.	(5) Anterior
(6) Spine			(6) Posterior
(7) Upper Extremity	The exceptions to this rule apply to:		(7) Superior
(8) Lower Extremity			(8) Inferior
(9) Unspecified			(9) Unknown
			(0) Whole region
Type of Anatomic Structure	<u>Whole Area</u>	Abbreviated Injury Scale	
(1) Whole Area	(02) Skin - Abrasion	(1) Minor Injury	
(2) Vessels	(04) Skin - Contusion	(2) Moderate Injury	
(3) Nerves	(06) Skin - Laceration	(3) Serious Injury	
(4) Organs (includes Muscles/ligaments)	(08) Skin - Avulsion	(4) Severe Injury	
(5) Skeletal (includes joints)	(10) Amputation	(5) Critical Injury	
(6) Head - LOC	(20) Burn	(6) Maximum (untreatable)	
(9) Skin	(30) Crush	(7) Injured, unknown severity	
	(40) Degloving		
	(50) Injury - NFS		
	(90) Trauma, other than mechanical		
	<u>Head - LOC</u>		
	(02) Length of LOC		
	(04) Level of		
	(06) Consciousness		
	(08) Concussion		
	(10) Concussion		
	<u>Spine</u>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		

SOURCE OF INJURY DATA

INJURY SOURCE

DIRECT/INDIRECT INJURY

CONFIDENCE LEVEL

OFFICIAL RECORDS

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

INJURY SOURCES

FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): _____
- (019) Other front object (specify): _____

LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): _____
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): _____

RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): _____
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): _____

INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): _____
- (155) Head restraint system
- (160) Other occupants (specify): _____
- (161) Interior loose objects
- (162) Child safety seat (specify): _____
- (163) Other interior object (specify): _____

AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify) _____
- (195) Other air bag compartment cover (specify) _____

ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

FLOOR

- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): _____
- (409) Additional or relocated switches, (specify): _____

- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): _____
- (454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): _____
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): _____
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): _____
- (514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT



- (551) Ground
- (598) Other vehicle or object (specify): _____
- (599) Unknown vehicle or object

NONCONTACT INJURY

- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): _____
- (604) Air bag exhaust gases
- (697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Blood Alcohol Level
(mg/dl)

BAL = ____

Glasgow Coma
Scale Score

GCSS = ____

Units of Blood
Given

Units = ____



Arterial Blood Gases

pH = ____

PO₂ = ____


PCO₂ ____

HCO₃ ____



OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum

3. Vehicle Number

4. Occupant Number

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height

Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight

Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify): _____

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify): _____

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify): _____

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify): _____

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify): _____

(99) Unknown

11. Occupant's Posture

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify): _____

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment φ

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): _____
- (9) Unknown

17. Occupant Mobility 2

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18 Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19 Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

(02) Shoulder belt

(03) Lap belt

(04) Lap and shoulder belt

(05) Belt used—type unknown

(08) Other belt used (specify):

(12) Shoulder belt used with child safety seat

(13) Lap belt used with child safety seat

(14) Lap and shoulder belt used with child safety seat

(15) Belt used with child safety seat—type unknown

(18) Other belt used with child safety seat (specify):

(99) Unknown if belt used

20 Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21 Manual (Active) Belt Failure Modes During Accident 9

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

(6) Broken retractor

(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22 Shoulder Belt Upper Anchorage Adjustment 9

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23 Automatic (Passive) Belt System Availability/Function Ø

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24 Automatic (Passive) Belt System Use Ø

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25 Automatic (Passive) Belt System Type Ø

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26 Proper Use of Automatic (Passive) Belt System Ø

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27 Automatic (Passive) Belt Failure Modes During Accident Ø

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

(6) Broken retractor

(7) Combination of above (specify):

(8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 4

- (0) None used
- (1) Police did not indicate belt use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Automatic belt
- (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1

- (0) No air bag available
- (1) Police did not indicate air bag availability/function
- (2) Deployed
- (3) Not deployed
- (4) Unknown if deployed
- (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☐ Not equipped/not available/destroyed or rendered inoperative
- ☐ Vehicle inspection
- ☐ Official injury data
- ☐ Driver/occupant interview
- ☐ Other (specify):

☒ Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System Ø

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
- (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

31. Frontal Air Bag System Deployment Ø

(This Occupant Position)

- (0) Not equipped/not available
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

32. Other Than First Seat Frontal Air Bag Ø

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
- (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) Ø

- (0) Not equipped with an "other" air bag
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

34. Are There Indications of Air Bag System Failure? Ø

(This Occupant Position)

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):

(9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? Ø

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag Ø

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? Ø

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number Ø Ø

- (00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact Ø

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + - Ø Ø Ø

- (-000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? Ø

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? Ø

- (0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? Ø Ø

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____

- (95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

44. Source of Air Bag Damage Ø Ø
 (00) Not equipped/not available
 (01) Not damaged
 (02) Object worn by occupant, (specify):

 (03) Object carried by occupant, (specify):

 (04) Adaptive/assistive controls, (specify):

 (05) Fire in vehicle
 (06) Thermal burns
 (07) Rescue or emergency efforts
 (88) Other damage source (specify):

 (95) Damaged, unknown source
 (96) Deployed, unknown if damaged
 (97) Not deployed
 (98) Unknown if deployed
 (99) Unknown
45. Was The Air Bag Tethered? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of tether straps):

 (3) Deployed, unknown if tethered
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
46. Did The Air Bag Have Vent Ports? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of vent ports):

 (3) Deployed, unknown if vent ports present
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

 (3) Deployed, unknown if other occupant contact to air bag
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
48. Was This Occupant Wearing Eye-wear? Ø
 (0) Not equipped/not available
 (1) No
 (2) Eyeglasses/sunglasses
 (3) Contact lenses
 (4) Deployed, unknown if eyewear worn
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position 9
 (0) No head restraints
 (1) Integral—no damage
 (2) Integral—damaged during accident
 (3) Adjustable—no damage
 (4) Adjustable—damaged during accident
 (5) Add-on—no damage
 (6) Add-on—damaged during accident
 (8) Other (specify):

 (9) Unknown
50. Seat Type (this Occupant Position) 9 9
 (00) Occupant not seated or no seat
 (01) Bucket
 (02) Bucket with folding back
 (03) Bench
 (04) Bench with separate back cushions
 (05) Bench with folding back(s)
 (06) Split bench with separate back cushions
 (07) Split bench with folding back(s)
 (08) Pedestal (i.e., column supported)
 (09) Box mounted seat (i.e., van type)
 (10) Other seat type (specify):

 (99) Unknown
51. Seat Orientation (this Occupant Position) 1
 (0) Occupant not seated or no seat
 (1) Forward facing seat
 (2) Rear facing seat
 (3) Side facing seat (inward)
 (4) Side facing seat (outward)
 (8) Other (specify):

 (9) Unknown
52. Seat Track Adjusted Position Prior To Impact 9
 (0) Occupant not seated or no seat
 (1) Non-adjustable seat track
 Adjustable Seat Track
 (2) Seat at forward most track position
 (3) Seat between forward most and middle track positions
 (4) Seat at middle track position
 (5) Seat between middle and rear most track positions
 (6) Seat at rear most track position
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 99

(00) Occupant not seated or no seat

(01) Not adjustable

Upright prior to impact

(11) Moved to completely rearward position

(12) Moved to rearward midrange position

(13) Moved to slightly rearward position

(14) Retained pre-impact position

(15) Moved to slightly forward position

(16) Moved to forward midrange position

(17) Moved to completely forward position

Slightly reclined prior to impact

(21) Moved to completely rearward position

(22) Moved to rearward midrange position

(23) Retained pre-impact position

(24) Moved to upright position

(25) Moved to slightly forward position

(26) Moved to forward midrange position

(27) Moved to completely forward position

Completely reclined prior to impact

(31) Retained pre-impact position

(32) Moved to rearward midrange position

(33) Moved to slightly rearward position




(34) Moved to upright position

(35) Moved to slightly forward position

(36) Moved to forward midrange position

(37) Moved to completely forward position

(99) Unknown

54. Seat Performance (this Occupant Position) 9

(0) Occupant not seated or no seat

(1) No seat performance failure(s)

(2) Seat adjusters failed

(3) Seat back folding locks or "seat back" failed
(specify): _____

(4) Seat track/anchors failed

(5) Deformed by impact of occupant

(6) Deformed by passenger compartment intrusion,
(specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES61. Injury Severity (Police Rating) 4

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 1

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):
- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):
- (9) Unknown

64. Hospital Stay 99

- (00) Not Hospitalized
- Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 62

- Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant φ

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE**VARIABLES 66-74****TO BE CODED BY THE ZONE CENTER**

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****TRAUMA DATA**

66. Time to Death

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

9 9

67. 1st Medically Reported Cause of Death

9 9

68. 2nd Medically Reported Cause of Death

9 9

69. 3rd Medically Reported Cause of Death

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):

9 9

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

70. Number of Recorded Injuries for This Occupant

Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

0 7

71. Glasgow Coma Scale (GCS) Score (at Medical Facility)

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

9 7

72. Was the Occupant Given Blood?

- (1) No - blood not given
(2) Yes - blood given

(specify units):

- (9) Unknown if blood given

973. Arterial Blood Gases (ABG) - HCO₃

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

9 7**BELT USE DETERMINATION**

74. Primary Source of Belt Use Determination

- (0) Not equipped/not available/destroyed or rendered inoperative

- (1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):
(9) Unknown if belt used

9



OCCUPANT INJURY FORM

BEST AVAILABLE

Form Approved
O.M.B. No. 2127-00NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

3. Vehicle Number

2. Case Number - Stratum

4. Occupant Number

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

Source of Injury Data	Body Region	A.I.S. - 90			A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Occupant Direct/ Indirect Injury	Area Intrusion Number	ICD-9
		Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury							
1st	5. 2	6. 8	7. 9	8. 20	9. 12	10. 2	11. 3	12. 601	13. 1	14. 3	15. 00 948.1
2nd	16. 2	17. 5	18. 9	19. 08	20. 00	21. 1	22. 1	23. 697	24. 9	25. 7	26. 00 877.4
3rd	27. 2	28. 8	29. 5	30. 18	31. 00	32. 3	33. 1	34. 012	35. 2	36. 2	37. 99 820.8
4th	38. 2	39. 8	40. 5	41. 34	42. 04	43. 3	44. 2	45. 251	46. 2	47. 1	48. 99 823.8
5th	49. 2	50. 8	51. 5	52. 16	53. 05	54. 3	55. 2	56. 251	57. 2	58. 1	59. 99 823.8
6th	60. 2	61. 4	62. 4	63. 10	64. 02	65. 3	66. 4	67. 697	68. 9	69. 7	70. 00 861.0
7th	71. 2	72. 9	73. 1	74. 92	75. 04	76. 4 ³	77. 0	78. 601	79. 1	80. 3	81. 00 986
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____

OCCUPANT INJURY CLASSIFICATION

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive two-digit numbers beginning with 02.	(1) Right
(2) Face			(2) Left
(3) Neck	<u>Vessels, Nerves, Organs.</u>		(3) Bilateral
(4) Thorax	<u>Bones, Joints</u> are assigned consecutive two digit numbers beginning with 02.		(4) Central
(5) Abdomen		To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.	(5) Anterior
(6) Spine			(6) Posterior
(7) Upper Extremity	The exceptions to this rule apply to:		(7) Superior
(8) Lower Extremity			(8) Inferior
(9) Unspecified			(9) Unknown
			(0) Whole region
Type of Anatomic Structure	<u>Whole Area</u>	Abbreviated Injury Scale	
(1) Whole Area	(02) Skin - Abrasion	(1) Minor Injury	
(2) Vessels	(04) Skin - Contusion	(2) Moderate Injury	
(3) Nerves	(06) Skin - Laceration	(3) Serious Injury	
(4) Organs (includes Muscles/ligaments)	(08) Skin - Avulsion	(4) Severe Injury	
(5) Skeletal (includes joints)	(10) Amputation	(5) Critical Injury	
(6) Head - LOC	(20) Burn	(6) Maximum (untreatable)	
(9) Skin	(30) Crush	(7) Injured, unknown severity	
	(40) Degloving		
	(50) Injury - NFS		
	(90) Trauma, other than mechanical		
	<u>Head - LOC</u>		
	(02) Length of LOC		
	(04) Level		
	(06) of		
	(08) Consciousness		
	(10) Concussion		
	<u>Spine</u>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		

SOURCE OF INJURY DATA	INJURY SOURCE CONFIDENCE LEVEL	DIRECT/INDIRECT INJURY
<u>OFFICIAL RECORDS</u> (1) Autopsy records with or without hospital/medical records (2) Hospital/medical records other than emergency room (e.g., discharge summary) (3) Emergency room records only (including associated X-rays or other lab reports) (4) Private physician, walk-in or emergency clinic <u>UNOFFICIAL RECORDS</u> (5) Lay coroner report (6) E.M.S. personnel (7) Interviewee (8) Other source (specify): _____ (9) Police	(1) Certain (2) Probable (3) Possible (9) Unknown	(1) Direct contact injury (2) Indirect contact injury (3) Noncontact injury (7) Injured, unknown source

INJURY SOURCES

FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): _____

- (019) Other front object (specify): _____

LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): _____
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): _____

RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): _____
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): _____

INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): _____
- (155) Head restraint system
- (160) Other occupants (specify): _____
- (161) Interior loose objects
- (162) Child safety seat (specify): _____
- (163) Other interior object (specify): _____

AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify): _____
- (195) Other air bag compartment cover (specify): _____

ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

FLOOR

- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): _____
- (409) Additional or relocated switches, (specify): _____
- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): _____
- (454) Unknown exterior objects

EXTERIOR of OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): _____
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): _____
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): _____
- (514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT


- (551) Ground
- (598) Other vehicle or object (specify): _____
- (599) Unknown vehicle or object

NONCONTACT INJURY


- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): _____
- (604) Air bag exhaust gases
- (697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



← BILATERAL LOWER
EXTREMITY THIRD DEGREE
BURNS (ABOUT 10%) →



RIGHT BUTTOCK
TISSUE AVULSION

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Blood Alcohol Level
(mg/dl)

BAL = ___

Glasgow Coma
Scale Score

GCSS = ___

Units of Blood
Given

Units = ___



Arterial Blood Gases

pH = ___

PO₂ = ___


PCO₂ = ___

HCO₃ = ___



OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DS1-95-SP-013

3. Vehicle Number

01

4. Occupant Number

03

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height

Code actual height to the nearest
centimeter.

(999) Unknown

____ inches X 2.54 = ____ centimeters

8. Occupant's Weight

Code actual weight to the nearest
kilogram.

(999) Unknown

____ pounds X .4536 = ____ kilograms

9. Occupant's Role

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify):

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify):

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify):

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify):

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify):

(99) Unknown

11. Occupant's Posture

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify):

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 2

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): FIRE

(9) Unknown

17. Occupant Mobility Ø

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 9
- (0) None available
 - (1) Belt removed/destroyed
 - (2) Shoulder belt
 - (3) Lap belt
 - (4) Lap and shoulder belt
 - (5) Belt available—type unknown
- Integral Belt Partially Destroyed*
- (6) Shoulder belt (lap belt destroyed/removed)
 - (7) Lap belt (shoulder belt destroyed/removed)
 - (8) Other belt (specify): _____
 - (9) Unknown
19. Manual (Active) Belt System Use 9 9
- (00) None used, not available, or belt removed/destroyed
 - (01) Inoperative (specify): _____
 - (02) Shoulder belt
 - (03) Lap belt
 - (04) Lap and shoulder belt
 - (05) Belt used—type unknown
 - (08) Other belt used (specify): _____
 - (12) Shoulder belt used with child safety seat
 - (13) Lap belt used with child safety seat
 - (14) Lap and shoulder belt used with child safety seat
 - (15) Belt used with child safety seat—type unknown
 - (18) Other belt used with child safety seat (specify): _____
 - (99) Unknown if belt used
20. Proper Use of Manual (Active) Belts 9
- (0) None used or not available
 - (1) Belt used properly
 - (2) Belt used properly with child safety seat
- Belt Used Improperly*
- (3) Shoulder belt worn under arm
 - (4) Shoulder belt worn behind back or seat
 - (5) Belt worn around more than one person
 - (6) Lap belt worn on abdomen
 - (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____
 - (8) Other improper use of manual belt system (specify): _____
 - (9) Unknown
21. Manual (Active) Belt Failure Modes During Accident 9
- (0) No manual belt used or not available
 - (1) No manual belt failure(s)
 - (2) Torn webbing (stretched webbing not included)
 - (3) Broken buckle or latchplate
 - (4) Upper anchorage separated
 - (5) Other anchorage separated (specify): _____
 - (6) Broken retractor
 - (7) Combination of above (specify): _____
 - (8) Other manual belt failure (specify): _____
 - (9) Unknown
22. Shoulder Belt Upper Anchorage Adjustment 9
- (0) No shoulder belt
 - (1) No upper anchorage adjustment for shoulder belt
- Adjustable shoulder Belt Upper Anchorage*
- (2) In full up position
 - (3) In mid position
 - (4) In full down position
 - (5) Position unknown
 - (9) Unknown if position has adjustable upper anchorage adjustment
23. Automatic (Passive) Belt System Availability/Function Ø
- (0) Not equipped/not available
 - (1) 2 point automatic belts
 - (2) 3 point automatic belts
 - (3) Automatic belts - type unknown
- Non-functional*
- (4) Automatic belts destroyed or rendered inoperative
 - (9) Unknown
24. Automatic (Passive) Belt System Use Ø
- (0) Not equipped/not available/destroyed or rendered inoperative
 - (1) Automatic belt in use
 - (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
 - (3) Automatic belt use unknown
 - (9) Unknown
25. Automatic (Passive) Belt System Type Ø
- (0) Not equipped/not available
 - (1) Non-motorized system
 - (2) Motorized system
 - (9) Unknown
26. Proper Use of Automatic (Passive) Belt System Ø
- (0) Not equipped/not available/not used
 - (1) Automatic belt used properly
 - (2) Automatic belt used properly with child safety seat
- Automatic Belt Used Improperly*
- (3) Automatic shoulder belt worn under arm
 - (4) Automatic shoulder belt worn behind back
 - (5) Automatic belt worn around more than one person
 - (6) Lap portion of automatic belt worn on abdomen
 - (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
 - (8) Other improper use of automatic belt system (specify): _____
 - (9) Unknown
27. Automatic (Passive) Belt Failure Modes During Accident Ø
- (0) Not equipped/not available/not in use
 - (1) No automatic belt failure(s)
 - (2) Torn webbing (stretched webbing not included)
 - (3) Broken buckle or latchplate
 - (4) Upper anchorage separated
 - (5) Other anchorage separated (specify): _____
 - (6) Broken retractor
 - (7) Combination of above (specify): _____
 - (8) Other automatic belt failure (specify): _____
 - (9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use

- (0) None used
 (1) Police did not indicate belt use
 (2) Shoulder belt
 (3) Lap belt
 (4) Lap and shoulder belt
 (5) Belt used, type not specified
 (6) Child safety seat
 (7) Automatic belt
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function

- (0) No air bag available
 (1) Police did not indicate air bag availability/function
 (2) Deployed
 (3) Not deployed
 (4) Unknown if deployed
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
 [] Vehicle inspection
 [] Official injury data
 [] Driver/occupant interview
 [] Other (specify):

[X] Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System

Availability/Function
 (This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

(2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

31. Frontal Air Bag System Deployment

(This Occupant Position)

- (0) Not equipped/not available
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

32. Other Than First Seat Frontal Air Bag

Availability/Function
 (This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

(2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position)

- (0) Not equipped with an "other" air bag
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

34. Are There Indications of Air Bag System Failure?

(This Occupant Position)

- (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

(9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? ϕ

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag ϕ

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? ϕ

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify):
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number $\phi\phi$

- (00) Not equipped/not available
Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact ϕ

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify):
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact $\phi\phi\phi$

- (-000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? $\phi\phi$

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):

- (95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

HEAD RESTRAINT AND SEAT EVALUATION

44. Source of Air Bag Damage 4/0
 (00) Not equipped/not available
 (01) Not damaged
 (02) Object worn by occupant, (specify):

 (03) Object carried by occupant, (specify):

 (04) Adaptive/assistive controls, (specify):

 (05) Fire in vehicle
 (06) Thermal burns
 (07) Rescue or emergency efforts
 (88) Other damage source (specify):

 (95) Damaged, unknown source
 (96) Deployed, unknown if damaged
 (97) Not deployed
 (98) Unknown if deployed
 (99) Unknown
45. Was The Air Bag Tethered? 0
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of tether straps):

 (3) Deployed, unknown if tethered
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
46. Did The Air Bag Have Vent Ports? 0
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of vent ports):

 (3) Deployed, unknown if vent ports present
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
47. Was the Air Bag in this Occupant's Position
 Contacted by Another Occupant? 0
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

 (3) Deployed, unknown if other occupant contact to
 air bag
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
48. Was This Occupant Wearing Eye-wear? 0
 (0) Not equipped/not available
 (1) No
 (2) Eyeglasses/sunglasses
 (3) Contact lenses
 (4) Deployed, unknown if eyewear worn
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

49. Head Restraint Type/Damage by Occupant
at This Occupant Position 9

- (0) No head restraints
 (1) Integral—no damage
 (2) Integral—damaged during accident
 (3) Adjustable—no damage
 (4) Adjustable—damaged during accident
 (5) Add-on—no damage
 (6) Add-on—damaged during accident
 (8) Other (specify):

 (9) Unknown

50. Seat Type (this Occupant Position) 9 9

- (00) Occupant not seated or no seat
 (01) Bucket
 (02) Bucket with folding back
 (03) Bench
 (04) Bench with separate back cushions
 (05) Bench with folding back(s)
 (06) Split bench with separate back cushions
 (07) Split bench with folding back(s)
 (08) Pedestal (i.e., column supported)
 (09) Box mounted seat (i.e., van type)
 (10) Other seat type (specify):

 (99) Unknown

51. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
 (1) Forward facing seat
 (2) Rear facing seat
 (3) Side facing seat (inward)
 (4) Side facing seat (outward)
 (8) Other (specify):

 (9) Unknown

52. Seat Track Adjusted Position Prior To Impact 1

- (0) Occupant not seated or no seat
 (1) Non-adjustable seat track

Adjustable Seat Track

- (2) Seat at forward most track position
 (3) Seat between forward most and middle track
 positions
 (4) Seat at middle track position
 (5) Seat between middle and rear most track
 positions
 (6) Seat at rear most track position
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact Ø 1

- (00) Occupant not seated or no seat
 (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
 (12) Moved to rearward midrange position
 (13) Moved to slightly rearward position
 (14) Retained pre-impact position
 (15) Moved to slightly forward position
 (16) Moved to forward midrange position
 (17) Moved to completely forward position




Slightly reclined prior to impact

- (21) Moved to completely rearward position
 (22) Moved to rearward midrange position
 (23) Retained pre-impact position
 (24) Moved to upright position
 (25) Moved to slightly forward position
 (26) Moved to forward midrange position
 (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
 (32) Moved to rearward midrange position
 (33) Moved to slightly rearward position
 (34) Moved to upright position
 (35) Moved to slightly forward position
 (36) Moved to forward midrange position
 (37) Moved to completely forward position

- (99) Unknown

54. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) No seat performance failure(s)
 (2) Seat adjusters failed
 (3) Seat back folding locks or "seat back" failed
 (specify): _____
 (4) Seat track/anchors failed
 (5) Deformed by impact of occupant
 (6) Deformed by passenger compartment intrusion,
 (specify): _____
 (7) Combination of above (specify): _____
 (8) Other (specify): _____
 (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model φ φ φ

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat φ

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation φ φ

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage φ φ59. Child Safety Seat Shield Usage φ φ60. Child Safety Seat Tether Usage φ φNote: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES61. Injury Severity (Police Rating) 4

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 1

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):

- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) Ø

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

- (9) Unknown

64. Hospital Stay Ø Ø

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 62

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant Ø

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE**VARIABLES 66-74****TO BE CODED BY THE ZONE CENTER**

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****TRAUMA DATA**66. Time to Death 01

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death 9968. 2nd Medically Reported Cause of Death 9969. 3rd Medically Reported Cause of Death 99

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

70. Number of Recorded Injuries for This Occupant 97

Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

71. Glasgow Coma Scale (GCS) Score (at Medical Facility) 01

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood? 1

- (1) No - blood not given
(2) Yes - blood given (specify units):
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO₃ 01

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION74. Primary Source of Belt Use Determination 9

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):
(9) Unknown if belt used

National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DS1-95-SP-0133. Vehicle Number 014. Occupant Number 04

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 30

Code actual age at time of accident.

(00) Less than one year old (specify by month): _____

(97) 97 years and older _____

(99) Unknown _____

6. Occupant's Sex 2

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height 999Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight 999Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role 2

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 99

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify): _____

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify): _____

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify): _____

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify): _____

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify): _____

(99) Unknown

11. Occupant's Posture 9

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify): _____

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 2

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): FIRE

(9) Unknown

17. Occupant Mobility Ø

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 9

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 9

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function Ø

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use Ø

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type Ø

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System Ø

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident Ø

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use

- (0) None used
 (1) Police did not indicate belt use
 (2) Shoulder belt
 (3) Lap belt
 (4) Lap and shoulder belt
 (5) Belt used, type not specified
 (6) Child safety seat
 (7) Automatic belt
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function

- (0) No air bag available
 (1) Police did not indicate air bag availability/function
 (2) Deployed
 (3) Not deployed
 (4) Unknown if deployed
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
 [] Vehicle inspection
 [] Official injury data
 [] Driver/occupant interview
 [] Other (specify):

☒ Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

31. Frontal Air Bag System Deployment

(This Occupant Position)

- (0) Not equipped/not available
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

32. Other Than First Seat Frontal Air Bag

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position)

- (0) Not equipped with an "other" air bag
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

34. Are There Indications of Air Bag System Failure?

(This Occupant Position)

- (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

(9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? ϕ

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag ϕ

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? ϕ

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify):
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number $\phi \phi$

- (00) Not equipped/not available
Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact ϕ

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify):
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact $\phi \phi \phi$

- (-000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes (specify):
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? $\phi \phi$

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify):
(95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

44. Source of Air Bag Damage *φ*
 (00) Not equipped/not available
 (01) Not damaged
 (02) Object worn by occupant, (specify):

 (03) Object carried by occupant, (specify):

 (04) Adaptive/assistive controls, (specify):

 (05) Fire in vehicle
 (06) Thermal burns
 (07) Rescue or emergency efforts
 (88) Other damage source (specify):

 (95) Damaged, unknown source
 (96) Deployed, unknown if damaged
 (97) Not deployed
 (98) Unknown if deployed
 (99) Unknown
45. Was The Air Bag Tethered? *φ*
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of tether straps):

 (3) Deployed, unknown if tethered
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
46. Did The Air Bag Have Vent Ports? *φ*
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of vent ports):

 (3) Deployed, unknown if vent ports present
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? *φ*
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

 (3) Deployed, unknown if other occupant contact to air bag
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
48. Was This Occupant Wearing Eye-wear? *φ*
 (0) Not equipped/not available
 (1) No
 (2) Eyeglasses/sunglasses
 (3) Contact lenses
 (4) Deployed, unknown if eyewear worn
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION

49. Head Restraint Type/Damage by Occupant at This Occupant Position *9*
 (0) No head restraints
 (1) Integral—no damage
 (2) Integral—damaged during accident
 (3) Adjustable—no damage
 (4) Adjustable—damaged during accident
 (5) Add-on—no damage
 (6) Add-on—damaged during accident
 (8) Other (specify):

 (9) Unknown
50. Seat Type (this Occupant Position) *9 9*
 (00) Occupant not seated or no seat
 (01) Bucket
 (02) Bucket with folding back
 (03) Bench
 (04) Bench with separate back cushions
 (05) Bench with folding back(s)
 (06) Split bench with separate back cushions
 (07) Split bench with folding back(s)
 (08) Pedestal (i.e., column supported)
 (09) Box mounted seat (i.e., van type)
 (10) Other seat type (specify):

 (99) Unknown
51. Seat Orientation (this Occupant Position) *1*
 (0) Occupant not seated or no seat
 (1) Forward facing seat
 (2) Rear facing seat
 (3) Side facing seat (inward)
 (4) Side facing seat (outward)
 (8) Other (specify):

 (9) Unknown
52. Seat Track Adjusted Position Prior To Impact *1*
 (0) Occupant not seated or no seat
 (1) Non-adjustable seat track
Adjustable Seat Track
 (2) Seat at forward most track position
 (3) Seat between forward most and middle track positions
 (4) Seat at middle track position
 (5) Seat between middle and rear most track positions
 (6) Seat at rear most track position
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 01

- (00) Occupant not seated or no seat
 (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
 (12) Moved to rearward midrange position
 (13) Moved to slightly rearward position
 (14) Retained pre-impact position
 (15) Moved to slightly forward position
 (16) Moved to forward midrange position
 (17) Moved to completely forward position




Slightly reclined prior to impact

- (21) Moved to completely rearward position
 (22) Moved to rearward midrange position
 (23) Retained pre-impact position
 (24) Moved to upright position
 (25) Moved to slightly forward position
 (26) Moved to forward midrange position
 (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
 (32) Moved to rearward midrange position
 (33) Moved to slightly rearward position
 (34) Moved to upright position
 (35) Moved to slightly forward position
 (36) Moved to forward midrange position
 (37) Moved to completely forward position

- (99) Unknown

54. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) No seat performance failure(s)
 (2) Seat adjusters failed
 (3) Seat back folding locks or "seat back" failed
 (specify): _____
 (4) Seat track/anchors failed
 (5) Deformed by impact of occupant
 (6) Deformed by passenger compartment intrusion,
 (specify): _____
 (7) Combination of above (specify): _____
 (8) Other (specify): _____
 (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES**61. Injury Severity (Police Rating)** 4

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 1

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):

- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) Ø

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

- (9) Unknown

64. Hospital Stay ØØ

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 62

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant Ø

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE**VARIABLES 66-74****TO BE CODED BY THE ZONE CENTER**

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****TRAUMA DATA**

66. Time to Death

_____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death

68. 2nd Medically Reported Cause of Death

69. 3rd Medically Reported Cause of Death

_____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

70. Number of Recorded Injuries for This Occupant

_____ Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

71. Glasgow Coma Scale (GCS) Score (at Medical Facility)

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood?

- (1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO₃

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DS1-95-SP-013

3. Vehicle Number

01

4. Occupant Number

05

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height

Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight

Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify): _____

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify): _____

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify): _____

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify): _____

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify): _____

(99) Unknown

11. Occupant's Posture

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify): _____

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 2

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): FIRE

(9) Unknown

17. Occupant Mobility Ø

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 9

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 9

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function Ø

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use Ø

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type Ø

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System Ø

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident Ø

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

AIR BAG SYSTEM FUNCTION

28. Police Reported Belt Use 9

- (0) None used
 (1) Police did not indicate belt use
 (2) Shoulder belt
 (3) Lap belt
 (4) Lap and shoulder belt
 (5) Belt used, type not specified
 (6) Child safety seat
 (7) Automatic belt
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1

- (0) No air bag available
 (1) Police did not indicate air bag availability/function
 (2) Deployed
 (3) Not deployed
 (4) Unknown if deployed
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☐ Not equipped/not available/destroyed or rendered inoperative
☐ Vehicle inspection
☐ Official injury data
☐ Driver/occupant interview
☐ Other (specify):

☒ Unknown if belt used

30. Frontal Air Bag System Availability/Function Ø

- (This Occupant Position)
 (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):
 (3) Air bag not reinstalled
 (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) Ø

- (0) Not equipped/not available
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) Ø

- (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):
 (3) Air bag not reinstalled
 (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) Ø

- (0) Not equipped with an "other" air bag
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

34. Are There Indications of Air Bag System Failure? Ø

- (This Occupant Position)
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):
 (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? ϕ

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag ϕ

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? ϕ

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number ϕ ϕ

- (00) Not equipped/not available
_____ Code the accident event sequence number that initiated the air bag deployment
(96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact ϕ

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____
(6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact ϕ ϕ ϕ

- (-000) Not equipped/not available
Code the value of the delta V for the impact that initiated the air bag deployment
(-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? ϕ

- (0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? ϕ ϕ

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____

- (95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

HEAD RESTRAINT AND SEAT EVALUATION

44. Source of Air Bag Damage Ø Ø

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):

- (03) Object carried by occupant, (specify):

- (04) Adaptive/assistive controls, (specify):

- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):

- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

45. Was The Air Bag Tethered? Ø

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps):

- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

46. Did The Air Bag Have Vent Ports? Ø

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):

- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

47. Was the Air Bag in this Occupant's Position
Contacted by Another Occupant? Ø

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):

- (3) Deployed, unknown if other occupant contact to
air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

48. Was This Occupant Wearing Eye-wear? Ø

- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

49. Head Restraint Type/Damage by Occupant
at This Occupant Position 9

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify):

- (9) Unknown

50. Seat Type (this Occupant Position) 9 9

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Box mounted seat (i.e., van type)
- (10) Other seat type (specify):

- (99) Unknown

51. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify):

- (9) Unknown

52. Seat Track Adjusted Position Prior To Impact 1

- (0) Occupant not seated or no seat
- (1) Non-adjustable seat track

Adjustable Seat Track

- (2) Seat at forward most track position
- (3) Seat between forward most and middle track
positions
- (4) Seat at middle track position
- (5) Seat between middle and rear most track
positions
- (6) Seat at rear most track position
- (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 6 1

- (00) Occupant not seated or no seat
 (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
 (12) Moved to rearward midrange position
 (13) Moved to slightly rearward position
 (14) Retained pre-impact position
 (15) Moved to slightly forward position
 (16) Moved to forward midrange position
 (17) Moved to completely forward position




Slightly reclined prior to impact

- (21) Moved to completely rearward position
 (22) Moved to rearward midrange position
 (23) Retained pre-impact position
 (24) Moved to upright position
 (25) Moved to slightly forward position
 (26) Moved to forward midrange position
 (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
 (32) Moved to rearward midrange position
 (33) Moved to slightly rearward position
 (34) Moved to upright position
 (35) Moved to slightly forward position
 (36) Moved to forward midrange position
 (37) Moved to completely forward position

(99) Unknown

54. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) No seat performance failure(s)
 (2) Seat adjusters failed
 (3) Seat back folding locks or "seat back" failed
 (specify): _____
 (4) Seat track/anchors failed
 (5) Deformed by impact of occupant
 (6) Deformed by passenger compartment intrusion,
 (specify): _____
 (7) Combination of above (specify): _____
 (8) Other (specify): _____
 (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating) 4

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 1

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):

- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) Ø

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

64. Hospital Stay Ø Ø

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 62

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant Ø

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****66. Time to Death**

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death**68. 2nd Medically Reported Cause of Death****69. 3rd Medically Reported Cause of Death**
Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

70. Number of Recorded Injuries for This Occupant

Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

TRAUMA DATA**71. Glasgow Coma Scale (GCS) Score (at Medical Facility)**

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood?

- (1) No - blood not given
(2) Yes - blood given

(specify units):

- (9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO₃

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION**74. Primary Source of Belt Use Determination**

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify):
(9) Unknown if belt used

National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DS1-95-SP-0133. Vehicle Number 014. Occupant Number 06

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 62

Code actual age at time of accident.

(00) Less than one year old (specify by month): _____

(97) 97 years and older _____

(99) Unknown

6. Occupant's Sex 2

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height 999Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight 999Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role 2

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 99

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify): _____

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify): _____

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify): _____

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify): _____

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify): _____

(99) Unknown

11. Occupant's Posture 9

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify): _____

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 2

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): FIRE

(9) Unknown

17. Occupant Mobility Ø

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

(9) Unknown

POLICE REPORTED RESTRAINT USE

AIR BAG SYSTEM FUNCTION

28. Police Reported Belt Use 9

- (0) None used
- (1) Police did not indicate belt use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Automatic belt
- (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1

- (0) No air bag available
- (1) Police did not indicate air bag availability/function
- (2) Deployed
- (3) Not deployed
- (4) Unknown if deployed
- (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☐ Not equipped/not available/destroyed or rendered inoperative
- ☐ Vehicle inspection
- ☐ Official injury data
- ☐ Driver/occupant interview
- ☐ Other (specify):

☒ Unknown if belt used

30. Frontal Air Bag System Availability/Function Ø

- (This Occupant Position)
- (0) Not equipped/not available
 - (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) Ø

- (0) Not equipped/not available
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function Ø

- (This Occupant Position)
- (0) Not equipped/not available
 - (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
- (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) Ø

- (0) Not equipped with an "other" air bag
- (1) Deployed during accident (as a result of impact)
- (2) Deployed inadvertently just prior to accident
- (3) Deployed, details unknown
- (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (5) Unknown if deployed
- (7) Nondeployed
- (9) Unknown

34. Are There Indications of Air Bag System Failure? Ø

- (This Occupant Position)
- (0) Not equipped/not available
 - (1) No
 - (2) Yes (specify):

- (9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? ☒

(0) Not equipped/not available

(1) No previous accidents

Yes

(2) Previous accident(s) without deployment(s)

(3) One previous accident with deployment

(4) More than one previous accident with at least one deployment

(8) Previous accidents, unknown deployment status

(9) Unknown

36. Type of Air Bag ☒

(0) Not equipped/not available

(1) Original manufacturer installed system

(2) Retrofitted air bag

(3) Replacement air bag

(8) Unknown type of air bag

(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? ☒

(0) Not equipped/not available

(1) No prior maintenance

(2) Yes, prior maintenance (specify): _____

(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number ☒

(00) Not equipped/not available

Code the accident event sequence number that initiated the air bag deployment

(96) Deployed, unknown event

(97) Not deployed

(98) Unknown if deployed

(99) Unknown

39. CDC For Air Bag Deployment Impact ☒

(0) Not equipped/not available

(1) Highest delta V

(2) Second highest delta V

(3) Other non-coded delta V (specify): _____

(6) Deployed, unknown event

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

40. Longitudinal Component of ☒

Delta V For Air Bag

Deployment Impact

(-000) Not equipped/not available

Code the value of the delta V for the impact that initiated the air bag deployment

(-996) Deployment, unknown longitudinal Delta V

(-997) Not deployed

(-998) Unknown if deployed

(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? ☒

(0) Not equipped/not available

(1) No

(2) Yes

(3) Deployed, unknown if flap(s) opened at designated tear points

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? ☒

(0) Not equipped/not available

(1) No

(2) Yes (specify): _____

(3) Deployed, unknown if air bag module cover flap(s) damaged

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

43. Was There Damage To The Air Bag? ☒

(00) Not equipped/not available

(01) Not damaged

Yes - Air Bag Damage

(02) Ruptured

(03) Cut

(04) Torn

(05) Holed

(06) Burned

(07) Abraded

(88) Other damage (specify): _____

(95) Damaged, details unknown

(96) Deployed, unknown if damaged

(97) Not deployed

(98) Unknown if deployed

(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

HEAD RESTRAINT AND SEAT EVALUATION

44. Source of Air Bag Damage Ø Ø
 (00) Not equipped/not available
 (01) Not damaged
 (02) Object worn by occupant, (specify):

 (03) Object carried by occupant, (specify):

 (04) Adaptive/assistive controls, (specify):

 (05) Fire in vehicle
 (06) Thermal burns
 (07) Rescue or emergency efforts
 (08) Other damage source (specify):

 (95) Damaged, unknown source
 (96) Deployed, unknown if damaged
 (97) Not deployed
 (98) Unknown if deployed
 (99) Unknown
45. Was The Air Bag Tethered? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of tether straps):

 (3) Deployed, unknown if tethered
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
46. Did The Air Bag Have Vent Ports? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify number of vent ports):

 (3) Deployed, unknown if vent ports present
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
47. Was the Air Bag in this Occupant's Position
Contacted by Another Occupant? Ø
 (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

 (3) Deployed, unknown if other occupant contact to
air bag
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown
48. Was This Occupant Wearing Eye-wear? Ø
 (0) Not equipped/not available
 (1) No
 (2) Eyeglasses/sunglasses
 (3) Contact lenses
 (4) Deployed, unknown if eyewear worn
 (7) Not deployed
 (8) Unknown if deployed
 (9) Unknown

49. Head Restraint Type/Damage by Occupant
at This Occupant Position 9
 (0) No head restraints
 (1) Integral—no damage
 (2) Integral—damaged during accident
 (3) Adjustable—no damage
 (4) Adjustable—damaged during accident
 (5) Add-on—no damage
 (6) Add-on—damaged during accident
 (8) Other (specify):

 (9) Unknown
50. Seat Type (this Occupant Position) 9 9
 (00) Occupant not seated or no seat
 (01) Bucket
 (02) Bucket with folding back
 (03) Bench
 (04) Bench with separate back cushions
 (05) Bench with folding back(s)
 (06) Split bench with separate back cushions
 (07) Split bench with folding back(s)
 (08) Pedestal (i.e., column supported)
 (09) Box mounted seat (i.e., van type)
 (10) Other seat type (specify):

 (99) Unknown
51. Seat Orientation (this Occupant Position) 1
 (0) Occupant not seated or no seat
 (1) Forward facing seat
 (2) Rear facing seat
 (3) Side facing seat (inward)
 (4) Side facing seat (outward)
 (8) Other (specify):

 (9) Unknown
52. Seat Track Adjusted Position Prior To Impact 1
 (0) Occupant not seated or no seat
 (1) Non-adjustable seat track
- Adjustable Seat Track*
 (2) Seat at forward most track position
 (3) Seat between forward most and middle track
positions
 (4) Seat at middle track position
 (5) Seat between middle and rear most track
positions
 (6) Seat at rear most track position
 (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 6 1

- (00) Occupant not seated or no seat
 (01) Not adjustable

Upright prior to impact

- (11) Moved to completely rearward position
 (12) Moved to rearward midrange position
 (13) Moved to slightly rearward position
 (14) Retained pre-impact position
 (15) Moved to slightly forward position
 (16) Moved to forward midrange position
 (17) Moved to completely forward position




Slightly reclined prior to impact

- (21) Moved to completely rearward position
 (22) Moved to rearward midrange position
 (23) Retained pre-impact position
 (24) Moved to upright position
 (25) Moved to slightly forward position
 (26) Moved to forward midrange position
 (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
 (32) Moved to rearward midrange position
 (33) Moved to slightly rearward position
 (34) Moved to upright position
 (35) Moved to slightly forward position
 (36) Moved to forward midrange position
 (37) Moved to completely forward position

(99) Unknown

54. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
 (1) No seat performance failure(s)
 (2) Seat adjusters failed
 (3) Seat back folding locks or "seat back" failed
 (specify): _____
 (4) Seat track/anchors failed
 (5) Deformed by impact of occupant
 (6) Deformed by passenger compartment intrusion,
 (specify): _____
 (7) Combination of above (specify): _____
 (8) Other (specify): _____
 (9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES

61. Injury Severity (Police Rating)

4

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality

1

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):
- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment)

Ø

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):
- (9) Unknown

64. Hospital Stay

Ø Ø

- (00) Not Hospitalized
- Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost

62

- Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant

Ø

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE

VARIABLES 66-74

TO BE CODED BY THE ZONE CENTER

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES**

66. Time to Death 01
 _____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
 (96) Fatal - ruled disease
 (99) Unknown

67. 1st Medically Reported Cause of Death 99

68. 2nd Medically Reported Cause of Death 99

69. 3rd Medically Reported Cause of Death 99

_____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
 (96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____

(97) Other result (includes fatal ruled disease) (specify): _____

(99) Unknown

70. Number of Recorded Injuries for This Occupant 97

_____ Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
 (97) Injured, details unknown
 (99) Unknown if injured

TRAUMA DATA

71. Glasgow Coma Scale (GCS) Score 01
 (at Medical Facility)

- (00) Not injured
 (01) Injured - not treated at medical facility
 (02) No GCS Score at medical facility
 (03-15) Code the actual value of the initial GCS Score recorded at medical facility.
 (97) Injured, details unknown
 (99) Unknown if injured

72. Was the Occupant Given Blood? 1

- (1) No - blood not given
 (2) Yes - blood given

(specify units): _____

(9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO₃ 01

- (00) Not injured
 (01) Injured, ABGs not measured or reported
 (02-50) Code the actual value of the HCO₃
 (96) ABGs reported, HCO₃ unknown
 (97) Injured, details unknown
 (99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination 9

(0) Not equipped/not available/destroyed or rendered inoperative

- (1) Vehicle inspection
 (2) Official injury data
 (3) Driver/occupant interview
 (8) Other (specify): _____
 (9) Unknown if belt used



GENERAL VEHICLE FORM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DSI-95-SP-013

3. Vehicle Number

02

VEHICLE IDENTIFICATION

4. Vehicle Model Year

Code the last two digits of the model year
(99) Unknown91

5. Vehicle Make (specify):

TOYOTAApplicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(99) Unknown49

6. Vehicle Model (specify):

CELICA GTSApplicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(999) Unknown033

7. Body Type

Note: Applicable codes may be found on
the back of this page.03

8. Vehicle Identification Number

JT2SI85N8M0 * * * * *Left justify; Slash zeros and letter Z (0 and Z)
No VIN—Code all zeros
Unknown—Code all nines

9. Vehicle Special Use (This Trip)

(0) No special use

(1) Taxi

(2) Vehicle used as school bus

(3) Vehicle used as other bus

(4) Military

(5) Police

(6) Ambulance

(7) Fire truck or car

(8) Other (specify):

(9) Unknown

0

OFFICIAL RECORDS

10. Police Reported Vehicle Disposition

(0) Not towed due to vehicle damage

(1) Towed due to vehicle damage

(9) Unknown

1

11. Police Reported Travel Speed

Code to the nearest kmph (NOTE: 000 means
less than 0.5 kmph)

(160) 159.5 kmph and above

(999) Unknown

_____ mph X 1.6093 = _____ kmph

999

12. Speed Limit

(000) No statutory limit

Code posted or statutory speed limit
in kmph

(999) Unknown

08955 mph X 1.6093 = 089 kmph

13. Police Reported Alcohol Presence For Driver

(0) No alcohol present

(1) Yes alcohol present

(7) Not reported

(8) No driver present

(9) Unknown

1

14. Alcohol Test Result For Driver

Code actual value (decimal implied
before first digit—0.xx)

(95) Test refused

(96) None given

(97) AC test performed, results unknown

(98) No driver present

(99) Unknown

97Source: PAR15. Police Reported Other Drug Presence For
Driver

(0) No other drug(s) present

(1) Yes other drug(s) present

(7) Not reported

(8) No driver present

(9) Unknown

9

16. Other Drug Specimen Test Result For Driver

(0) No specimen test given

(1) Drug(s) not found in specimen

(2) Drug(s) found in specimen, (specify):

(3) Specimen test given, results unknown or not
obtained

(8) No driver present

(9) Unknown if specimen test given

9

17. Driver's Zip Code

(00001) Driver not a resident of U.S. or territories

Code actual 5-digit zip code

(99998) No driver present

(99999) Unknown

18. Driver's Race/Ethnic Origin

(1) White (non-Hispanic)

(2) Black (non-Hispanic)

(3) White (Hispanic)

(4) Black (Hispanic)

(5) American Indian, Eskimo or Aleut

(6) Asian or Pacific Islander

(7) Other (specify):

(8) No driver present

(9) Unknown

1

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): _____
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles ($\leq 4,500$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks ($\leq 4,500$ kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ($\leq 4,500$ kgs GVWR)
- (23) Van based motorhome ($\leq 4,500$ kgs GVWR)
- (24) Van based school bus ($\leq 4,500$ kgs GVWR)
- (25) Van based other bus ($\leq 4,500$ kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): _____
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, $\leq 4,500$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)

- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks ($\leq 4,500$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): _____
- (59) Unknown bus type

Medium/Heavy Trucks ($> 4,500$ kgs GVWR)

- (60) Step van ($> 4,500$ kgs GVWR)
- (61) Single unit straight truck ($4,500$ kgs $<$ GVWR $\leq 8,850$ kgs)
- (62) Single unit straight truck ($8,850$ kgs $<$ GVWR $\leq 12,000$ kgs)
- (63) Single unit straight truck ($> 12,000$ kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): _____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

PRECRASH ENVIRONMENTAL DATA

19. Relation To Interchange Or Junction φ

- (0) Non-interchange area and non-junction
(1) Interchange area related

Non-Interchange junctions

- (2) Intersection related
(3) Driveway, alley access related
(4) Other junction (specify) _____

- (5) _____
Unknown type of junction

- (9) Unknown

20. Trafficway Flow 1

- (0) Not physically divided (two way traffic)
(1) Divided trafficway-median strip without positive barrier
(2) Divided trafficway-median strip with positive barrier
(3) One way traffic
(9) Unknown

21. Number Of Travel Lanes 5

- (1) One
(2) Two
(3) Three
(4) Four
(5) Five
(6) Six
(7) Seven or more
(9) Unknown

22. Roadway Alignment 1

- (1) Straight
(2) Curve right
(3) Curve left
(9) Unknown

23. Roadway Profile 4

- (1) Level
(2) Uphill grade (>2%)
(3) Hill crest
(4) Downhill grade (>2%)
(5) Sag
(9) Unknown

24. Roadway Surface Type 2

- (1) Concrete
(2) Bituminous (asphalt)
(3) Brick or block
(4) Slag, gravel, or stone
(5) Dirt
(8) Other (specify): _____
(9) Unknown

25. Roadway Surface Condition 1

- (1) Dry
(2) Wet
(3) Snow or slush
(4) Ice
(5) Sand, dirt, or oil
(8) Other (specify): _____
(9) Unknown

26. Light Conditions 3

- (1) Daylight
(2) Dark
(3) Dark, but lighted
(4) Dawn
(5) Dusk
(9) Unknown

27. Atmospheric Conditions φ

- (0) No adverse atmospheric-related driving conditions
(1) Rain
(2) Sleet/hail
(3) Snow
(4) Fog
(5) Rain and fog
(6) Sleet and fog
(7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): _____
(9) Unknown

28. Traffic Control Device 5

- (0) No traffic control(s)
(1) Traffic control signal (not RR crossing)

Regulatory

- (2) Stop sign
(3) Yield sign
(4) School zone sign
(5) Other regulatory sign (specify):
DO NOT ENTER
(6) Warning sign (not RR crossing)
(7) Unknown sign
(8) Miscellaneous/other controls including RR controls (specify): _____
(9) Unknown

29. Traffic Control Device Functioning 2

- (0) No traffic control device
(1) Traffic control device not functioning (specify): _____
(2) Traffic control device functioning properly
(9) Unknown

		BEST AVAILABLE							
Category	Configuration	ACCIDENT TYPES (Includes Intent)							
I. Single Driver	A. Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN			
	B. Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN			
	C. Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER	16 SPECIFICS UNKNOWN		
II. Same Trafficway Same Direction	D. Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 26, 27	 24 DECEL. 28, 29, 30, 31	 26 AVOID COLLISION WITH VEH.	 28 AVOID COLLISION WITH OBJECT	(EACH • 32) SPECIFICS OTHER	(EACH • 33) SPECIFICS UNKNOWN	
	E. Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	 42 AVOID COLLISION WITH VEH.	 44 AVOID COLLISION WITH OBJECT	(EACH • 42) SPECIFICS OTHER	(EACH • 43) SPECIFICS UNKNOWN
	F. Sideswipe Angle	 44 LATERAL MOVE	 45 LATERAL MOVE	 46 LATERAL MOVE	 47 LATERAL MOVE	(EACH • 48) SPECIFICS OTHER	(EACH • 49) SPECIFICS UNKNOWN		
III. Same Trafficway Opposite Direction	G. Head-On	 50 LATERAL MOVE	 51 LATERAL MOVE	(EACH • 52) SPECIFICS OTHER	(EACH • 53) SPECIFICS UNKNOWN				
	H. Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	 62 AVOID COLLISION WITH VEH.	 64 AVOID COLLISION WITH OBJECT	(EACH • 62) SPECIFICS OTHER	(EACH • 63) SPECIFICS UNKNOWN
	I. Sideswipe Angle	 64 LATERAL MOVE	 65 LATERAL MOVE	(EACH • 66) SPECIFICS OTHER	(EACH • 67) SPECIFICS UNKNOWN				
IV. Change Trafficway Vehicle Turning	J. Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 70 INITIAL SAME DIRECTIONS	 72 INITIAL SAME DIRECTIONS	 74 INITIAL SAME DIRECTIONS	 76 INITIAL SAME DIRECTIONS	(EACH • 74) SPECIFICS OTHER	(EACH • 75) SPECIFICS UNKNOWN	
	K. Turn Into Path	 77 TURN INTO SAME DIRECTION	 79 TURN INTO SAME DIRECTION	 81 TURN INTO OPPOSITE DIRECTIONS	 83 TURN INTO OPPOSITE DIRECTIONS	 85 TURN INTO OPPOSITE DIRECTIONS	 87 TURN INTO OPPOSITE DIRECTIONS	(EACH • 84) SPECIFICS OTHER	(EACH • 85) SPECIFICS UNKNOWN
V. Intersecting Paths (Vehicle Damage)	L. Straight Paths	 86	 88	 90	 92	 94	(EACH • 90) SPECIFICS OTHER	(EACH • 91) SPECIFICS UNKNOWN	
VI. Miscellaneous	M. Backing Etc.	 92 BACKING VEH.	 93 OTHER VEH. OR OBJECT	98 Other Accident Type 99 Unknown Accident Type 00 No Impact					

PRECRASH DRIVER RELATED DATA

30. Driver's Distraction/Inattention To Driving
(Prior To Recognition Of Critical Event)99

- (00) No driver present
- (01) Attentive or not distracted
- (02) Looked but did not see
- (03) By other occupant(s), (specify): _____
- (04) By moving object in vehicle (specify): _____
- (05) While talking or listening to cellular phone (specify location and type of phone): _____
- (06) While dialing cellular phone (specify location and type of phone): _____
- (07) While adjusting climate controls
- (08) While adjusting radio, cassette, CD (specify): _____
- (09) While using other device/object in vehicle (specify): _____
- (10) Sleepy or fell asleep
- (11) Distracted by outside person, object, or event (specify): _____
- (12) Eating or drinking
- (13) Smoking related
- (97) Distracted/inattentive, details unknown
- (98) Other, distraction (specify): _____
- (99) Unknown

31. Pre-Event Movement (Prior to Recognition of Critical Event)

41

- (00) No driver present
- (01) Going straight
- (02) Decelerating in traffic lane
- (03) Accelerating in traffic lane
- (04) Starting in traffic lane
- (05) Stopped in traffic lane
- (06) Passing or overtaking another vehicle
- (07) Disabled or parked in travel lane
- (08) Leaving a parking position
- (09) Entering a parking position
- (10) Turning right
- (11) Turning left
- (12) Making a U-turn
- (13) Backing up (other than for parking position)
- (14) Negotiating a curve
- (15) Changing lanes
- (16) Merging
- (17) Successful avoidance maneuver to a previous critical event
- (97) Other (specify): _____
- (99) Unknown

32. Critical Precrash Event

98*This Vehicle Loss of Control Due To:*

- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off) (specify): _____
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): _____
- (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): _____
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): _____
- (09) Unknown cause of control loss

This Vehicle Traveling

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (18) This vehicle decelerating
- (19) Unknown travel direction

Other Motor Vehicle In Lane

- (50) Other vehicle stopped
- (51) Traveling in same direction with lower steady speed
- (52) Traveling in same direction while decelerating
- (53) Traveling in same direction with higher speed
- (54) Traveling in opposite direction
- (55) In crossover
- (56) Backing
- (59) Unknown travel direction of other motor vehicle in lane

Other Motor Vehicle Encroaching Into Lane

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

Pedestrian, Pedalcyclist, or Other Nonmotorist

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway (specify): _____
- (84) Pedalcyclist or other nonmotorist approaching roadway, (specify): _____
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): _____

Object or Animal

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location
- (98) Other critical precrash event (specify): WRONG WAY ON A ONEWAY
- (99) Unknown ROADWAY

33. Attempted Avoidance Maneuver

00

- (00) No driver present
- (01) No avoidance maneuver
- (02) Braking (no lockup)
- (03) Braking (lockup)
- (04) Braking (lockup unknown)
- (05) Releasing brakes
- (06) Steering left
- (07) Steering right
- (08) Braking and steering left
- (09) Braking and steering right
- (10) Accelerating
- (11) Accelerating and steering left
- (12) Accelerating and steering right
- (98) Other action (specify):

(99) Unknown

34. Pre-Impact Stability

1

- (0) No driver present
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify):

(9) Precrash stability unknown

35. Pre-Impact Location

1

- (0) No driver present
- (1) Stayed in original travel lane
- (2) Stayed on roadway but left original travel lane
- (3) Stayed on roadway, not known if left original travel lane
- (4) Departed roadway
- (5) Remained off roadway
- (6) Returned to roadway
- (7) Entered roadway
- (9) Unknown

36. Accident Type

52

(Note: Applicable codes on back of this page)

- (00) No impact

Code the number of the diagram that best describes the accident circumstance

- (98) Other accident type (specify):

(99) Unknown

STOP HERE IF GV07 DOES NOT EQUAL 01 - 49

OCCUPANT RELATED

37. Driver Presence in Vehicle 1
(0) Driver not present
(1) Driver present
(9) Unknown

38. Number of Occupants This Vehicle 0 1
(00-96) Code actual number of occupants for this vehicle
(97) 97 or more
(99) Unknown

39. Number of Occupant Forms Submitted 0 1

AIR BAG RELATED

40. Is this an AOPS Vehicle? 1
(0) No (includes unknown)
(1) Yes - researcher determined
(2) VIN determined air bag system
(3) VIN determined automatic (passive) belts
(4) VIN determined air bag and automatic (passive) belts

41. Air Bag(s) Deployment, First Seat Frontal 2
(0) Not equipped or not available
(1) No air bags deployed

Single Air Bag Vehicle

- (2) Driver air bag deployed
(3) Driver air bag, unknown if deployed

Multiple Air Bag Vehicle

- (4) Driver side only deployed
(5) Passenger side only deployed
(6) Driver and passenger side deployed
(7) Driver and passenger side unknown if deployed
(8) Air bag(s) deployed, details unknown
(9) Unknown

42. Air Bag(s) Deployment, Other Than First Seat Frontal 0
(0) Not equipped with an "other" air bag
(1) Deployed during accident (as a result of impact)
(2) Deployed inadvertently just prior to accident
(3) Deployed, details unknown
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(5) Unknown if deployed
(7) Nondeployed
(9) Unknown

Specify type of "other" air bag present: _____

VEHICLE WEIGHT ITEMS

43. Vehicle Curb Weight 1 2 7 0
Code weight to nearest 10 kilograms.
(045) Less than 450 kilograms
(610) 6,100 kilograms or more
(999) Unknown
0 2 8 0 9 lbs X .4536 = 1 2 7 2 kgs

Source: _____

44. Vehicle Cargo Weight 0 0 0 0
Code weight to nearest 10 kilograms.
(000) Less than 5 kilograms
(450) 4,500 kilograms or more
(999) Unknown

_____ lbs X .4536 = _____ kgs

Source: _____

ROLLOVER DATA

45. Rollover 0 0
(00) No rollover (no overturning)
Rollover (primarily about the longitudinal axis)
(01-16) Code the number of quarter turns
(17) Rollover, 17 or more quarter turns (specify):

- (98) Rollover—end-over-end (i.e., primarily about the lateral axis)
(99) Rollover (overturn), details unknown

46. Rollover Initiation Type 0 0
(00) No rollover
(01) Trip-over
(02) Flip-over
(03) Turn-over
(04) Climb-over
(05) Fall-over
(06) Bounce-over
(07) Collision with another vehicle
(08) Other rollover initiation type specify: _____
(98) Rollover—end-over-end
(99) Unknown rollover initiation type

47. Location of Rollover Initiation 0
(0) No rollover
(1) On roadway
(2) On shoulder—paved
(3) On shoulder—unpaved
(4) On roadside or divided trafficway median
(8) Rollover—end-over-end
(9) Unknown

48. Rollover Initiation Object Contacted 0 0
(Note: Applicable codes on back of page)

49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0
(0) No rollover
(1) Wheels/tires
(2) Side plane
(3) End plane
(4) Undercarriage
(5) Other location on vehicle (specify): _____

- (6) Non-contact rollover forces (specify): _____

- (8) Rollover—end-over-end
(9) Unknown

50. Direction of Initial Roll 0
(0) No rollover
(1) Roll right - primarily about the longitudinal axis
(2) Roll left - primarily about the longitudinal axis
(8) Rollover—end-over-end
(9) Unknown roll direction

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

Noncollision

- (31) Turn-over — fall-over
- (32) No rollover impact initiation (end-over-end)
- (34) Jackknife

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)
(specify): _____

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____

- (69) Unknown fixed object _____

Collision with Nonfixed Object

- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____

- (89) Unknown nonfixed object _____

- (98) Other event (specify): _____

- (99) Unknown event or object _____

OVERRIDE/UNDERRIDE (THIS VEHICLE)

51. Front Override/Underride (this Vehicle) Ø
52. Rear Override/Underride (this Vehicle) Ø
- (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride

Override (see specific CDC)

[Between 2 CDS applicable vehicles (Bodytype, GV07=1-49)]

- (1) 1st CDC
(2) 2nd CDC
(3) Other not automated CDC (specify):

Underride (see specific CDC)

[Between 2 CDS applicable vehicles (Bodytype, GV07=1-49)]

- (4) 1st CDC
(5) 2nd CDC
(6) Other not automated CDC (specify):

- (7) Medium/heavy truck or bus override (of any configuration)
(9) Unknown

HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V

Values: (000)-(359) Code actual value

- (997) Noncollision
(998) Impact with object
(999) Unknown

53. Heading Angle For This Vehicle 1 8 Ø
54. Heading Angle For Other Vehicle Ø Ø Ø

RECONSTRUCTION DATA

55. Towed Trailing Unit Ø
- (0) No towed unit
(1) Yes—towed trailing unit
(9) Unknown
56. Documentation of Trajectory Data for This Vehicle Ø
- (0) No
(1) Yes
57. Post Collision Condition of Tree or Pole (For Highest Delta V) Ø
- (0) Not collision (for highest delta V) with tree or pole
(1) Not damaged
(2) Cracked/sheared
(3) Tilted <45 degrees
(4) Tilted ≥45 degrees
(5) Uprooted tree
(6) Separated pole from base
(7) Pole replaced
(8) Other (specify):

- (9) Unknown

ACCIDENT RECONSTRUCTION PROGRAMS HIGHEST DELTA V

58. Basis for Total (Resultant) Delta V (highest) Ø 1

(00) No vehicle inspection

Delta V Calculated

- (01) Reconstruction program
-damage only routine
(02) Reconstruction program
-damage and trajectory routine
(03) Missing vehicle algorithm

Delta V Not Calculated

- (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.

All vehicles within scope (CDC applicable) of reconstruction program but one of the collision conditions is beyond the scope of the reconstruction program or other acceptable reconstruction technique, regardless of adequacy of damage data.

- (05) Rollover
(06) Other non-horizontal forces
(07) Sideswipe type damage
(08) Severe override
(09) Yielding object
(10) Overlapping damage
(11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available.

(98) Other, (specify):

COMPUTER GENERATED CRASH SEVERITY

59. Total Delta V

08887.9 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means less than 0.5 kmph)

(160) 159.5 kmph and above

(999) Unknown

60. Longitudinal Component of
Delta V

Highest

+007-86.6 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: __000 means greater than

-0.5 kmph and less than +0.5 kmph)

(±160) ±159.5 kmph and above

(999) Unknown

61. Lateral Component of Delta V

Highest

+015-15.3 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: __000 means greater than -0.5 kmph and
less than +0.5 kmph)

(±160) ±159.5 kmph and above

(999) Unknown

62. Energy Absorption

228.60022866.2 Nearest 100 joules (highest)

____ Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)

(9997) 999,650 joules or more

(9999) Unknown

63. Impact Speed

Highest

998

____ Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means

less than 0.5 kmph)

(160) 159.5 kmph and above

(998) Trajectory algorithm not run

(999) Unknown

DELTA V CONFIDENCE LEVEL

64. Confidence In Reconstruction Program
Results (For Highest Delta V)

(0) No reconstruction

(1) Collision fits model — results appear
reasonable

(2) Collision fits model — results appear high

(3) Collision fits model — results appear low

(4) Borderline reconstruction — results appear
reasonable

OTHER SPEED ESTIMATE

65. Barrier Equivalent
Speed

Highest

06565.4 Nearest kmph (highest)

____ Nearest kmph (secondary)

(NOTE: 000 means

less than 0.5 kmph)

(160) 159.5 kmph and above

(999) Unknown

IS MISSING VEHICLE ALGORITHM APPLICABLE FOR THIS VEHICLE? [] YES [X] NO

IF YES: IS A COMPLETED PROGRAM SUMMARY INCLUDED? [] YES [] NO

ESTIMATED DELTA V

VEHICLE INSPECTION

66. Estimated Highest Delta V (Researcher Determined)

(0) Reconstruction Delta V coded

Estimated Delta V

- (1) Less than 10 kmph
- (2) ≥ 10 kmph but < 25 kmph
- (3) ≥ 25 kmph but < 40 kmph
- (4) ≥ 40 kmph but < 55 kmph
- (5) ≥ 55 kmph

Other estimates of damage severity

- (6) Minor
- (7) Moderate
- (8) Severe
- (9) Unknown

ϕ

67. Type of Vehicle Inspection

- (0) No inspection
- (1) Vehicle fully repaired-no damage evident
- (2) Partial inspection (specify):

- (3) Complete inspection

3

*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67=0), ***

DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***

THE EXTERIOR VEHICLE, INTERIOR VEHICLE,
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

EXTERIOR VEHICLE FORM

1. Primary Sampling Unit Number	_____	3. Vehicle Number	<u>02</u>
2. Case Number - Stratum	<u>DS1-95-SP-013</u>		

VEHICLE IDENTIFICATION

VIN JT2S185N8M0XXXXXX Model Year 91
Vehicle Make (specify): TOYOTA Vehicle Model (specify): CELICA

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
01	FULL FRONTAL	FULL FRONTAL	C6

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

[illegible]

ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	<u>99.6</u>	inches	x 2.54	=	<u>253</u> cm
Overall Length	<u>174.0</u>	inches	x 2.54	=	<u>442</u> cm
Maximum Width	<u>68.9</u>	inches	x 2.54	=	<u>175</u> cm
Curb Weight	<u>2804</u>	pounds	x .4536	=	<u>1272</u> kg
Average Track	<u>57.9</u>	inches	x 2.54	=	<u>147</u> cm
Front Overhang	<u>38.6</u>	inches	x 2.54	=	<u>98</u> cm
Rear Overhang	<u>35.8</u>	inches	x 2.54	=	<u>91</u> cm
Undeformed End Width	<u>55.1</u>	inches	x 2.54	=	<u>140</u> cm
Engine Size: cyl./displ.	<u>2200</u>	cc	x .001	=	<u>2.2</u> L
	<u>134</u>	CID	x .0164	=	<u>2.2</u> L

VEHICLE DAMAGE SKETCH

TIRE - WHEEL DAMAGE

a. Rotation physically restricted b. Tire deflated

RF <u>2</u>	RF <u>2</u>
LF <u>1</u>	LF <u>2</u>
RR <u>2</u>	RR <u>2</u>
LR <u>2</u>	LR <u>2</u>

(1) Yes (2) No (8) NA (9) Unk.

TYPE OF TRANSMISSION

☐ Manual ☒ Automatic

END SHIFT ≥ 10 CM

☒ Yes ☐ No

ORIGINAL SPECIFICATIONS

Wheelbase	<u>253</u>	cm
Overall Length	<u>442</u>	cm
Maximum Width	<u>175</u>	cm
Curb Weight	<u>1272</u>	kg
Average Track	<u>147</u>	cm
Front Overhang	<u>98</u>	cm
Rear Overhang	<u>91</u>	cm
Undeformed End Width	<u>140</u>	cm
Engine Size: cyl./displ.	<u>2.2</u>	L

WHEEL STEER ANGLES

(For locked front wheels or displaced rear axles only)

RF ± °
 LF ± 15 °
 RR ± °
 LR ± °






Within ± 5 degrees

DRIVE WHEELS

☒ FWD ☐ RWD ☐ 4WD

Approximate Cargo Weight 0 kg

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CODES FOR OBJECT CONTACTED

(99) **Unknown event or object**

[illegible]

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>Ø 1</u>	5. <u>Ø 2</u>	6. <u>7 2</u>	7. <u>F</u>	8. <u>D</u>	9. <u>E</u>	10. <u>W</u>	11. <u>Ø 4</u>

Second Highest Delta "V"

12. _____	13. _____	14. _____	15. _____	16. _____	17. _____	18. _____	19. _____
-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. <u>L</u>	21. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	22. <u>±D</u>
<u>14Ø</u>	<u>Ø4Ø</u>	<u>Ø82</u>	<u>Ø81</u>	<u>Ø95</u>	<u>1Ø2</u>	<u>1Ø6</u>	<u>+ - ØØØ</u>

Second Highest Delta "V"

23. <u>L</u>	24. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	25. <u>±D</u>
_____	_____	_____	_____	_____	_____	_____	<u>+ -</u>

26. Undeformed End Width

(Coded when highest severity impact is an end plane impact.)

_____ Code to the nearest centimeter

(250) 250 centimeters or more

(998) No highest severity end plane impact

(999) Unknown

14Ø

27. Direct Damage Width

(For highest severity impact)

_____ Code to the nearest centimeter

(250) 250 centimeters or more

(999) Unknown

14Ø

28. Original Wheelbase

_____ Code to the nearest centimeter

(650) 650 centimeters or more

(999) Unknown

Ø99.6 inches X 2.54 = 253 centimeters

253

29. Original Average Track Width

_____ Code to the nearest centimeter

(185) 185 centimeters or more

(999) Unknown

Ø57.9 inches X 2.54 = 147 centimeters

147

FUEL SYSTEM

30. Are CDCs Documented
but Not Coded on The
Automated File?

- (0) No
(1) Yes

0

31. Researcher's Assessment of Vehicle
Disposition

- (0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

1

32. Is This A Multi-Stage Manufactured Vehicle
And/Or A Certified Altered Vehicle?

- (0) No post manufacturer modifications
(1) Yes - post manufacturer modifications
(specify): _____

0

(Include photograph of CERTIFICATION
PLACARD in case report)

- (9) Unknown if vehicle is modified

FIRE OCCURRENCE

33. Fire Occurrence

- (0) No fire

Yes, fire occurred

- (1) Minor
(2) Major
(9) Unknown

0

34. Origin of Fire

- (0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention
system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify): _____

0

- (9) Unknown

35. Location of Fuel Tank-1 Filler Cap

2

36. Location of Fuel Tank-2 Filler Cap

0

- (0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on
left side plane
(3) Aft of center of the rear wheels (rear axle) on
right side plane
(4) Forward of center of the rear wheels (rear axle)
on left side plane
(5) Forward of center of the rear wheels (rear axle)
on right side plane
(6) Over the center of the rear wheels (rear axle)
on left side plane
(7) Over the center of the rear wheels (rear axle)
on right side plane
(8) Other (specify): _____
(9) Unknown

37. Type of Fuel Tank-1

1

38. Type of Fuel Tank-2

0

- (0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

39. Location of Fuel Tank-1

5

40. Location of Fuel Tank-2

0

- (0) No fuel tank
(1) Aft of center of the rear wheels (rear axle)
centered
(2) Aft of center of the rear wheels (rear axle) left
side
(3) Aft of center of the rear wheels (rear axle) right
side
(4) Forward of center of the rear wheels (rear axle)
centered
(5) Forward of center of the rear wheels (rear axle)
left side
(6) Forward of center of the rear wheels (rear axle)
right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

41. Damage to Fuel Tank-1

1

42. Damage to Fuel Tank-2

0

- (0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): _____
(9) Unknown

$$\frac{1}{\phi}$$

(0) No fuel tank
(1) No fuel leakage

(2) Tank
(3) Filler neck
(4) Cap
(5) Lines/pump/filter
(6) Vent/emission recovery
(8) Other (specify): _____
(9) Unknown

01

φ φ

(00) No fuel tank
(01) Gasoline
(02) Diesel
(03) CNG (Compressed Natural Gas)
(04) LPG (Liquid Petroleum Gas) also known as Propane
(05) LNG (Liquid Natural Gas)
(06) Methanol (M100 or M85)
(07) Ethanol (E100 or E85)
(08) Other (Hydrogen or others) (specify):

(10) Lead Acid Battery
(11) Nickel-Iron Battery
(12) Nickel-Cadmium Battery
(13) Sodium Metal Chloride Battery
(14) Sodium Sulfur Battery
(18) Other (Specify): _____

(99) Unknown fuel type

Φ

(9) Unknown if more than two tanks

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are approximately 20 lines visible. The paper has a slightly textured appearance and is set against a dark background.

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.



INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number

2. Case Number - Stratum

DSI-95-SP-013

3. Vehicle Number

02

INTEGRITY

4. Passenger Compartment Integrity

(00) No integrity loss

12

Yes, Integrity Was Lost Through

(01) Windshield

(02) Door (side)

(03) Door/hatch (back door)

(04) Roof

(05) Roof glass

(06) Side window

(07) Rear window (backlight)

(08) Roof and roof glass

(09) Windshield and door (side)

(10) Windshield and roof

(11) Side and rear window (side window and backlight)

(12) Windshield and side window

(13) Door and side window

(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 1 6. RF 3 7. LR 0 8. RR 0 9. TG/H 1

(0) No door/gate/hatch

(1) Door/gate/hatch remained closed and operational

(2) Door/gate/hatch came open during collision

(3) Door/gate/hatch jammed shut

(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch
Opening in Collision. If IV05-IV09 = 2, Then code 010. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

(1) Door operational (no damage)

(2) Latch/striker failure due to damage

(3) Hinge failure due to damage

(4) Door structure failure due to damage

(5) Door support (i.e., pillar, sill, roof side rail,
etc.) failure due to damage

(6) Latch/striker and hinge failure due to damage

(8) Other failure (specify):

(9) Unknown

GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 220. BL 2 21. Roof 2 22. Other 0

(0) No glazing

(1) AS-1 — Laminated

(2) AS-2 — Tempered

(3) AS-3 — Tempered-tinted (original)

(4) AS-2 — Tempered-with after market tint

(5) AS-3 — Tempered-tinted (with additional after market tint)

(6) AS-14 — Glass/Plastic

(7) Glazing removed prior to accident

(8) Other (specify):

(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR 2 27. RR 228. BL 1 29. Roof 2 30. Other 0

(0) No glazing

(1) Fixed

(2) Closed

(3) Partially opened

(4) Fully opened

(7) Glazing removed prior to accident

(9) Unknown

Glazing Damage from Impact Forces

31. WS 4 32. LF 6 33. RF 6 34. LR 6 35. RR 136. BL 1 37. Roof 1 38. Other 0

(0) No glazing

(1) No glazing damage from impact forces

(2) Glazing in place and cracked from impact forces

(3) Glazing in place and holed from impact forces

(4) Glazing out-of-place (cracked or not) and not holed from impact
forces

(5) Glazing out-of-place and holed from impact forces

(6) Glazing disintegrated from impact forces

(7) Glazing removed prior to accident

(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 3 40. LF 1 41. RF 1 42. LR 1 43. RR 144. BL 1 45. Roof 1 46. Other 0

(0) No glazing

(1) No occupant contact to glazing

(2) Glazing contacted by occupant but no glazing damage

(3) Glazing in place and cracked by occupant contact

(4) Glazing in place and holed by occupant contact

(5) Glazing out-of-place (cracked or not) by occupant

contact and not holed by occupant contact

(6) Glazing out-of-place by occupant contact and holed by occupant
contact



(7) Glazing removed prior to accident

(8) Glazing disintegrated by occupant contact

(9) Unknown if contacted by occupant

INTRUSION WORKSHEET

Note: Sketch intruded areas



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters)				DOMINANT CRUSH DIRECTION
		COMPARISON VALUE	—	INTRUDED VALUE	=	
R/SIDE	"A" PILLAR (LOWER)	103.0	—	69.0	= 34.0	LONG
R/SIDE	"A" PILLAR (TOP)	65.0	—	50.0	= 15.0	LONG
R/SIDE	INSTRUMENT PANEL	85.0	—	54.0	= 31.0	LONG
R/SIDE	SIDE PANEL	0	—	23.0	= 23.0	LAT.
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

INTRUDING COMPONENT

Interior Components

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify):

Exterior Components

- (30) Hood
- (31) Outside surface of this vehicle (specify):
- (32) Other exterior object in the environment (specify):
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify):
- (99) Unknown

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

Location of
IntrusionIntruding
ComponentMagnitude
of IntrusionDominant
Crush
Direction1st 47. 2 3 48. 0 6 49. 4 50. 22nd 51. 2 3 52. 0 4 53. 4 54. 23rd 55. 2 3 56. 1 0 57. 3 58. 34th 59. 2 3 60. 0 6 61. 2 62. 2

5th 63. _____ 64. _____ 65. _____ 66. _____

6th 67. _____ 68. _____ 69. _____ 70. _____

7th 71. _____ 72. _____ 73. _____ 74. _____

8th 75. _____ 76. _____ 77. _____ 78. _____

9th 79. _____ 80. _____ 81. _____ 82. _____

10th 83. _____ 84. _____ 85. _____ 86. _____

LOCATION OF INTRUSION

Front Seat

- (11) Left
- (12) Middle
- (13) Right

Fourth Seat

- (41) Left
- (42) Middle
- (43) Right

Second Seat

- (21) Left
- (22) Middle
- (23) Right

- (97) Catastrophic
- (98) Other enclosed area (specify)

(99) Unknown

Third Seat

- (31) Left
- (32) Middle
- (33) Right

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE — DAMAGE VALUE = DEFORMATION

—

=

—



=

—

=

—

=



STEERING COLUMN

INSTRUMENT PANEL

87. Steering Column Type 2

- (1) Fixed column
 (2) Tilt column
 (3) Telescoping column
 (4) Tilt and telescoping column
 (8) Other column type (specify): _____

(9) Unknown

88. Tilt Steering Column Adjustment 9

- (0) No tilt steering column
 (1) Full up
 (2) Between full up and center
 (3) Center
 (4) Between center and full down
 (5) Full down
 (9) Unknown

89. Telescoping Steering Column Adjustment Ø

- (0) No telescoping steering column
 (1) Full back
 (2) Between full back and midpoint
 (3) Midpoint
 (4) Between midpoint and full forward
 (5) Full forward
 (9) Unknown

90. Steering Rim/Spoke Deformation Ø Ø

Code actual measured

deformation to the nearest centimeter

- (00) No steering rim deformation
 (01-14) Actual measured value in centimeters
 (15) 15 centimeters or more
 (98) Observed deformation cannot be measured
 (99) Unknown

91. Location of Steering Rim/Spoke Deformation Ø Ø

(00) No steering rim deformation



Quarter Sections

- (01) Section A
 (02) Section B
 (03) Section C
 (04) Section D



Half Sections

- (05) Upper half of rim/spoke
 (06) Lower half of rim/spoke
 (07) Left half of rim/spoke
 (08) Right half of rim/spoke



- (09) Complete steering wheel collapse
 (10) Undetermined location
 (99) Unknown

92. Odometer Reading 999,000

_____ kilometers

Code to the nearest 1,000 kilometers

- (000) No odometer
 (001) Less than 1,500 kilometers
 (500) 499,500 kilometers or more
 (999) Unknown

_____ miles X 1 6093 = _____ kilometers

Source: INSPECTION / UNABLE TO READ93. Instrument Panel Damage from Occupant Contact? 1

- (0) No
 (1) Yes
 (9) Unknown

94. Type of Knee Bolster Covering 2

- (0) No knee bolster
 (1) Padded
 (2) Rigid plastic
 (8) Other (specify): _____
 (9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 2

- (0) No knee bolster
 (1) No deformation
 (2) Yes - deformation
 (9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 2

- (0) No glove compartment door
 (1) No - door did not open
 (2) Yes - door opened
 (9) Unknown


97. Adaptive (Assistive) Driving Equipment Ø

- (0) No adaptive driving equipment
 (1) Adaptive driving equipment installed (Check all that apply.)
☐ Hand controls for braking/acceleration
☐ Steering control devices (attached to OEM steering wheel)
☐ Steering knob attached to steering wheel
☐ Low effort power steering (unit or device)
☐ Replacement steering wheel (i.e., reduced diameter)
☐ Joy-stick steering controls
☐ Wheelchair tie-downs
☐ Modification to seat belts (specify): _____
☐ Additional or relocated switches (specify): _____
☐ Raised roof
☐ Wall-mounted head rest (used behind wheelchair)
☐ Other adaptive device (specify): _____

(9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).

Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.

Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	Φ1Φ	Φ1	KNEE	CRACKED / DISPLACED	3
B	ΦΦ7	Φ1	KNEE/LEG	DISPLACED	3
C	254	Φ1	R FOOT	DISPLACED	2
D	Φ1Φ	Φ1	KNEE	CRACKED / DISPLACED	1
E	ΦΦ1	Φ1	HEAD	HAIR / CRACKED	1
F	Φ11	Φ1	WINK	CRACKED / DISPLACED	2
G	17Φ	Φ1	CHEST	DEPLOYED	1
H	ΦΦ4	Φ1	(R) HAND	TRANSFER	2
I					
J					
K					
L					
M					
N					

FRONT

- (001) Windshield
 (002) Mirror
 (003) Sunvisor
 (004) Steering wheel rim
 (005) Steering wheel hub/spoke
 (006) Steering wheel (combination of codes 004 and 005)
 (007) Steering column, transmission selector lever, other attachment
 (008) Cellular telephone or CB radio
 (009) Add on equipment (e.g., tape deck, air conditioner)
 (010) Left instrument panel and below
 (011) Center instrument panel and below
 (012) Right instrument panel and below
 (013) Glove compartment door
 (014) Knee bolster
 (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
 (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
 (017) Windshield reinforced by exterior object, (specify):
 (019) Other front object (specify):

CODES FOR INTERIOR COMPONENTS

LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
 (052) Left side hardware or armrest
 (053) Left A (A1/A2)-pillar
 (054) Left B-pillar
 (055) Other left pillar (specify):
 (056) Left side window glass
 (057) Left side window frame
 (058) Left side window sill
 (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
 (060) Other left side object (specify):

RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests
 (102) Right side hardware or armrest
 (103) Right A (A1/A2)-pillar
 (104) Right B-pillar
 (105) Other right pillar (specify):
 (106) Right side window glass
 (107) Right side window frame
 (108) Right side window sill
 (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
 (110) Other right side object (specify):

INTERIOR

- (151) Seat, back support
 (152) Belt restraint webbing/buckle
 (153) Belt restraint B-pillar or door frame attachment point
 (154) Other restraint system component (specify):
 (155) Head restraint system
 (160) Other occupants (specify):
 (161) Interior loose objects
 (162) Child safety seat (specify):
 (163) Other interior object (specify):

AIR BAG

- (170) Air bag-driver side
 (175) Air bag compartment cover-driver side
 (180) Air bag-passenger side
 (185) Air bag compartment cover-passenger side
 (190) Other air bag (specify):
 (195) Other air bag compartment cover (specify):

ROOF

- (201) Front header
 (202) Rear header
 (203) Roof left side rail
 (204) Roof right side rail
 (205) Roof or convertible top

FLOOR

- (251) Floor (including toe pan)
 (252) Floor or console mounted transmission lever, including console
 (253) Parking brake handle
 (254) Foot controls including parking brake

REAR

- (301) Backlight (rear window)
 (302) Backlight storage rack, door, etc.
 (303) Other rear object (specify):

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
 (402) Steering control devices (attached to OEM steering wheel)
 (403) Steering knob attached to steering wheel
 (405) Replacement steering wheel (i.e., reduced diameter)
 (406) Joy stick steering controls
 (407) Wheelchair tie-downs
 (408) Modification to seat belts, (specify):
 (409) Additional or relocated switches, (specify):
 (410) Raised roof
 (411) Wall mounted head rest (used behind wheel chair)
 (412) Other adaptive device (specify):

CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain
 (2) Probable
 (3) Possible
 (9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	0	4
	Evidence of usage	04	00	04
	Used in this crash?	00	00	00
	Proper Use	0	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment	1	0	1
SECOND	Availability	4	3	4
	Evidence of usage	00	00	00
	Used in this crash?	00	00	00
	Proper Use	0	0	0
	Failure Modes	0	0	0
	Anchorage Adjustment	1	0	1
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			
	Anchorage Adjustment			

Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify):
- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):
- (8) Other improper use of manual belt system (specify):

(9) Unknown

Shoulder Belt Upper Anchorage Adjustment

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):
- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other manual belt failure (specify):
- (9) Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left Front	Right Front	Other
F I R S T	Availability/Function	/	Ø	Ø
	Deployment	/	Ø	Ø
	Failure	/	Ø	Ø

Air Bag System Availability/Function

(0) Not equipped/not available

(1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled

(9) Unknown

Are There Indications of Air Bag System Failure? (This Occupant Position)

(0) Not equipped/not available

(1) No

(2) Yes (specify): _____

(9) Unknown

Frontal Air Bag System Deployment (This Occupant Position)

(0) Not equipped/not available

(1) Deployed during accident (as a result of impact)

(2) Deployed inadvertently just prior to accident

(3) Deployed, accident sequence undetermined

(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)

(5) Unknown if deployed

(7) Nondeployed

(9) Unknown

Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position)

(0) Not equipped with an "other" air bag

(1) Deployed during accident (as a result of impact)

(2) Deployed inadvertently just prior to accident

(3) Deployed, details unknown

(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)

(5) Unknown if deployed

(7) Nondeployed

(9) Unknown

AUTOMATIC BELTS

		Left	Right
F I R S T	Availability/Function	/	/
	Use	Ø	Ø
	Type	/	/
	Proper Use	/	/
	Failure Modes	/	/

Automatic (Passive) Belt System Availability/Function

(0) Not equipped/not available

(1) 2 point automatic belts

(2) 3 point automatic belts

(3) Automatic belts - type unknown

Non-functional

(4) Automatic belts destroyed or rendered inoperative

(9) Unknown

Automatic (Passive) Belt System Use

(0) Not equipped/not available/destroyed or rendered inoperative

(1) Automatic belt in use

(2) Automatic belt not in use (manually disconnected, motorized track inoperative)

(3) Automatic belt use unknown

(9) Unknown

Automatic (Passive) Belt System Type

(0) Not equipped/not available

(1) Non-motorized system

(2) Motorized system

(9) Unknown

Proper Use of Automatic (Passive) Belt System

(0) Not equipped/not available/not used

(1) Automatic belt used properly

(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

(3) Automatic shoulder belt worn under arm

(4) Automatic shoulder belt worn behind back

(5) Automatic belt worn around more than one person

(6) Lap portion of automatic belt worn on abdomen

(7) Automatic lap and shoulder belt or

automatic shoulder belt used

improperly

with child safety seat (specify): _____

(8) Other improper use of automatic belt system (specify): _____

(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident

(0) Not equipped/not available/not in use

(1) No automatic belt failure(s)

(2) Torn webbing (stretched webbing not included)

(3) Broken buckle or latchplate

(4) Upper anchorage separated

(5) Other anchorage separated (specify): _____

(6) Broken retractor

(7) Combination of above (specify): _____

(8) Other automatic belt failure (specify): _____

(9) Unknown

FIRST SEAT FRONTAL AIR BAGS

BEST AVAILABLE

NOTES: Encode the applicable data for the driver and first seat passenger in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
Type of air bag?	1	
Flaps open at tear points?	2	
Flaps damaged?	1	
Air bag damaged?	0/1	
Source of air bag damage	0/1	
Air bag tethered?	2	
Air bag have vent ports?	2	
Other occupant contact air bag?	0	
Occupant wearing eyewear?	9	

Type of Air Bag

- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?

- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Were Air Bag Module Cover Flap(s) Damaged?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was There Damage To The Air Bag?

- (00) Not equipped/not available
- (01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify):

- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Source of Air Bag Damage

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):
- (03) Object carried by occupant, (specify):
- (04) Adaptive/assistive controls, (specify):
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):

- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

Was The Air Bag Tethered?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps):

- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Did The Air Bag Have Vent Ports?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was the Air Bag in this Occupant's Position Contacted by Another Occupant?


- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

Was This Occupant Wearing Eye-wear?


- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)




DRIVER AIR BAG SKETCHES (Cont'd)


3. DRIVER AIR BAG MODULE COVER FLAP SIZE
(DOUBLE)

a. Upper Flap

b. Lower Flap


width (W_U) 17width (W_L) 7height (H_U) 17height (H_L) 74. SKETCH OF OTHER TYPE OF AIR BAG MODULE
FLAP AND SIZE

5. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS


6. SKETCH LOCATION OF CIRCULAR AIR BAG VENT
PORTS

PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)



2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)




PASSENGER AIR BAG SKETCHES (Cont'd)

3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

a. Flap

width (W) _____


height (H) _____



4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap


b. Lower Flap

width (W_u) _____width (W_l) _____height (H_u) _____height (H_l) _____

5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3		3
	Seat Type	02		02
	Seat Performance	1		1
	Seat Orientation	1		1
	Seat Track Position	9		9
	Seat Back Incline Pre/Post Impact	9		9
SECOND	Head Restraint Type/Damage	7	0	1
	Seat Type	05	05	05
	Seat Performance	1	1	1
	Seat Orientation	1	1	1
	Seat Track Position	01	01	01
	Seat Back Incline Pre/Post Impact	01	01	01
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
	Seat Track Position			
	Seat Back Incline Pre/Post Impact			

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

HEAD RESTRAINTS/SEAT EVALUATION

Head Restraint Type/Damage by Occupant at This Occupant Position

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other
Specify: _____
- (9) Unknown

Seat Performance (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown

Seat Back Incline Prior and Post Impact

- (00) Occupant not seated or no seat
- (01) Not adjustable
- Upright prior to impact*
- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position

Slightly reclined prior to impact

- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position

Completely reclined prior to impact

- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position
- (99) Unknown

Seat Type (this Occupant Position)

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

Seat Orientation (this Occupant Position)




- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown

Seat Track Adjusted Position Prior To Impact

- (0) Occupant not seated or no seat
- (1) Non-adjustable seat track

Adjustable Seat Track

- (2) Seat at forward most track position
- (3) Seat between forward most and middle track positions
- (4) Seat at middle track position
- (5) Seat between middle and rear most track positions
- (6) Seat at rear most track position
- (9) Unknown



Coding diagrams for Seat Back Incline Position Prior and Post Impact

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify):

- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

- (00) No child safety seat

Designed for Rear Facing for This Age/Weight

- (01) Rear facing
- (02) Forward facing
- (08) Other orientation (specify):

- (09) Unknown orientation

Designed for Forward Facing for This Age/Weight

- (11) Rear facing
- (12) Forward facing
- (18) Other orientation (specify):

- (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

- (21) Rear facing
- (22) Forward facing
- (28) Other orientation (specify):

- (29) Unknown orientation

- (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage

Note: Options Below Are Used for Variables 3-5.

- (00) No child safety seat

Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used

- (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model

(Specify make/model and occupant number)

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No ☒ Yes ☐

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

Ejection Area

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

(7) Roof

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown

Ejection Medium

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

(5) Integral structure

- (8) Other medium (specify):

(9) Unknown

Medium Status (Immediately Prior to Impact)

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

ENTRAPMENT No ☒ Yes ☐

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

National Highway Traffic Safety
AdministrationNATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DS1-95-SP-0133. Vehicle Number 024. Occupant Number 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 24

Code actual age at time of accident.

(00) Less than one year old (specify by month): _____

(97) 97 years and older _____

(99) Unknown

6. Occupant's Sex 1

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height 999Code actual height to the nearest
centimeter.

(999) Unknown

_____ inches X 2.54 = _____ centimeters

8. Occupant's Weight 999Code actual weight to the nearest
kilogram.

(999) Unknown

_____ pounds X .4536 = _____ kilograms

9. Occupant's Role 1

(1) Driver

(2) Passenger

(9) Unknown

OCCUPANT'S SEATING

10. Occupant's Seat Position 11

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify): _____

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify): _____

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify): _____

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify): _____

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify): _____

(99) Unknown

11. Occupant's Posture 0

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front of
seat

(8) Other abnormal posture (specify): _____

(9) Unknown

BEST AVAILABLE

EJECTION/ENTRAPMENT

12. Ejection Ø

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) Ø

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

13. Ejection Area Ø

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

16. Entrapment Ø

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.
(specify): _____

(9) Unknown

14. Ejection Medium Ø

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____

- (5) Integral structure
- (8) Other medium (specify): _____

(9) Unknown

17. Occupant Mobility 2

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or disoriented
- (2) Removed from vehicle due to injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (9) Unknown

BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify): _____

(9) Unknown

19. Manual (Active) Belt System Use Ø Ø

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify): _____

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify): _____
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts Ø

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident Ø

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown

22. Shoulder Belt Upper Anchorage Adjustment 1

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function Ø

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use Ø

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type Ø

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System Ø

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify): _____

- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident Ø

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____

(9) Unknown

POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 9

- (0) None used
 (1) Police did not indicate belt use
 (2) Shoulder belt
 (3) Lap belt
 (4) Lap and shoulder belt
 (5) Belt used, type not specified
 (6) Child safety seat
 (7) Automatic belt
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 1

- (0) No air bag available
 (1) Police did not indicate air bag availability/function
 (2) Deployed
 (3) Not deployed
 (4) Unknown if deployed
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☐ Not equipped/not available/destroyed or rendered inoperative
☒ Vehicle inspection
☐ Official injury data
☐ Driver/occupant interview
☐ Other (specify):

☐ Unknown if belt used

AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System 1

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 1

- (0) Not equipped/not available
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function 0

(This Occupant Position)

- (0) Not equipped/not available
 (1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled
 (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0

- (0) Not equipped with an "other" air bag
 (1) Deployed during accident (as a result of impact)
 (2) Deployed inadvertently just prior to accident
 (3) Deployed, details unknown
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
 (5) Unknown if deployed
 (7) Nondeployed
 (9) Unknown

34. Are There Indications of Air Bag System Failure? 1

(This Occupant Position)

- (0) Not equipped/not available
 (1) No
 (2) Yes (specify):

(9) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 1

- (0) Not equipped/not available
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)
(3) One previous accident with deployment
(4) More than one previous accident with at least one deployment
(8) Previous accidents, unknown deployment status
(9) Unknown

36. Type of Air Bag 1

- (0) Not equipped/not available
(1) Original manufacturer installed system
(2) Retrofitted air bag
(3) Replacement air bag
(8) Unknown type of air bag
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 9

- (0) Not equipped/not available
(1) No prior maintenance
(2) Yes, prior maintenance (specify): _____

(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01

- (00) Not equipped/not available

Code the accident event sequence number that initiated the air bag deployment

- (96) Deployed, unknown event
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

39. CDC For Air Bag Deployment Impact 1

- (0) Not equipped/not available
(1) Highest delta V
(2) Second highest delta V
(3) Other non-coded delta V (specify): _____

- (6) Deployed, unknown event
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 0 8 7

- (-000) Not equipped/not available

Code the value of the delta V for the impact that initiated the air bag deployment

- (-996) Deployment, unknown longitudinal Delta V
(-997) Not deployed
(-998) Unknown if deployed
(-999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2

- (0) Not equipped/not available
(1) No
(2) Yes
(3) Deployed, unknown if flap(s) opened at designated tear points
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 1

- (0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(3) Deployed, unknown if air bag module cover flap(s) damaged
(7) Not deployed
(8) Unknown if deployed
(9) Unknown

43. Was There Damage To The Air Bag? 01

- (00) Not equipped/not available
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured
(03) Cut
(04) Torn
(05) Holed
(06) Burned
(07) Abraded
(88) Other damage (specify): _____

- (95) Damaged, details unknown
(96) Deployed, unknown if damaged
(97) Not deployed
(98) Unknown if deployed
(99) Unknown

FIRST SEAT FRONTAL AIR BAG SYSTEM
EVALUATION *continued*

HEAD RESTRAINT AND SEAT EVALUATION

44. Source of Air Bag Damage 01
- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify): _____
- (03) Object carried by occupant, (specify): _____
- (04) Adaptive/assistive controls, (specify): _____
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (08) Other damage source (specify): _____
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown
45. Was The Air Bag Tethered? 2
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps): _____
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown
46. Did The Air Bag Have Vent Ports? 2
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports): _____
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown
47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1
- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown
48. Was This Occupant Wearing Eye-wear? 9
- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

49. Head Restraint Type/Damage by Occupant at This Occupant Position 3
- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____
- (9) Unknown
50. Seat Type (this Occupant Position) 02
- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Box mounted seat (i.e., van type)
- (10) Other seat type (specify): _____
- (99) Unknown
51. Seat Orientation (this Occupant Position) 1
- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown
52. Seat Track Adjusted Position Prior To Impact 9
- (0) Occupant not seated or no seat
- (1) Non-adjustable seat track
- Adjustable Seat Track*
- (2) Seat at forward most track position
- (3) Seat between forward most and middle track positions
- (4) Seat at middle track position
- (5) Seat between middle and rear most track positions
- (6) Seat at rear most track position
- (9) Unknown

HEAD RESTRAINT AND SEAT EVALUATION *continued*53. Seat Back Incline Prior and Post Impact 9 9

(00) Occupant not seated or no seat

(01) Not adjustable

Upright prior to impact

(11) Moved to completely rearward position

(12) Moved to rearward midrange position

(13) Moved to slightly rearward position

(14) Retained pre-impact position

(15) Moved to slightly forward position

(16) Moved to forward midrange position

(17) Moved to completely forward position

Slightly reclined prior to impact

(21) Moved to completely rearward position

(22) Moved to rearward midrange position

(23) Retained pre-impact position

(24) Moved to upright position

(25) Moved to slightly forward position

(26) Moved to forward midrange position

(27) Moved to completely forward position

Completely reclined prior to impact

(31) Retained pre-impact position

(32) Moved to rearward midrange position

(33) Moved to slightly rearward position




(34) Moved to upright position

(35) Moved to slightly forward position

(36) Moved to forward midrange position

(37) Moved to completely forward position

(99) Unknown

54. Seat Performance (this Occupant Position) 1

(0) Occupant not seated or no seat

(1) No seat performance failure(s)

(2) Seat adjusters failed

(3) Seat back folding locks or "seat back" failed
(specify): _____

(4) Seat track/anchors failed

(5) Deformed by impact of occupant

(6) Deformed by passenger compartment intrusion,
(specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown

CHILD SAFETY SEAT

55. Child Safety Seat Make/Model Ø Ø Ø

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat Ø

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation Ø Ø

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage Ø Ø59. Child Safety Seat Shield Usage Ø Ø60. Child Safety Seat Tether Usage Ø ØNote: Options below applicable to
Variables OA58-OA60.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES61. Injury Severity (Police Rating) 9

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):

- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

- (9) Unknown

64. Hospital Stay 99

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 99

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

99. Case Occupant 1

- (0) Not the Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case.

STOP WORK HERE**VARIABLES 66-74****TO BE CODED BY THE ZONE CENTER**

TO BE CODED BY THE ZONE CENTER**INJURY CONSEQUENCES****TRAUMA DATA**

66. Time to Death

0 0

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
(96) Fatal - ruled disease
(99) Unknown

67. 1st Medically Reported Cause of Death

0 0

68. 2nd Medically Reported Cause of Death

0 0

69. 3rd Medically Reported Cause of Death

0 0

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
(96) Mode of death given but specific injuries are not linked to cause of death. (specify): _____

(97) Other result (includes fatal ruled disease) (specify): _____

(99) Unknown

70. Number of Recorded Injuries for This Occupant

0 7

Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
(97) Injured, details unknown
(99) Unknown if injured

71. Glasgow Coma Scale (GCS) Score (at Medical Facility)

9 7

- (00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured

72. Was the Occupant Given Blood?

9

- (1) No - blood not given
(2) Yes - blood given

(specify units): _____

- (9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO₃0 1

- (00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO₃
(96) ABGs reported, HCO₃ unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

74. Primary Source of Belt Use Determination

1

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



U.S. Department of Transportation

National Highway Traffic Safety
Administration

OCCUPANT INJURY FORM

BEST AVAILABLE Form Approved
O.M.B. No. 2127-002
NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DS1-95-SP-013

4. Occupant Number

01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

Source of Injury Data	A.I.S. - 90					Injury Source Confidence Level	Occupant Direct/ Indirect Injury	Area Intrusion Number	ICD-9			
	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity							
1st	5. <u>2</u>	6. <u>1</u>	7. <u>6</u>	8. <u>02</u>	9. <u>02</u>	10. <u>2</u>	11. <u>0</u>	12. <u>001</u>	13. <u>1</u>	14. <u>1</u>	15. <u>06</u>	<u>850.1</u>
2nd	16. <u>2</u>	17. <u>1</u>	18. <u>4</u>	19. <u>06</u>	20. <u>84</u>	21. <u>3</u>	22. <u>1</u>	23. <u>001</u>	24. <u>1</u>	25. <u>1</u>	26. <u>06</u>	<u>852.0</u>
3rd	27. <u>2</u>	28. <u>5</u>	29. <u>9</u>	30. <u>04</u>	31. <u>02</u>	32. <u>1</u>	33. <u>2</u>	34. <u>170</u>	35. <u>1</u>	36. <u>1</u>	37. <u>06</u>	<u>922.2</u>
4th	38. <u>2</u>	39. <u>8</u>	40. <u>9</u>	41. <u>02</u>	42. <u>02</u>	43. <u>1</u>	44. <u>1</u>	45. <u>011</u>	46. <u>1</u>	47. <u>1</u>	48. <u>06</u>	<u>916.0</u>
5th	49. <u>2</u>	50. <u>8</u>	51. <u>9</u>	52. <u>04</u>	53. <u>02</u>	54. <u>1</u>	55. <u>1</u>	56. <u>011</u>	57. <u>1</u>	58. <u>1</u>	59. <u>06</u>	<u>924.11</u>
6th	60. <u>2</u>	61. <u>8</u>	62. <u>9</u>	63. <u>06</u>	64. <u>02</u>	65. <u>1</u>	66. <u>1</u>	67. <u>011</u>	68. <u>1</u>	69. <u>1</u>	70. <u>06</u>	<u>891.0</u>
7th	71. <u>2</u>	72. <u>8</u>	73. <u>5</u>	74. <u>26</u>	75. <u>02</u>	76. <u>2</u>	77. <u>1</u>	78. <u>252</u>	79. <u>1</u>	80. <u>1</u>	81. <u>06</u>	<u>808.0</u>
8th	82. _____	83. _____	84. _____	85. _____	86. _____	87. _____	88. _____	89. _____	90. _____	91. _____	92. _____	_____
9th	93. _____	94. _____	95. _____	96. _____	97. _____	98. _____	99. _____	100. _____	101. _____	102. _____	103. _____	_____
10th	104. _____	105. _____	106. _____	107. _____	108. _____	109. _____	110. _____	111. _____	112. _____	113. _____	114. _____	_____

OCCUPANT INJURY CLASSIFICATION

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive two-digit numbers beginning with 02.	(1) Right
(2) Face			(2) Left
(3) Neck	<u>Vessels, Nerves, Organs.</u>		(3) Bilateral
(4) Thorax	<u>Bones, Joints</u> are assigned consecutive two digit numbers beginning with 02.		(4) Central
(5) Abdomen		To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.	(5) Anterior
(6) Spine			(6) Posterior
(7) Upper Extremity	The exceptions to this rule apply to:		(7) Superior
(8) Lower Extremity			(8) Inferior
(9) Unspecified			(9) Unknown
			(0) Whole region
Type of Anatomic Structure	<u>Whole Area</u>		
(1) Whole Area	(02) Skin - Abrasion		
(2) Vessels	(04) Skin - Contusion		
(3) Nerves	(06) Skin - Laceration		
(4) Organs (includes Muscles/ligaments)	(08) Skin - Avulsion		
(5) Skeletal (includes joints)	(10) Amputation		
(6) Head - LOC	(20) Burn		
(9) Skin	(30) Crush		
	(40) Degloving		
	(50) Injury - NFS		
	(90) Trauma, other than mechanical		
	<u>Head - LOC</u>		
	(02) Length of LOC		
	(04) Level		
	(06) of		
	(08) Consciousness		
	(10) Concussion		
	<u>Spine</u>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		

Abbreviated Injury Scale

- (1) Minor Injury
- (2) Moderate Injury
- (3) Serious Injury
- (4) Severe Injury
- (5) Critical Injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

SOURCE OF INJURY DATA

INJURY SOURCE

DIRECT/INDIRECT INJURY

CONFIDENCE LEVEL

OFFICIAL RECORDS

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL RECORDS

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

INJURY SOURCES

FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): _____
- (019) Other front object (specify): _____

LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): _____
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): _____

RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): _____
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): _____

INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): _____
- (155) Head restraint system
- (160) Other occupants (specify): _____
- (161) Interior loose objects
- (162) Child safety seat (specify): _____
- (163) Other interior object (specify): _____

AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify) _____
- (195) Other air bag compartment cover (specify) _____

ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

FLOOR

- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): _____

ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): _____
- (409) Additional or relocated switches, (specify): _____

- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): _____
- (454) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): _____
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): _____
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): _____
- (514) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT


- (551) Ground
- (598) Other vehicle or object (specify): _____
- (599) Unknown vehicle or object

NONCONTACT INJURY

- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): _____
- (604) Air bag exhaust gases
- (697) Injured, unknown source

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

___ No

___ Yes

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Blood Alcohol Level
(mg/dl)

BAL = ___

Glasgow Coma
Scale Score

GCSS = ___

Units of Blood
Given

Units = ___



Arterial Blood Gases

pH = ___

PO₂ = ___

PCO₂ = ___

HCO₃ = ___





RIGHT POSTERIOR
ACETABULAR COLUMN
FRACTURE
(MULTIPLE BONE
FRAGMENTS)

OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

RIGHT OCCIPITAL
SUBARACHNOID
HEMATOMA

LOSS OF CONSCIOUSNESS
< 1 HOUR





CRASHPC PROGRAM SUMMARY

(All Measurements in Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title	<u>DSI-95-SP-013</u>	<u>01</u>	
Primary Sampling Unit	Case No.-Stratum	Accident Event Sequence No.	Date (Month, day, year) of Run

CRASHPC Vehicle Identification

Vehicle 1	<u>1983</u>	<u>DODGE</u>	<u>VAN</u>	
Vehicle 2	<u>1991</u>	<u>TOYOTA</u>	<u>CELICA GTS</u>	
	Year	Make	Model	NASS Veh. No.

GENERAL INFORMATION

VEHICLE 1		VEHICLE 2	
Size	<u>1</u>	Size	<u>2</u>
Weight		Weight	
<u>1575</u> + <u>403</u> + <u>0</u> = <u>1978</u> kg		<u>1277</u> + <u>72</u> + <u>0</u> = <u>1349</u> kg	
Curb Occupant(s) Cargo		Curb Occupant(s) Cargo	
CDC	<u>72 FDEW7</u>	CDC	<u>72 FDEW4</u>
PDOF (-180 to +180)	<u>010</u>	PDOF (-180 to +180)	<u>010</u>
Stiffness	<u>7</u>	Stiffness	<u>2</u>

SCENE INFORMATION

VEHICLE 1		VEHICLE 2	
Rest and Impact Positions [] No, Go To Damage Information [] Yes			
Rest Position	X _____ m Y _____ m PSI _____ °	Rest Position	X _____ m Y _____ m PSI _____ °
Impact Position	X _____ m Y _____ m PSI _____ °	Impact Position	X _____ m Y _____ m PSI _____ °
Slip Angle(-180 to +180)	_____ °	Slip Angle (-180 to +180)	_____ °

VEHICLE MOTION

VEHICLE 1		VEHICLE 2	
Sustained Contact [] No [] Yes			
Vehicle Rotation [] No [] Yes			
Rotation Stop Before Rest [] No [] Yes			
End of Rotation Position	X _____ m Y _____ m PSI _____ °	End of Rotation Position	X _____ m Y _____ m PSI _____ °
Curved Path [] No [] Yes			
Point on Path X _____ m Y _____ m			
Rotation Direction [] None [] CW [] CCW			
Rotation >360° [] No [] Yes			

FRICTION INFORMATION

Coefficient of Friction _____

Rolling Resistance Option _____

Vehicle 1 Rolling Resistance

LF _____ RF _____

LR _____ RR _____

Vehicle 2 Rolling Resistance

LF _____ RF _____

LR _____ RR _____

TRAJECTORY INFORMATION

Trajectory Data [] No [] Yes

If No, Go To Damage Information

Vehicle 1 Steer Angles

LF _____ ° RF _____ °

LR _____ ° RR _____ °

Vehicle 2 Steer Angles

LF _____ ° RF _____ °

LR _____ ° RR _____ °

Terrain Boundary [] No [] Yes

First Point

X _____ m Y _____ m

Second Point

X _____ m Y _____ m

Secondary Coefficient of Friction _____

DAMAGE INFORMATION

VEHICLE 1

Damage Length L 187 cmCrush Depths C₁ 000 cmC₂ 005 cmC₃ 022 cmC₄ 085 cmC₅ 097 cmC₆ 123 cmDamage Offset D 0024 cm

VEHICLE 2

Damage Length L 140 cmCrush Depths C₁ 040 cmC₂ 082 cmC₃ 081 cmC₄ 095 cmC₅ 102 cmC₆ 106 cmDamage Offset D ⁺ 000 cm

FOR EACH VEHICLE INVOLVED IN THIS ACCIDENT, IF A VEHICLE WAS IN TRANSPORT, FILL IN THE INFORMATION BELOW

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

DSI-95-SP-013

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (KPH)	LONG. (KPH)	LAT. (KPH)	ANG. (DEG)
	VEH #2	59.7	-58.8	-10.4	10.0
		87.9	-86.6	-15.3	10.0

ENERGY DISSIPATED BY DAMAGE VEH#1:474621.4 JOULES VEH#2:228616.2 JOULES

SUMMARY OF DAMAGE DATA VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 7
STIFFNESS---CATEGORY 7
WEIGHT-----1978.0 KGS
CDC-----12FDEW7
L-----187.0 CM.
C1-----0 CM.
C2-----5.0 CM.
C3-----22.0 CM.
C4-----85.0 CM.
C5-----97.0 CM.
C6-----123.0 CM.
D-----24.0 CM.
RHO-----1.00 *
ANG-----10.0 DEG.
D'-----65.9 CM.

TYPE-----CATEGORY 2
STIFFNESS---CATEGORY 2
WEIGHT-----1344.0 KGS
CDC-----12FDEW4
L-----140.0 CM.
C1-----40.0 CM.
C2-----82.0 CM.
C3-----81.0 CM.
C4-----95.0 CM.
C5-----102.0 CM.
C6-----106.0 CM.
D-----0 CM.
RHO-----1.00 *
ANG-----10.0 DEG.
D'-----7.0 CM.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 123.2 CM.
B1 = 174.0 CM.
TR1 = 171.7 CM.
I1 = 475628.0 NEWT-SEC**2-CM
M1 = 19.855 NEWT-SEC**2/CM
XF1 = 192.0 CM.
XR1 = -271.8 CM.
YS1 = 100.3 CM.

A2 = 117.6 CM.
B2 = 127.3 CM.
TR2 = 138.7 CM.
I2 = 256853.0 NEWT-SEC**2-CM
M2 = 13.491 NEWT-SEC**2/CM
XF2 = 211.6 CM.
XR2 = -232.7 CM.
YS2 = 85.3 CM.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

DSI-95-SP-013

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (MPH)	LONG. (MPH)	LAT. (MPH)	ANG. (DEG)
	VEH #1	37.1	-36.5	-6.4	10.0
	VEH #2	54.6	-53.8	-9.5	10.0

ENERGY DISSIPATED BY DAMAGE VEH#1:350015.8 FT-LB. VEH#2:168596.0 FT-LB.

SUMMARY OF DAMAGE DATA
VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 7
STIFFNESS---CATEGORY 7
WEIGHT----- 4360.7 LBS.
CDC-----12FDEW7
L----- 73.6 IN.
C1----- .0 IN.
C2----- 2.0 IN.
C3----- 8.7 IN.
C4----- 33.5 IN.
C5----- 38.2 IN.
C6----- 48.4 IN.
D----- 9.4 IN.
RHO----- 1.00 *
ANG----- 10.0 DEG.
D'----- 25.9 IN.

TYPE-----CATEGORY 2
STIFFNESS---CATEGORY 2
WEIGHT----- 2963.0 LBS.
CDC-----12FDEW4
L----- 55.1 IN.
C1----- 15.7 IN.
C2----- 32.3 IN.
C3----- 31.9 IN.
C4----- 37.4 IN.
C5----- 40.2 IN.
C6----- 41.7 IN.
D----- .0 IN.
RHO----- 1.00 *
ANG----- 10.0 DEG.
D'----- 2.8 IN.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 48.5 IN.
B1 = 68.5 IN.
TR1 = 67.6 IN.
I1 = 42098.7 LB-SEC**2-IN
M1 = 11.338 LB-SEC**2/IN
XF1 = 75.6 IN.
XR1 = -107.0 IN.
YS1 = 39.5 IN.

A2 = 46.3 IN.
B2 = 50.1 IN.
TR2 = 54.6 IN.
I2 = 22734.5 LB-SEC**2-IN
M2 = 7.704 LB-SEC**2/IN
XF2 = 83.3 IN.
XR2 = -91.6 IN.
YS2 = 33.6 IN.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

SP-13 Vehicle 1 ebs

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (KPH)	LONG. (KPH)	LAT. (KPH)	ANG. (DEG)
	VEH #1	76.2	-75.1	-13.2	10.0
	VEH #2	.0	.0	.0	.0

ENERGY DISSIPATED BY DAMAGE VEH#1:474621.4 JOULES VEH#2: .0 JOULES

SUMMARY OF DAMAGE DATA
VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 7
 STIFFNESS---CATEGORY 7
 WEIGHT----- 1978.0 KGS
 CDC-----12FDEW7
 L----- 187.0 CM.
 C1----- .0 CM.
 C2----- 5.0 CM.
 C3----- 22.0 CM.
 C4----- 85.0 CM.
 C5----- 97.0 CM.
 C6----- 123.0 CM.
 D----- 24.0 CM.
 RHO----- 1.00 *
 ANG----- 10.0 DEG.
 D'----- 65.9 CM.

TYPE-----CATEGORY 11
 STIFFNESS---CATEGORY 0
 WEIGHT----- 999999.9 KGS *
 CDC-----BARRIER
 L----- .0 CM. *
 C1----- .0 CM. *
 C2----- .0 CM. *
 C3----- .0 CM. *
 C4----- .0 CM. *
 C5----- .0 CM. *
 C6----- .0 CM. *
 D----- .0 CM. *
 RHO----- 1.00 *
 ANG----- .0 DEG. *
 D'----- 65.9 CM.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 123.2 CM.
 B1 = 174.0 CM.
 TR1 = 171.7 CM.
 I1 = 475628.0 NEWT-SEC**2-CM
 M1 = 19.855 NEWT-SEC**2/CM
 XF1 = 192.0 CM.
 XR1 = -271.8 CM.
 YS1 = 100.3 CM.

A2 = 127.0 CM.
 B2 = 127.0 CM.
 TR2 = 127.0 CM.
 I2 =***** NEWT-SEC**2-CM
 M2 =***** NEWT-SEC**2/CM
 XF2 = 127.0 CM.
 XR2 = -127.0 CM.
 YS2 = 127.0 CM.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

SP-13 Vehicle 1 ebs

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (MPH)	LONG. (MPH)	LAT. (MPH)	ANG. (DEG)
	VEH #1	47.4	-46.6	-8.2	10.0
	VEH #2	.0	.0	.0	.0

ENERGY DISSIPATED BY DAMAGE VEH#1:350015.8 FT-LB. VEH#2: .0 FT-LB.

SUMMARY OF DAMAGE DATA VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 7
STIFFNESS---CATEGORY 7
WEIGHT----- 4360.7 LBS.
CDC-----12FDEW7
L----- 73.6 IN.
C1----- .0 IN.
C2----- 2.0 IN.
C3----- 8.7 IN.
C4----- 33.5 IN.
C5----- 38.2 IN.
C6----- 48.4 IN.
D----- 9.4 IN.
RHO----- 1.00 *
ANG----- 10.0 DEG.
D'----- 25.9 IN.

TYPE-----CATEGORY 11
STIFFNESS---CATEGORY 0
WEIGHT-----2204586.0 LBS. *
CDC-----BARRIER
L----- .0 IN. *
C1----- .0 IN. *
C2----- .0 IN. *
C3----- .0 IN. *
C4----- .0 IN. *
C5----- .0 IN. *
C6----- .0 IN. *
D----- .0 IN. *
RHO----- 1.00 *
ANG----- .0 DEG. *
D'----- 25.9 IN.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 48.5 IN.
B1 = 68.5 IN.
TR1 = 67.6 IN.
I1 = 42098.7 LB-SEC**2-IN
M1 = 11.338 LB-SEC**2/IN
XF1 = 75.6 IN.
XR1 = -107.0 IN.
YS1 = 39.5 IN.

A2 = 50.0 IN.
B2 = 50.0 IN.
TR2 = 50.0 IN.
I2 = 5732151000.0 LB-SEC**2-IN
M2 = 5732.151 LB-SEC**2/IN
XF2 = 50.0 IN.
XR2 = -50.0 IN.
YS2 = 50.0 IN.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

SP-13 Vehicle 2 ebs

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (KPH) 65.4	LONG. (KPH) -64.4	LAT. (KPH) -11.4	ANG. (DEG) 10.0
	VEH #2	.0	.0	.0	.0

ENERGY DISSIPATED BY DAMAGE VEH#1:228616.2 JOULES VEH#2: .0 JOULES

SUMMARY OF DAMAGE DATA VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 2
STIFFNESS---CATEGORY 2
WEIGHT-----1344.0 KGS
CDC-----12FDEW4
L-----140.0 CM.
C1-----40.0 CM.
C2-----82.0 CM.
C3-----81.0 CM.
C4-----95.0 CM.
C5-----102.0 CM.
C6-----106.0 CM.
D----- .0 CM. *
RHO-----1.00 *
ANG-----10.0 DEG.
D'-----7.0 CM.

TYPE-----CATEGORY 11
STIFFNESS---CATEGORY 0
WEIGHT-----999999.9 KGS *
CDC-----BARRIER
L----- .0 CM. *
C1----- .0 CM. *
C2----- .0 CM. *
C3----- .0 CM. *
C4----- .0 CM. *
C5----- .0 CM. *
C6----- .0 CM. *
D----- .0 CM. *
RHO-----1.00 *
ANG----- .0 DEG. *
D'-----65.9 CM.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 117.6 CM.
B1 = 127.3 CM.
TR1 = 138.7 CM.
I1 = 256853.0 NEWT-SEC**2-CM
M1 = 13.491 NEWT-SEC**2/CM
XF1 = 211.6 CM.
XR1 = -232.7 CM.
YS1 = 85.3 CM.

A2 = 127.0 CM.
B2 = 127.0 CM.
TR2 = 127.0 CM.
I2 =***** NEWT-SEC**2-CM
M2 =***** NEWT-SEC**2/CM
XF2 = 127.0 CM.
XR2 = -127.0 CM.
YS2 = 127.0 CM.

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

SP-13 Vehicle 2 ebs

SPEED CHANGE (DAMAGE)	VEH #1	TOTAL (MPH)	LONG. (MPH)	LAT. (MPH)	ANG. (DEG)
	VEH #1	40.6	-40.0	-7.1	10.0
	VEH #2	.0	.0	.0	.0

ENERGY DISSIPATED BY DAMAGE VEH#1:168596.0 FT-LB. VEH#2: .0 FT-LB.

SUMMARY OF DAMAGE DATA
VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 2
 STIFFNESS---CATEGORY 2
 WEIGHT-----2963.0 LBS.
 CDC-----12FDEW4
 L-----55.1 IN.
 C1-----15.7 IN.
 C2-----32.3 IN.
 C3-----31.9 IN.
 C4-----37.4 IN.
 C5-----40.2 IN.
 C6-----41.7 IN.
 D----- .0 IN. *
 RHO-----1.00 *
 ANG-----10.0 DEG.
 D'-----2.8 IN.

TYPE-----CATEGORY 11
 STIFFNESS---CATEGORY 0
 WEIGHT-----2204586.0 LBS. *
 CDC-----BARRIER
 L----- .0 IN. *
 C1----- .0 IN. *
 C2----- .0 IN. *
 C3----- .0 IN. *
 C4----- .0 IN. *
 C5----- .0 IN. *
 C6----- .0 IN. *
 D----- .0 IN. *
 RHO-----1.00 *
 ANG----- .0 DEG. *
 D'-----25.9 IN.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 46.3 IN.
 B1 = 50.1 IN.
 TR1 = 54.6 IN.
 I1 = 22734.5 LB-SEC**2-IN
 M1 = 7.704 LB-SEC**2/IN
 XF1 = 83.3 IN.
 XR1 = -91.6 IN.
 YS1 = 33.6 IN.

A2 = 50.0 IN.
 B2 = 50.0 IN.
 TR2 = 50.0 IN.
 I2 = 5732151000.0 LB-SEC**2-IN
 M2 = 5732.151 LB-SEC**2/IN
 XF2 = 50.0 IN.
 XR2 = -50.0 IN.
 YS2 = 50.0 IN.



U.S. Department of Transportation

National Highway Traffic Safety
Administration

SMASH PROGRAM SUMMARY

(All Measurements in Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

DSI-95-SP-013 01 1 1 96
 Primary Case No.-Stratum Accident Event Date (Month, day, year) of Run
 Sampling Unit Sequence No.

GENERAL INFORMATION

VEHICLE 1

VEHICLE 2

NASS Vehicle Number

NASS Vehicle Number

Year 1983Year 1991Make DODGEMake TOYOTAModel RAM VANModel CELICABody Style VNBody Style 3HCDC 12 FDEW7CDC 12 FDEW4PDOF ± 010°PDOF ± _____°Heading Angle ± _____°Heading Angle ± _____°

VEHICLE SPECIFICATIONS

VEHICLE 1

VEHICLE 2

Wheelbase 324 cmWheelbase 253 cmOverall Length 500 cmOverall Length 442 cmOverall Width 203 cmOverall Width 175 cmWeight
1575 + 403 + 0 = 1978 kgWeight
1272 + 720 + 0 = 1344 kg

Curb Occupant(s) Cargo

Curb Occupant(s) Cargo

Engine Displacement 5.2 LEngine Displacement 2.2 LDrive System RWDDrive System FWDSize 7Size 2Stiffness 7Stiffness 2

DAMAGE INFORMATION

VEHICLE 1

VEHICLE 2

Damage known? YDamage known? YDamage Length 187 cmDamage Length 140 cmDamage Offset ± 024 cmDamage Offset ± 000 cmCrush Depth: C1 000 cmCrush Depth: C1 040 cmC2 005 cmC2 082 cmC3 022 cmC3 081 cmC4 085 cmC4 095 cmC5 097 cmC5 102 cmC6 123 cmC6 106 cm

SCENE INFORMATION

Rest and Impact Positions ☐ No ☐ Yes

	VEHICLE 1			VEHICLE 2	
Rest	X	_____ . _____ m	Rest	X	_____ . _____ m
Position	Y	_____ . _____ m	Position	Y	_____ . _____ m
	PSI	_____ °		PSI	_____ °
Impact	X	_____ . _____ m	Impact	X	_____ . _____ m
Position	Y	_____ . _____ m	Position	Y	_____ . _____ m
	PSI	_____ °		PSI	_____ °
Slip Angle (-180 to +180)		_____ °	Slip Angle (-180 to +180)		_____ °

VEHICLE MOTION

Sustained Contact <input type="checkbox"/> No <input type="checkbox"/> Yes		Sustained Contact <input type="checkbox"/> No <input type="checkbox"/> Yes	
VEHICLE 1		VEHICLE 2	
Vehicle Rotation	<input type="checkbox"/> No <input type="checkbox"/> Yes	Vehicle Rotation	<input type="checkbox"/> No <input type="checkbox"/> Yes
Rotation Stop Before Rest	<input type="checkbox"/> No <input type="checkbox"/> Yes	Rotation Stop Before Rest	<input type="checkbox"/> No <input type="checkbox"/> Yes
End of Rotation	X _____ . _____ m	End of Rotation	X _____ . _____ m
Position	Y _____ . _____ m	Position	Y _____ . _____ m
	PSI _____ °		PSI _____ °
Curved Path	<input type="checkbox"/> No <input type="checkbox"/> Yes	Curved Path	<input type="checkbox"/> No <input type="checkbox"/> Yes
Point on Path		Point on Path	
X _____ . _____ m	Y _____ . _____ m	X _____ . _____ m	Y _____ . _____ m
Rotation Direction	<input type="checkbox"/> None <input type="checkbox"/> CW <input type="checkbox"/> CCW	Rotation Direction	<input type="checkbox"/> None <input type="checkbox"/> CW <input type="checkbox"/> CCW
Rotation > 360°	<input type="checkbox"/> No <input type="checkbox"/> Yes	Rotation > 360°	<input type="checkbox"/> No <input type="checkbox"/> Yes

FRICTION INFORMATION

Coefficient of Friction
Rolling Resistance Option_____ . _____
1

Vehicle 1 Rolling Resistance

LF _____ . _____ RF _____ . _____

LR _____ . _____ RR _____ . _____

Vehicle 2 Rolling Resistance

LF _____ . _____ RF _____ . _____

LR _____ . _____ RR _____ . _____

IF THIS COLLISION INVOLVED A CBS VEHICLE NOT IN TRANSPORT, FILL IN THE INFORMATION BELOW.

Model Year: _____

Make: _____

Model: _____

VIN: _____

The Weight, CDC, Scene Data and Damage Information
for this vehicle should be recorded above.**Complete and ATTACH the appropriate
damage sketch and dimensions to the form.**